

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJB 20 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 1250 ✓	
3	To respray front bumper and rhs front fender.	\$ 2,500.00 1100 ✓	
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✗	
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u><u>6,252.00</u></u>	

premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 20 M

S/N	Parts Description		Damaged Parts & Prices		Remarks
			S/Nett		
1	FRONT BUMPER <i>Del d</i>	\$	2,073.00	✓	1658.40
2	FRONT BUMPER FIXING PARTS	\$	368.00	+	
3	FRONT BUMPER SECURING STRIP <i>2</i>	\$	64.00	✓	
4	FRONT BUMPER GRILLE - CENTRE	\$	178.00	✓	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	207.00	+	
6	FRONT BUMPER SPOILER <i>new</i>	\$	489.00	+	
7	FRONT BUMPER AIR GUIDE - RH <i>new</i>	\$	56.00	+	
8	RADIATOR GRILLE COVER - UPPER <i>3 new</i>	\$	2,131.00	+	
9	FRONT BUMPER AIR GUIDE GRILLE - RH	\$	431.00	+	
10	FRONT BUMPER CARRIER <i>new</i>	\$	733.00	+	
11	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$	113.00	+	
12	FRONT BUMPER COVER <i>new</i>	\$	116.00	+	
13	FRONT BUMPER GUIDE SECTION - RH <i>2H new</i>	\$	33.00	?	
14	CAUTION SIGN STICKER <i>2</i>	NEC \$	13.00	+	
15	AIRCON STICKER <i>new</i>	NEC \$	7.00	+	
16	LOCK CARRIER BRACKET	\$	125.00	+	
17	FRONT BUMPER SUPPORT - LH / RH <i>2</i>	\$	52.00	+	
18	FRONT PARKING AID SENSOR - OUTER / INNER <i>2</i>	\$	462.00	+	
19	FRONT PARKING AID SEAL RING <i>4</i>	\$	12.00	+	
20	HORN - RH LOW TONE <i>2H new</i>	\$	262.00	?	
SUB TOTAL SPARE PARTS		:	\$	7,925.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJB 20 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	SPRING SHACKLE - RH <i>Neu</i>	\$ 26.00	✓
22	FRONT FENDER - RH <i>Dented</i>	\$ 968.00	✓
23	FRONT FENDER ATTACHMENT PARTS	\$ 48.00	+
24	FRONT FENDER CLOSING ELEMENT - RH <i>3 Neu</i>	\$ 68.00	+
25	FRONT FENDER BRACKET - RH	\$ 32.00	+
26	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>Neu</i>	\$ 45.00	+
27	FRONT FENDER TRIM - RH <i>Neu</i>	\$ 145.00	✓
28	FRONT WHEEL HOUSING LINER - RH <i>3 Neu</i>	\$ 256.00	+
29	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 82.00	+
30	WHEEL SPOILER - RH <i>included</i>	\$ 66.00	✓
31	WHEEL SPOILER TRIM - RH <i>Not Nec</i>	\$ 33.00	+
32	WHEEL SPOILER TRIM BRACKET - RH <i>Not Nec</i>	\$ 22.00	+
33	STONE CHIP GUARD - RH <i>Neu</i>	\$ 46.00	✓
34	FRONT FENDER LEDGE COVER - RH <i>Neu</i>	\$ 32.00	?
35	FRONT FENDER LEDGE COVER - RH <i>Neu</i>	\$ 14.00	?
36	LED HEADLIGHT - RH <i>cut</i>	\$ 7,204.00	✓
37	LIFT CYLINDER - RH <i>Neu</i>	\$ 181.00	?
38	LIFT CYLINDER BRACKET - RH <i>Neu</i>	\$ 13.00	+
39	HEADLIGHT CORRUGATED PIPE <i>3 Neu</i>	\$ 78.00	+
40	HEADLIGHT SPRING CLIP	\$ 23.00	+
41	FRONT ALUMINIUM RIM - RH <i>3 Neu</i>	\$ 943.00	+
42	ALUMINIUM RIM RUBBER VALVE	\$ 13.00	+
43	FRONT NO PLATE <i>Neu</i>	\$ 60.00	✓
44	SUNDRIES <i>Neu</i>	\$ 300.00	?
TOTAL SPARE PARTS		\$ 18,623.00	
TOTAL LABOUR CHARGES		\$ 6,252.00	
GRAND TOTAL		\$ 24,875.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.