

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5391C**AAD1912-214***Not Authorised
V/Rup @ 6500/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 JAN 2020

SHC 5391C

VF1ABL15AUC280064

RENAULT

LATITUDE

31.12.19

EQ

21/10/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Tr</i> 747.20 ✓
1	BUMPER SPOILER FRT	\$	<i>Dr</i> 344.70 ✓
1	BUMPER ABSORBER FRT	\$	<i>M11</i> 394.68 ✓
1	BUMPER RETAINER FRT LH	\$	<i>CM</i> 101.40 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 10.70 X
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 101.40 X
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 10.70 X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 292.50 X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 147.00 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 663.70 X
1	HEADLAMP RH	\$	<i>M3 BR</i> 743.60 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 128.30 X
1	HEADLAMP LH	\$	<i>BR</i> 743.60 ✓
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 127.70 X
1	HEADLAMP HARNESS	\$	<i>SL</i> 928.29 X
2	HEADLAMP ADJUST MOTOR	\$	<i>SL M3 ADJ</i> 313.90 ✓
1	HORN	\$	<i>SL</i> 449.90 X
1	FENDER PANEL FRT RH	\$	<i>R BR</i> 437.10 X
1	WHEELARCH FRT RH	\$	<i>SL TR</i> 191.40 X
1	FENDER BRACKET FRT RH	\$	<i>R</i> 106.40 X
1	FENDER BRACKET LOWER RH	\$	<i>R</i> 11.80 X
1	FENDER INSULATOR RH	\$	<i>SL</i> 66.30 X
1	CHASSIS PANEL FRT LH	\$	<i>R</i> 655.80 X
1	CHASSIS PANEL REINFORCEMENT FRT LH	\$	<i>R</i> 283.90 X
1	FENDER PANEL INNER FRT LH L70Y	\$	<i>R</i> 858.30 X

Trans-cab Auto Services Pte Ltd**AAD1912-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5391C

1	FENDER PANEL REINFORCEMENT FRT LH L70Y	\$	N	642.40	X
1	WHEEL HOUSING PANEL FRT LH	\$	N	2,621.60	X
1	FENDER PANEL FRT LH	\$	B	414.40	✓
1	WHEELARCH FRT LH	\$	T	112.30	✓
1	FENDER BRACKET LOWER LH	\$	S	11.80	X
1	FENDER INSULATOR LH	\$	S	65.50	X
1	FENDER BRACKET FRT LH	\$	N	59.00	X
1	TOW COVER FRT	\$	S	60.90	X
1	FRONT BRACE PANEL	\$	N	177.22	X
1	RADIATOR GRILLE	\$	N	969.90	✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	N	225.36	✓
1	RADIATOR GRILLE FRAME	\$	C	686.00	✓
1	FRAME FULL SUPPORT PANEL	\$	C	592.70	✓
1	FRAME FULL SUPPORT BRACKET	\$	N	41.60	X
1	BONNET	\$	B	1,312.70	✓
1	BONNET INSULATOR	\$	S	294.30	✓
1	BONNET STRUT RH	\$	S	53.30	✓
1	BONNET HINGE RH	\$	N	237.40	✓
1	BONNET STRUT LH	\$	S	53.30	✓
1	BONNET HINGE LH	\$	N	236.50	✓
1	BONNET LOCK	\$	N	152.80	✓
1	BONNET CABLE	\$	S	55.20	✓
1	BONNET CABLE COVER	\$	S	80.60	✓
1	BONNET SEAL OUTER	\$	S	83.20	✓
1	BONNET SEAL INNER	\$	S	70.10	✓
1	LOWER ARM LH L70Y	\$	S	192.70	✓
1	KNUCKLE ARM LH L70Y	\$	S	481.50	✓
1	ABSORBER FRT LH L70Y	\$	S	274.10	✓
1	DRIVESHAFT LH	\$	N	1,355.70	✓
1	STABILIZER BAR FRT	\$	N	427.90	✓
1	KNUCKLE HUB+BEARING LH/RH L70Y	\$	S	272.30	✓
1	ABSORBER MOUNTING KIT LH L70Y	\$	S	273.60	✓
1	BRAKE CALIPER FRT LH L70Y	\$	S	536.10	✓
1	ENGINE UNDERTRAY	\$	S	583.10	✓
1	STEERING PINION RACK L70Y	\$	S	3,765.30	✓

Trans-cab Auto Services Pte Ltd**AAD1912-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5391C

1	AUTO COMPUTER	\$	S 1,287.30
1	INJECTION COMPUTER	\$	S 2,706.30
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S 3,765.30
1	STEERING PUMP ELECTRIC L70Y	\$	S 2,026.70
1	WIPER RESERVOIR MOTOR	\$	S 82.60
1	WIPER RESERVOIR	\$	S 179.60
1	WIPER RESERVOIR NECK	\$	S 29.30
1	SUBFRAME OUTER FRT	\$	S 1,094.20
1	SUBFRAME BRACKET OUTER LH	\$	" 49.00
1	SUBFRAME BRACKET OUTER RH	\$	" 49.00
1	A/C CONDENSER	\$	S 1,537.80
1	A/C PIPE CONDENSER TO COMPRESSOR	\$	S 187.20
1	A/C PIPE CONDENSER TO EXPANSION VALVE	\$	S 380.20
1	A/C PIPE COMPRESSOR	\$	S 222.70
1	A/C PIPE	\$	S 486.50
1	A/C CONDENSER GARNISH LH UPPER	\$	S 57.30
1	A/C CONDENSER GARNISH RH UPPER	\$	S 56.70
1	A/C CONDENSER GARNISH LH	\$	S 67.90
1	A/C CONDENSER GARNISH RH	\$	S 67.70
1	A/C COMPRESSOR	\$	S 2,142.30
1	AIR COOLER	\$	S 598.90
1	AIR INTERCOOLER HOSE (LONG)	\$	S 1,014.13
1	AIR INTERCOOLER HOSE (Short)	\$	S 375.14
1	TRANSMISSION COOLER	\$	S 1,219.30
1	TRANSMISSION COOLER PAD	\$	S 9.50
1	RADIATOR	\$	S 871.20
2	RADIATOR STUD UPPER	\$	S 11.10
2	RADIATOR BUSH UPPER	\$	S 11.10
2	RADIATOR MTG LOWER	\$	S 30.10
1	RADIATOR FAN COWLING	\$	S 417.00
1	RADIATOR FAN MOTOR LH	\$	S 826.70
1	RADIATOR FAN MOTOR RH	\$	S 821.20
1	RADIATOR TANK	\$	S 174.80
1	RADIATOR HOSE UPPER	\$	S 97.50
1	RADIATOR HOSE LOWER	\$	S 254.10

Trans-cab Auto Services Pte Ltd**AAD1912-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5391C

1	RADIATOR TANK HOSE	\$	56.20
1	FUSE BOX	\$	987.39
1	ENGINE MOUNTING UPPER	\$	592.02
1	ENGINE MOUNTING LOWER	\$	149.20
1	A/C HEATER VALVE	\$	484.50
1	TURBO DUCT	\$	1,027.80
1	BASE BATTERY TRAY	\$	363.40
1	ALTERNATOR	\$	1,442.30
1	ENGINE HARNESS	\$	1,501.60
1	BATTERY COVER	\$	363.40
1	AIR CLEANER LOWER	\$	271.26
1	AIR CLEANER HOSE	\$	175.85
1	AIR CLEANER BOX	\$	464.20
1	DOOR PANEL FRT LH	\$	2,844.66
1	DOOR HARNESS LH	\$	2,640.00
1	DOOR MIRROR ASSY LH	\$	727.90
1	DOOR SEAL FRT LH	\$	93.90
1	ROCKER PANEL INNER GARNISH LH	\$	466.51
1	ROCKER PANEL INNER LH	\$	1,024.79
1	ROCKER PANEL OUTER LH	\$	1,184.99
1	ROCKER PANEL CENTER LH	\$	990.25
1	SUBFRAME INNER FRT	\$	746.00
1	SUBFRAME BRACKET INNER LH	\$	101.00
1	SUBFRAME BRACKET INNER RH	\$	101.00
1	SUBFRAME SUPPORT INNER	\$	69.50
1	BATTERY	\$	350.00
TOTAL		\$	69,174.06
10%		\$	6,917.41
		\$	62,256.65

*Recx***Special Nett**

1	BUMPER CLIP FRT	\$	<i>nc</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i> 10.50 X
1	BUMPER GRILLE LOWER CLIP	\$	<i>nc</i> 69.00 ✓

Trans-cab Auto Services Pte Ltd**AAD1912-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5391C

1	BUMPER BRACKET CLIP FRT LH	\$	nn 12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	nn 10.50
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00
1	WHEELARCH CLIP FRT RH	\$	nn 30.50
1	FRONT RIGHT TYRE	\$	nn 300.00
1	WHEELARCH CLIP FRT LH	\$	nn 30.50
1	FRONT RIGHT TYRE RIM	\$	nn 380.00
1SET	Front licence plate with holder	\$	nn 80.00
1SET	RADIATOR GRILLE SCREW	\$	nn 16.00
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn 52.00
1	WINDSCREEN SEALANT	\$	nn 109.20
1	FRONT WINDSCREEN MOULDING	\$	nn 120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00
6	BONNET INSULATOR CLIP L70Y	\$	nn 7.30
2	BONNET CABLE CLIP L70Y	\$	nn 6.31
2	BONNET CABLE COVER SCREW L70Y	\$	nn 10.85
1	FRONT DOOR STICKER 'Trans-Cab'	\$	nn 80.00
1	FRONT DOOR STICKER 'Classic'	\$	nn 80.00
1	FRONT LEFT TYRE	\$	nn 300.00
1	FRONT LEFT TYRE RIM	\$	nn 380.00
1SET	HEADLAMP SCREW	\$	nn 20.00
TOTAL		\$	2,402.67

TOTAL PARTS	\$	64,659.32
--------------------	-----------	------------------

LABOUR

To transfer of front windscreen glass to facilitate bodywork repair.

\$	nn 170.00 X
----	-------------

To transfer of bonnet fittings, attachment and perform water seepage test.

\$	nn 170.00 X
----	-------------

Trans-cab Auto Services Pte Ltd**AAD1912-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5391C

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	9,000.00	500
To transfer of front fender fittings, attachment and perform water seepage test.	\$	350.00	X
To rust-proofing of the affected areas.	\$	170.00	30
Putty and spray painting of the affected portion.	\$	9,000.00	660
To Check Electrical Lighting Concerned.	\$	170.00	20
To check steering geometry and computer wheel alignment	\$	220.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	100

Trans-cab Auto Services Pte Ltd**AAD1912-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5391C

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	~ 380.00	X
To lift-up engine with gear box and refit.	\$	~ 440.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	~ 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	~ 440.00	X
To remove and renew engine and gear box mounting.	\$	~ 380.00	X
To replace, refix and top up coolant for radiator	\$	170.00	Scp
To vacuum, replace, refix and recharge Air Intercooler	\$	~ 170.00	X
TOTAL	\$	24,400.00	
Over All Total	\$	89,059.32	

LUMP SUM (REPAIR DAY)**30 DAYS***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: