



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

JMYLTZ23W62000248

TP China

Page No. 1

Vehicle No. SGE6839Z MITSUBISHI CORTPLUS

Veron.

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	REAR TAILGATE <i>Distorted</i>		907.50	✓
2	REAR TAILGATE HINGE LH & RH @\$78.90 <i>xlern</i>		157.80	X
2	REAR TAILGATE ABSORBER LH & RH @\$215.00 <i>xlern</i>		430.00	X
1	REAR TAILGATE LOGO <i>Nec</i>		68.00	✓
1	REAR TAILGATE GARNISH <i>cauled</i>		236.50	✓
1	REAR TAILGATE INNER GARNISH <i>xlern</i>	2170	211.20	X
1	REAR TAILGATE LOCK <i>Dond</i>	1953	453.20	339.
1	REAR TAILGATE RUBBER <i>xlern</i>		212.40	X
1	REAR WIPER MOTOR <i>Dond</i>		351.00	✓
1	REAR TAILGATE LAMP RH <i>enclad</i>		410.00	268
1	REAR BUMPER <i>Regis</i>		722.40	X
2	REAR BUMPER SIDE RETAINER LH & RH @\$115.00 <i>xlern</i>		230.00	X
			4390.00	
less 10%			439.00	10%
			3951.00	
<u>SPECIAL ITEMS</u>				
1 SET	REAR BUMPER CLIPS <i>xlern</i>		100.00	X
1	REAR WINDSCREEN SEALANT <i>xlern</i>	80	80.00	40
1	REAR WINDSCREEN INNER SEAL <i>xlern</i>		70.00	40
1 SET	REVERSE SENSOR <i>xlern</i>		280.00	X
Total Parts			4481.00	



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SGE6839Z MITSUBISHI CORTPLUS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
<u>LABOUR</u>			
1	To remove and panel beat the affected parts & fitting to commence repairs and replace damaged parts	1200.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	400
3	To remove and refix wiring at damaged areas	150.00	30
4	To perform anti rust treatment on affected areas	150.00	X
5	To remove & replace reverse sensor and check for proper functions	120.00	X
6	To remove & refix / replace rear trims , garnish and fittings so as to facilitate repairs as rear compartment	150.00	X
8	To conduct water seepage test	120.00	X
9	To transfer rear boot mechanism	150.00	80
Labour Total :		3040.00	
TOTAL (PARTS & LABOUR) :		7521.00	

810

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 2843
H/S: 1.81K ✓
CNett Value)
04 Days