



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005956  
INV Date 01/09/2020  
Reference CC4/FCI20000185/Uka3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SJE 4265G  
Insured Veh. SHC 394C  
Claim No. D20000117MFSH  
Policy No. D-19092579MFSH  
Accident Date 30/12/2019  
Inspection Date 06/01/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20000185/Uka3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-09-2020		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 394C	Veh. Inspected	SJE 4265G	
Policy No.	D-19092579MFSH	Coverage (\$)	0.00	
Claim No.	D20000117MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	03/01/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUBARU FORESTER (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JF1SJGK85GG080969	Colour	WHITE	
Odometer	61670	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	225/55 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/55 R18	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/55 R18	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/12/2019	Inspection Date	06/01/2020	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 4265G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DENTED	660.30	660.30
2	REAR BUMPER SIDE HOLDER -LH/RH @\$19.20	NOT NECESSARY	38.40	-
2	REAR BUMPER BRACKETS -RH/LH @\$20.20	NOT NECESSARY	40.40	-
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	320.30	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	17.30	-
2	REAR BUMPER REFLECTOR -RH/LH @\$27.40	NOT NECESSARY	54.80	-
1	REAR BUMPER TOP PROTECTOR	CRACKED	380.00	380.00
1	REAR PANEL	TO REPAIR SEE LABOUR	320.00	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	42.30	-
	LESS 20% DISCOUNT		-382.56	-215.86
			1,530.24	863.44
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER SENSOR (SN)	NOT NECESSARY	220.00	-
			220.00	-
	<b><u>LABOUR</u></b>			
	TO REMOVE,REALIGN ,REPAIR ,CUT/WELD ,KNOCK OUT DENTS & REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR PANEL.		600.00	300.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		800.00	400.00
	TO TRANSFER REAR BUMPER SENSOR .		50.00	50.00
	TO REMOVE,REFIT END PANEL GARNISH TO FACILITATE REPAIR.	NOT NECESSARY	50.00	-
			-	-
			-	-
			-	-
			1,500.00	750.00
	<b>GRAND TOTAL</b>		<b>3,250.24</b>	<b>1,613.44</b>

Report Ref No. CC4/FCI20000185/Uka3q2



RECOMMENDED COST OF REPAIRS			1,613.44
-----------------------------	--	--	----------

Report Ref No. CC4/FCI20000185/Uka3q2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SJE 4265G

### INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJE 4265G

RE-INSPECTION

