



TRANS EUROKARS PTE LTD
5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

*Not Admin
Haha nooing*

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE Singapore 199555 ATTN : MOTOR CLAIMS FAX :		NAME : Mr T Rengasamy Ragavel ADDRESS : 970 Hougang Street 91 #15-152 Singapore 530970 TEL : 97697616	WIP : 18005 EXCESS : DATE: 26-Dec-18 <i>Whipped Behn party. 3 dy. 3/1/20</i>
VEH NO :	SFD9420U	DATE IN :	CONTACT PERSON : RONALD / 9127 7928
CHASSIS NO :	JM6GL1071J0136932	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIMS
MODEL :	MAZDA6	DATE REG.: 23-Mar-18	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	REAR BUMPER GJ/GL	1	MGJS1-50-221ABB	DO/A \$ 1,266.60
2	TAPE,PROTECTOR	4	MGS1D-50-EM1A	nu \$ 34.40
3	SENSOR,ULTRASONIC KE/BN	2	MGMK6-67-UC1 13	\$ 363.40
4	SENSOR,ULTRASONIC	2	MKD47-67-UC1 13	\$ 407.20
5	RETAINER	2	MKD45-67-UC5A13	11 \$ 36.40
6	RETAINER	2	MKD47-67-UC5A13	11 \$ 36.40
7	GROMMET,SCREW	1	MBHN1-50-0Z1A	nu \$ 2.70
8	BRACKET,BUMPER SKYACTIV	1	MKD53-50-251	nu \$ 5.40
9	RETAINER RHR BUMPE GJ	1	MGJR9-50-2H1	11 \$ 41.00
10	RETAINER LHR BUMPE GJ	1	MGJR9-50-2J1	11 \$ 41.00
11	SHIELD(R),SPLASH-R.B GJ	1	MGHP9-50-340D	11 \$ 53.90
12	MGHP9-50-350C/SHIELD(L),SPLASH-R.B GJ	1	MGHP9-50-350D	11 \$ 45.60
13	CLIPS	4	MC274-50-133	nu \$ 14.80
14	CAP,DRIP MOULD	2	MGS2A-50-5A1B13	nu \$ 31.80
15	FASTENER	2	MH260-50-841	nu \$ 6.00
16	MGJR9-50-EK1A13/COVER(R),TOWING HOOK	1	MG4YL-50-EK1 13	\$ 24.90
17	MGJR9-50-EL1A13/COVER(L),TOWING HOOK	1	MG4YL-50-EL1 13	\$ 24.90
18	REFLECTOR LHR REFLEX-	1	MD350-51-5M0E	11 \$ 53.00
19	REFLECTOR RHR,REFLEX-	1	MD350-51-5L0E	11 \$ 53.00
20	REINF.,REAR BUMPER GJ/GL	1	MGHK1-50-260	\$ 538.30
21	FASTENER	6	MB45A-56-146A	nu \$ 18.00
22	CLIPS	1	M9991-00-501	nu \$ 3.00
23	PANEL,REAR END GJ	1	MGHY1-70-75Z	R \$ 700.10
	TOTAL PARTS			\$ 3,801.80
	TOTAL PARTS COST			\$ 3,801.80

Labour Description

1		TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND REAR END PANEL. TO REPAIR BOOTLID AND ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$	2,640.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOTLID.	630	\$	2,520.00
3		TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY FOR THE REPAIR ON THE REAR SECTION.	111 X	\$	1,320.00
4		TO SUPPLY TEROSTAT SEALANT ON THE CUTTING AREAS.	111 X	\$	250.00
5		TO TRANSFER REVERSE SENSORS.	180	NETT	\$ 330.00
6		TO SUPPLY 1 PC NUMBER PLATE (REAR)	111 X	NETT	\$ 70.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	111	X	\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120		\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150		\$ 350.00
10		TO SUPPLY BRILA PREMIUM COATING.	150	NETT	\$ 350.00
11	MZ-BR-SUNDRI	SUNDRIES.	111 20	NETT	\$ 100.00

TOTAL LABOUR	\$	-	\$ 8,430.00
TOTAL PARTS	\$	-	\$ 3,801.80
TOTAL	\$	-	\$ 12,231.80
LESS EXCESS	\$	-	\$ -
TOTAL AFTER EXCESS	\$	-	
GST 7%	\$	-	\$ -
GRAND TOTAL	\$	-	\$ -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Acknowledged by Repairer

TRANS EUROKARS PTE LTD

Authorised Signature