



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007552
INV Date 11/11/2020
Reference CC4/FCI20000196/Kka3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKV 9333J
Insured Veh. SH 8816T
Claim No. D20000012MFSH/1
Policy No. D-19092580MFSH
Accident Date 23/12/2019
Inspection Date 06/01/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD	Ref : CC4/FCI20000196/Kka3q2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877	Date : 11-11-2020
	Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8816T	Veh. Inspected	SKV 9333J
Policy No.	D-19092580MFSH	Coverage (\$)	0.00
Claim No.	D20000012MFSH/1	Excess (\$)	0.00
Assign From	CHRIS	Assign Date	27/12/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MR053REH104536808	Colour	METALLIC SILVER
Odometer	58701	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	8 mm
L/H Front Tyre	205/55 R16	PIRELLI	8 mm
R/H Rear Tyre	205/55 R16	PIRELLI	8 mm
L/H Rear Tyre	205/55 R16	PIRELLI	8 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--	--

5. General Information

Accident Date	23/12/2019	Inspection Date	06/01/2020
Survey held at	160 SIN MING DRIVE #05-01		
Repairer	CITY AUTO PTE LTD		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 9333J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL LAMP -RH	SERVICEABLE	348.90	-
1	REAR FENDER -RH	TO REPAIR SEE LABOUR	987.00	-
1	REAR BUMPER	BUCKLED / DENTED	501.50	501.50
1	REAR BUMPER RETAINER	DISTORTED	104.50	104.50
1	REAR BUMPER LAMP	SERVICEABLE	69.74	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	125.00	-
	LESS 25% DISCOUNT		-534.16	-151.50
			1,602.48	454.50
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
			40.00	-
LABOUR				
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS .	NOT NECESSARY	120.00	-
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER -RH .		650.00	500.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		550.00	400.00
			1,320.00	900.00
GRAND TOTAL			2,962.48	1,354.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CC4/FCI20000196/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 9333J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



TOYOTA MOTOR CORPORATION
MODEL: 2E 71R-G XGK2
ENGINE: 1.8L-E T598
TRC No: MF053REH104536808
JLH JEM J.M. 0N04
104-DC1-235
PART: K313-C9A JUN 15
© 2007 TOYOTA MOTOR (THAILAND) CO., LTD. ALL RIGHTS RESERVED



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 9333J

RE-INSPECTION

