

ASS. REC. BY:

REF:

cs/INC20000218/kyd3n2

Special Instruction:

Assigner: Kennedy

ASSIGNMENT (Office)

From (Person): Theresa Vimalan

of

INC

Date/Time: 9:55am @ 3/1/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

JPT 7907

Insured:

SLU 9154

at Workshop m/s

Auto Excel

Tel:

93825367

of

160 Sin Ming Drive #06-01

Policy No:

Claim No:

MT/1077081-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:11am @ 3/1/2020

Person Contacted:

Ryan

Vehicle IN / OUT

Date/Time

Action/Instruction Estimate ✓

JPT 7907 - X

5/3 L1 Rep & 63rd encl & confirm (Red \$8860-17, 58%)

ASS. REC. BY:

REF:

INC 1

ASSIGNMENT

JPT 7907

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Nuclear Optima

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

MAR 504P

Yr Regn:

11, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A

Make:

Toy Vell Fire

c.c

2362

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

111.861

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ANH 20.8103464

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

235/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

24/12/19

D.O.I.

3/1/2020

Survey held at

11.12 am

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 3 MAR 2020

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

5/3/20 Typist

Days Of Repair:

6

Resurvey No. of Trip:

3

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

250

Report Format:

Lump Sum / I.B.I. (\$

6300/-

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Friday, 3 January 2020 9:55 AM
To: 'assignments'
Cc: Theresa Vimala D/O Balagangadharan; Thio Tse Kiat
Subject: RE: TP CASES FARMED OUT TO LKK ON 3/1/2020

Dear LKK

Please assist to survey the following vehicles :

SN	OIC	Claim No.	Appt Type	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	chester	MT/1077081-002	TP	3/1/2020	JPT7907	AUTOEXCEL ENGINEERING PTE LTD	160 SIN MING DRIVE SIN MING AUTOCITY #06-01	Ryan Soh / 93825367				
2		MT/1078094-001	TP	3/1/2020	SLF7157L	TEAM AUTOPRO PTE LTD	BLK 160 SIN MING DRIVE #01-14 SINGAPORE 575722	Eric Lee / 8269 9999				
3		MT/1077727-002	TP	3/1/2020	SMC6867G	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295				
4		MT/1077764-002	TP	3/1/2020	SLH8755T	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295				

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with
you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN

JPT7907

No. Siri B 5582159
IZNEMKOR

Nama Pemunya
Bendaftar

KOH AH HEW

700117015659
[VAL]

Alamat

NO 24 JALAN INDAH 19/4A TAMAN BUKIT INDAH
81200 JOHOR BAHRU JOHOR

No. Enjin : 2AZC822196
No. Chasis : ANH20-8103464
Buatan : TOYOTA
Nama Model : VELLFIRE DBA-ANH20W (A)
Keupayaan Enjin : 2362 S.P
Bahan Bakar : PETROL
Warna : HITAM
Kelas Kegunaan : PSDN-JIP/VAN/BAS/KVN IND
Jenis Badan : WINDOW VAN
Tahun Dibuat : 2010
Tarikh Pendaftaran : 21/11/2013
Status Pemunya : PERSENDIRIAN
Muatan Tempet :
Duduk : 7
Kadar Lesen :
Kenderaan Motor : 6 bulan 12 bulan
RM364.80 RM729.60

B.D M/B G.K -
B.T.T. -
Berat Kerd -
B.T.M -
B.G.1 -
B.G.2 -
B.G.3 -
B.G.4 -
B.G.5 -
B.G.6 -
B.G.7 -
B.G.8 -
B.G.9 -
B.G.10 -
B.G.11 -
B.G.12 -

Tandatangan Pemunya Bendaftar

Perakuan Pendaftaran ini dikeluarkan
oleh Pengerah JPJ Negeri JPJ NEGERI JOHOR

UNTUK KEGUNAAN PEJABAT

KENDERAAN IMPORT TERPAKAI

HAK MILIK DITUNTUT OLEH: PUBLIC BANK BERHAD NO SIRI: H05/627823/13

NOTA PENTING

- Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
- Senak butiran-butiran kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
- Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh memperbaharui lesen 60 hari sebelum tempohnya tamat.
- Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berlesen.
- Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
- Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
- Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.



Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20191224/2087

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/12/2019 15:10	Vide Report No.: G/20191224/0137	Station Diary No.: 28
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: FONG KAH HUI			Address: 8 WILKIE ROAD #02-01 SINGAPORE 228095		
ID Type / ID No.: FIN NO / G1534699Q			Contact No.: Home/Office: Mobile: 90019907		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 25	Date of Birth: 23/01/1994	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: ADMINISTRATIVE OFFICER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 24/12/2019 13:15	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Before exit 9 (Jln eunos)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JPT7907	Car	TOYOTA			Slightly Damaged	0
SLU915H	Car	AUDI			Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20191224/2087

CONTINUATION OF REPORT

Driver			
Name	FONG KAH HUI	ID No.	G1534699Q
Related Vehicle	JPT7907 (Car)	Contact No.	90019907
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM CHIN SIANG	ID No.	NIL
Related Vehicle	SLU915H (Car)	Contact No.	97660780
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 24/12/2019 at about 1.16pm, I was driving in my car JPT7907 along the first lane of PIE towards airport direction. When I am nearing exit 9 of Jln Eunos, the Audi car in front of me suddenly did an emergency brake. I quickly step on my brake pedal and came to a complete stop. Right after, I felt an impact coming from the rear of my car. Luckily, the impact did not cause my car to hit onto the Audi car in front of me.

After, all of us came down to make a check on our vehicles and discovered that another car SLU915H had hit onto the rear of my car. As a result, my car rear boot cover and bumper at the rear left side were dented and have multiple scratches. While the other car had its bonnet popped open.

I am not injured and I've asked the other driver and he told me that he is fine as well. I have both front and back in-car camera installed and I have the footage as well.



SINGAPORE
POLICE FORCE



T/20191224/2087

3 of 3

Report No. T/20191224/2087

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Sgt 3 NG KA WAI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

24/12/2019 15:10

Officer In Charge Of Case:

TP / AEIT /
SSI 2 YEO GEAK ENG CECILIA
Contact No.: 65476404

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

Hy

Not Withheld
11 Sep @ 8300h
Resurvey After Point
6 days

ALICEYON ENGINEERING PTE LTD
2nd Fl, 100, North Bridge Road
Singapore 07007107 806-15
Singapore 075722
Tel: 645 0634, 64501630
Fax: 64501630

Date : 02/01/2020

QUOTATION -THIRD PARTY CLAIM

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : JPT 7907
Model : TOYOTA VELLFIRE
Insured Ins: NTUC INCOME

Accident on : 14/12/2019

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SLU 915 H		
1	TAILGATE 1870	\$ 2,488.00	✓
1	TAILGATE W/SCREEN MOULDING	\$ 280.00	—
1	TAILGATE CENTER LOGO	\$ 61.00	—
1	TAILGATE VELLFIRE	\$ 72.00	—
1	TAILGATE LAMP LH	\$ 785.00	X
1	TAILGATE TRIM BOARD	\$ 680.00	✓
1	TAILGATE LOCK	\$ 385.00	X
1	REAR RH FENDER	REPAIR	
	REAR LH FENDER INNER SIDE TRIM	\$ 785.00	✓
1	REAR RH FENDER UNDERSHIELD	\$ 181.45	X
1	REAR RH FENDER UNDERSHIELD CLIPS	\$ 35.00	X
1	REAR RH FENDER INNER AIRDUCT	\$ 220.00	X
1	TAILLAMP LH 524.40	\$ 980.45	✓
1	TAILLAMP LOWER BRACKET LH	\$ 181.45	✓
1	TAILLAMP PANEL LH	\$ 320.00	X
1	REAR LH CORNER PANEL	\$ 850.90	X
1	REAR BUMPER 820.30	\$ 2,488.50	✓
2	REAR BUMPER SENSORS	\$ 620.00	✓
1SET	REAR BUMPER SENSOR CABLE ASSY 648.20 Cur/Shm	\$ 988.45	✓
4	REAR BUMPER SENSOR OUTER RIMS X 4 ESS	\$ 360.00	220 ✓
1	REAR BUMPER RETAINER LH	\$ 282.45	✓
1	REAR BUMPER REFLECTOR LH	\$ 181.58	X
10	REAR BUMPER CLIPS	\$ 45.00	✓
1	END PANEL	\$ 680.50	—
1	END PANEL TOP GARNISH 265.90	\$ 420.00	—
1	FLOOR PANEL	REPAIR	
1	FLOOR PANEL TOP BOARD	\$ 748.50	X
		\$ 15,120.23	
	Less 25%	\$ 3,780.06	
		\$ 11,340.17	
	<u>S/NETT</u>		
2T	REAR W/SCREEN SEALANT	\$ 140.00	405 ✓
	TOTAL S/N :	\$ 140.00	
	TOTAL PARTS :	\$ 11,480.17	

Fax: 64591698

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
L/Sy @ ?
Recovery After Point
6 days

Date : 02/01/2020

QUOTATION -THIRD PARTY CLAIM

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 14/12/2019

Claim : Third Party Claim
Veh. No : JPT 7907
Model : TOYOTA VELLFIRE
Insured Ins: NTUC INCOME

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SLU 915 H		
1	TAILGATE <i>By</i>	\$ 2,488.00	✓
1	TAILGATE W/SCREEN MOULDING <i>Re</i>	\$ 280.00	✓
1	TAILGATE CENTER LOGO <i>Re</i>	\$ 61.00	✓
1	TAILGATE VELLFIRE <i>Re</i>	\$ 72.00	✓
1	TAILGATE LAMP LH <i>Sn</i>	\$ 785.00	X
1	TAILGATE TRIM BOARD	\$ 680.00	?
1	TAILGATE LOCK	\$ 385.00	X
1	REAR RH FENDER	REPAIR	
	REAR LH FENDER INNER SIDE TRIM	\$ 785.00	?
1	REAR RH FENDER UNDERSHIELD	\$ 181.45	?
1	REAR RH FENDER UNDERSHIELD CLIPS	\$ 35.00	?
1	REAR RH FENDER INNER AIRDUCT	\$ 220.00	?
1	TAILLAMP LH	\$ 980.45	?
1	TAILLAMP LOWER BRACKET LH	\$ 181.45	?
1	TAILLAMP PANEL LH	\$ 320.00	?
1	REAR LH CORNER PANEL	\$ 850.90	?
1	REAR BUMPER <i>By</i>	\$ 2,488.50	✓
2	REAR BUMPER SENSORS <i>nd/short</i>	\$ 620.00	✓
1SET	REAR BUMPER SENSOR CABLE ASSY	\$ 988.45	?
	REAR BUMPER SENSOR OUTER RIMS	\$ 360.00	?
1	REAR BUMPER RETAINER LH <i>Dir</i>	\$ 282.45	✓
1	REAR BUMPER REFLECTOR LH	\$ 181.58	?
10	REAR BUMPER CLIPS <i>Re</i>	\$ 45.00	✓
1	END PANEL <i>Sn</i>	\$ 680.50	✓
1	END PANEL TOP GARNISH <i>ng o'1</i>	\$ 420.00	✓
1	FLOOR PANEL	REPAIR	
1	FLOOR PANEL TOP BOARD <i>Sn</i>	\$ 748.50	X
		\$ 15,120.23	
	Less 25%	\$ 3,780.06	
		\$ 11,340.17	
	S/NETT		
2T	REAR W/SCREEN SEALANT <i>Re</i>	\$ 140.00	405n
	TOTAL S/N :	\$ 140.00	
	TOTAL PARTS :	\$ 11,480.17	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000218/Kyd3n2
73 BRAS BASAH ROAD Date: 06-03-2020
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: CHESTER

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 915H	Veh. Inspected	JPT 7907
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	03/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	ANH208103464	Colour	METALLIC BLACK
Odometer	111861 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	PIRELLI	7 mm
L/H Front Tyre	235/50 R18	PIRELLI	7 mm
R/H Rear Tyre	235/50 R18	PIRELLI	8 mm
L/H Rear Tyre	235/50 R18	PIRELLI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/12/2019	Inspect Date / Time	03/01/2020 (11:12 AM)
Survey held at	AUTOEXCEL ENGINEERING PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JPT 7907

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	2,488.00	1,870.00
1	TAILGATE W/SCREEN MOULDING	NECESSARY	280.00	280.00
1	TAILGATE CENTER LOGO	NECESSARY	61.00	61.00
1	TAILGATE VELLFIRE	NECESSARY	72.00	72.00
1	TAILGATE LAMP LH	SERVICEABLE	785.00	-
1	TAILGATE TRIM BOARD	MTG CRACKED	680.00	680.00
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	385.00	-
1	REAR RH FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR LH FENDER INNER SIDE TRIM	CRACKED	785.00	785.00
1	REAR RH FENDER UNDERSHIELD	SERVICEABLE	181.45	-
1	REAR RH FENDER UNDERSHIELD CLIPS	NOT NECESSARY	35.00	-
1	REAR RH FENDER INNER AIRDUCT	SERVICEABLE	220.00	-
1	TAILLAMP LH	MTG CRACKED	980.45	524.40
1	TAILLAMP LOWER BRACKET LH	DISTORTED	181.45	181.45
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	320.00	-
1	REAR LH CORNER PANEL	TO REPAIR SEE LABOUR	850.90	-
1	REAR BUMPER	BENT	2,488.50	820.30
2	REAR BUMPER SENSORS	DENTED / SHORTED	620.00	620.00
1	SET REAR BUMPER SENSOR CABLE ASSY	CUT / SHORTED	988.45	648.20
4	REAR BUMPER SENSOR OUTER RIMS	NECESSARY	360.00	220.00
1	REAR BUMPER RETAINER LH	DISTORTED	282.45	282.45
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	181.58	-
10	REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	END PANEL	BUCKLED	680.50	680.50
1	END PANEL TOP GARNISH	MTG DISTORTED	420.00	265.90
1	FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FLOOR PANEL TOP BOARD	SERVICEABLE	748.50	-

Report Ref No. CS/INC20000218/Kyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-3,780.06	-2,009.05
			11,340.17	6,027.15
	SPECIAL NETT ITEMS			
1	2T REAR W/SCREEN SEALANT (SN)	NECESSARY	140.00	40.00
			140.00	40.00
	LABOUR			
	LABOUR CHARGES TO DO CUTTING,WELDING ALIGN,ADJUST ON ACCIDENT DAMAGE AREA.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK,REAR RH FENDER,TAILLAMP PANEL LH,REAR LH CORNER PANEL AND FLOOR PANEL.		1,200.00	700.00
	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,200.00	800.00
	TO REMOVE REFIX GARNISH,SIDE TRIM,GARNISH CAR SEAT,TRIM BOARD UPHOLSTERY ETC.		380.00	100.00
	TO REPLACE SENSOR,SETTING DELETE FAULT CODE,DECODING AFTER REPAIR.	NOT NECESSARY	200.00	-
	TO CHECK REAR WIRING SYSTEM.		120.00	20.00
	TRANSFER TAILGATE PARTS TO ANOTHER TAILGATE.		120.00	60.00
	TO REMOVE REFIX REAR W/SCREEN.		140.00	120.00
	TO DO ANTI RUST.		120.00	60.00
	TO DO SEALANT,SEAL GAP,WATERPROOFING ON CUTTING WELDING AFFECTED AREA.		200.00	30.00
			3,680.00	1,890.00
GRAND TOTAL			15,160.17	7,957.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				6,300.00

Report Ref No. CS/INC20000218/Kyd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.