

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24732

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1544/2019/NS
Date : 2-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Rasul

12 days exclude 2 Sundays

jb 9 May 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Beatrice Cheng Bee Ong
Address : 90 Chestnut Drive
Singapore 679319
Telephone : (HP) 91370140
Type of Claim : Own Damage Claims
Policy No. : 1700086430-01
Vehicle No : **SJX 753 R**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 7/12/2017
Engine No : CVK 050875
Chassis No : WAUZZZF5XJA049879
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Dec-20
Place of Accident : Golden Mile Complex Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJX 753 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage	S/N \$	360.00	\$ 360.00
2	To remove and transfer lhs rear door's multi-lock system and power window devices. Check function and renew if	S/N \$	280.00	
3	To renew lhs 1/4 glass to facilitate fender renewal.	S/N \$	300.00	\$ 300.00
4	To install 1/4 glass solar film.	S/N \$	400.00	\$ 400.00
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay travs. electrical and audio equipment	S/N \$	1,400.00	\$ 1,400.00
SUB TOTAL LABOUR CHARGES		:	\$ 2,740.00	\$ 2,460.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJX 753 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
	<i>c/f</i>		\$ 2,460.00
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc	S/N \$ 1,400.00	\$ 1,400.00
7	To dismantle rear bumper, rear lid, rhs sill panel trim and lhs rear door. Cut out and weld lhs rear fender. To renew lhs rear door. Re-organise crash management components. Reinstall all parts removed	\$ 8,000.00	\$ 3,000.00
8	To respray rhs rear door, door handle, rhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip	\$ 5,400.00	\$ 2,475.00
9	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	
10	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 18,012.00	\$ 9,527.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJX 753 R

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remarks</u>
1	SIDE PANEL - LH	\$ 2,285.00	\$ 1,828.00
2	SIDE WINDOW - LH	\$ 653.00	\$ 522.40
3	REAR DOOR - LH	\$ 2,829.00	
4	REAR DOOR OUTER SEAL-LH	NEC \$ 201.00	
5	BONDING AGENT	NEC \$ 45.00	
6	CLEANING SOLUTION	NEC \$ 65.00	
7	REAR DOOR CATCH	\$ 109.00	
8	DOOR HANDLE TRIM PLATE - LH	\$ 80.00	
9	TRIM - LH	\$ 124.00	
10	SILL PANEL TRIM ATTACHMENT PARTS	\$ 118.00	\$ 94.00
11	SILL PANEL TRIM ADHESIVE TAPES	\$ 192.00	\$ 153.20
12	WHEEL HOUSING LINER - LH	\$ 256.00	
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 82.00	
14	REAR ALUMINIUM RIM - LH	\$ 943.00	
15	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
16	CAVITY WAX	S/N \$ 140.00	\$ 140.00
17	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
18	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
19	STONE CHIP	S/N \$ 180.00	\$ 180.00
20	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS CHARGES		: \$ 9,262.00	\$ 3,477.60
TOTAL LABOUR CHARGES		: \$ 18,012.00	\$ 9,527.00
GRAND TOTAL		: \$ 27,274.00	\$ 13,004.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.