

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24732

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1544/2019/NS
Date	:	2-Jan-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Beatrice Cheng Bee Ong
Address	:	90 Chestnut Drive Singapore 679319
Telephone	:	(HP) 91370140
Type of Claim	:	Own Damage Claims
Policy No.	:	1700086430-01
Vehicle No	:	SJX 753 R
Model Code	:	Audi A5 SB 2.0 TFS
Model / Year	:	7/12/2017
Engine No	:	CVK 050875
Chassis No	:	WAUZZZF5XJA049879
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-Dec-20
Place of Accident	:	Golden Mile Complex Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJX 753 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00 /	
2	To remove and transfer lhs rear door's multi-lock system and power window devices. Check function and renew if necessary.	S/N \$	280.00 X	NN
3	To renew lhs 1/4 glass to facilitate fender renewal.	S/N \$	300.00 /	
4	To install 1/4 glass solar film.	S/N \$	400.00 ? invoice?	✓ 200.00
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00 /	
SUB TOTAL LABOUR CHARGES		:	\$ 2,740.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJX 753 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
7	To dismantle rear bumper, rear lid, lhs sill panel trim and lhs rear door. Cut out and weld lhs rear fender. To renew lhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 8,000.00 4500	3,000.00
8	To respray lhs rear door, door handle, lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,400.00 3075	2,475.00
9	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00 X	NN
10	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 18,012.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJX 753 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	SIDE PANEL - LH <i>X LH</i>	\$ 2,285.00	1,828.00
2	SIDE WINDOW - LH <i>rec</i>	\$ 653.00	522.40
3	REAR DOOR - LH <i>rec-V</i>	\$ 2,829.00	X
4	REAR DOOR OUTER SEAL-LH <i>rec</i> X NN	NEC \$ 201.00	X
5	BONDING AGENT <i>rec</i> X NN	NEC \$ 45.00	X
6	CLEANING SOLUTION <i>rec</i> X NN	NEC \$ 65.00	X
7	REAR DOOR CATCH <i>X</i> X NN	\$ 109.00	X
8	DOOR HANDLE TRIM PLATE - LH <i>X</i> X NN	\$ 80.00	X
9	TRIM - LH <i>X</i> X NN	\$ 124.00	X
10	SILL PANEL TRIM ATTACHMENT PARTS <i>rec</i>	\$ 118.00	94.00
11	SILL PANEL TRIM ADHESIVE TAPES <i>rec</i>	\$ 192.00	153.20
12	WHEEL HOUSING LINER - LH <i>X</i> X NN	\$ 256.00	X
13	WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i> X NN	\$ 82.00	X
14	REAR ALUMINIUM RIM - LH <i>X</i> X SVC	\$ 943.00	X
15	ACRYLIC SEALANT <i>rec</i>	S/N \$ 180.00	✓
16	CAVITY WAX <i>rec</i>	S/N \$ 140.00	✓
17	METAL FILLER POWDER <i>rec</i>	S/N \$ 280.00	✓
18	1/4 GLASS SEALANT <i>rec</i>	S/N \$ 100.00	✓
19	STONE CHIP <i>rec</i>	S/N \$ 180.00	✓
20	SUNDRIES <i>X</i> X NN	\$ 400.00	X
TOTAL SPARE PARTS CHARGES		: \$ 9,262.00	
TOTAL LABOUR CHARGES		: \$ 18,012.00	
GRAND TOTAL		: \$ 27,274.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Rasm - Hp 90010068
Surveyed Date : 03/01/2020 @ 1550
Authorised Date :
Excess Cost : 12 days
Liability : EXCESS: TBA
Remarks :
REVERT
Resurvey before paint

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel.6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant