

ASS. REC. BY:

REF: CS / FWD 20000232 / EF302

Special Instruction: ok

Surveyor: SireASSIGNMENT (Office)From (Person): Eileen Bayof FWDDate/Time: 3 Jan 2020 18:24:13

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SKA 65805

Insured: _____

at Workshop m/s Automotive Repair CentreTel: 64688834of 38 woodland Industrial Park E1, #05-18Policy No: PNPV2019-00009656Claim No: 1201900042959

Sum Insured: _____

Excess: \$500.00

Make of Veh: _____

D.O.A. 30.12.2019

(Client's record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 6.1.2020 9:38a.mPerson Contacted: Sir W IvanVehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKA 65805-X6/1@17:23 mandate request lump sum due to 2008 model.6/1@18:07 mandate approval by Eileen Bay lump sum.7/1@9:02am inform workshop repair inform insured on lump sum
Sign lump sum

ASK REG BY:

Steve

REF:

FWD CS/FWD 20000232/E4f2

ASSIGNMENT

From

Date

6-Jan-2020

Estimated Cost:

OD / AP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKA 65805

at Workshop m/s

Automotive Repair Centre

of 38 Woodland Industrial Park G1 #05-18

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKA 65805

Yr Regn:

20/11/08

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz 1.5

C.C. 1497

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

250570

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMBE8850952007H

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

30/12/19

D.O.I.

6/1/99

Survey held at

Automotive Repair Centre

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK-26.000 23/12

PV-11.530

NR-14.470

Lump Sum \$9800/- (Red: 5938; 37%)

Date/Time, File Pass to?



Preli. Report

11/3 Typist



Final Report

Date/Time, File Return to?

21

Rep. Form:

OD

Lump Sum / F.R.:

9800

Days Of Repair:

10

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Meal and (\$

Survey Fee:

250

Transportation:

50

S + RS, SI

50+50

Photos

Notes

11

TOTAL

411

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2020 17:03 Sendback Est	03 Jan 2020 17:38 S\$11,703.00	03 Jan 2020 18:24 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ADNAN MOHD ALI, ID: S8613762C		
Vehicle Reg. No.:	SKA6580S	Date of Loss:	30/12/2019 14:00 - :59 [133 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900042959	Policy/Cover Note No.:	PNPV2019-00008656 (Comprehensive) Coverage: 17/05/2019 - 17/05/2020
		Excess:	S\$500.00
Repairer:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834		
Handling Insurer:	FWD Singapore Pte. Ltd, (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 7 January 2020 9:02 AM
To: raymond@automotiverepaircentre.com.sg
Cc: kenguan@automotiverepaircentre.com.sg;
shujuan@automotiverepaircentre.com.sg; SUR
Subject: SKA 6580S / OD / FWD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKA 6580S (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Please explain to our insured on lump sum repair basis and signed lump sum repair authorization form, email back once done.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKA65805 (1201900042959)

OD

Dec 30 2019 2:00PM

[ADNAN MOHD ALI]

Automotive Repair Centre Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 06/01/2020 18:07 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8750.00) - SKA65805 - Claim Handler: Eileen Bay

Approved:8750.00:Please inform workshop to explain to our insured on lump sum repair basis and upload a copy of signed lump sum repair authorization form in Merimen.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: raymond@automotiverepaircentre.com.sg
Sent: Monday, 9 March 2020 5:45 PM
To: Denise Tay (LKKAuto)
Cc: kenguan@automotiverepaircentre.com.sg; 'Lin Shu Juan'
Subject: RE: SKA6580S / OD / FWD / DOA: 30/12/2019

Hi Denise,

We confirmed repair at L/S \$9,800.00 before gst and excess (10 repair days)

Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Monday, 9 March 2020 5:31 PM
To: raymond@automotiverepaircentre.com.sg
Subject: RE: SKA6580S / OD / FWD / DOA: 30/12/2019

Dear Raymond,

Any update?

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Friday, 28 February 2020 2:56 PM
To: raymond@automotiverepaircentre.com.sg
Subject: SKA6580S / OD / FWD / DOA: 30/12/2019

Dear Raymond,

Enclosed supplementary and estimate.

Offer at lump sum \$9800, 10days

If you are agreeable, I will take approval from insurance.

> Back to OneMotoring

3-10-6

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 762C

Vehicle Details

Vehicle No.: SKA65805
Vehicle to be Exported: Yes
Intended Deregistration Date: 31 Dec 2019
Vehicle Make: HONDA
Vehicle Model: JAZZ 1.5L AT ABS D/AB HID 2WD 5DR
Primary Colour: Red
Manufacturing Year: 2008
Engine No.: L15A71000885
Chassis No.: JHMGE88509S200779
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$21,214.00
Original Registration Date: 20 Nov 2008
First Registration Date: 20 Nov 2008
Transfer Count: 3
Actual ARF Paid: \$21,214.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Nov 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$14,835.00
COE Rebate Amount: \$11,530.00
Total Rebate Amount: \$11,530.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/12/2019 17:25
Date Of Accident	30/12/2019 14:45
Exact Location Of Accident	ALONG CTE TOWARDS TOWN EXIT BRADDELL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA6580S
Insured/Policyholder	
Name Of Registered Owner	ADNAN MOHD ALI
NRIC No	SXXXX762C
Email Address	PLAYLISTED@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98531986
Alternative Phone No	OFFICE-98531986

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00008656
Cover Note Number	

Driver

Name of Driver	ADNAN MOHD ALI
NRIC No	SXXXX762C
Date Of Birth	19/05/1986
Occupation	INDOOR
Date Of Driving Pass	09/06/2007
Driving Experience	12 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98531986
Fax Number	
Contact Number	OFFICE-98531986
Email Address	PLAYLISTED@HOTMAIL.COM

Address	BLK 348 WOODLANDS AVE 3 #08-73
Postcode	730348
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	FBD1074H
	-
Insurance Company of Driver's Own Vehicle	FWD SINGAPORE PTE. LTD.
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA2058S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGP2210E
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Updated: 2008/01/01

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Lorry B came to a stop suddenly and I collided
into lorry B rear

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

6/11/14

Driver's Signature

(If driver is not the policyholder)

Date & Time:

AR



Reporting Centre Personnel's Signature

Name:

NRIC/Fish No.:

Automotive Repair Centre Pte Ltd (Co.Reg.No.201312913C)

38 Woodlands Industrial Park E1, #05-18

Singapore 757700

Tel: 64688834 Fax: 64622278 Email: raymond@automotiverepaircentre.com.sg

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	PNPV2019-00008656	Date of Loss:	30/12/2019
Vehicle Reg. No.:	SKA6580S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ADNAN MOHD ALI		
Make/Model:	HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)	Vehicle Reg. Date:	20/11/2008
Vehicle Colour:	Red		
Engine No:	L15A71000885	Chassis No:	JHMGE88509S200779
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Remarks:	VEHICLE IN WORKSHOP. PLEASE ARRANGE SURVEY SOONEST.		
Present Location:	AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	8,412.00
Miscellaneous Items	301.00
Labour	2,990.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	11,703.00
- Excess (S\$)	500.00
(S\$)	11,203.00
+ GST 7.00% (S\$)	784.21
Nett Amount (S\$)	11,987.21

This claim is handled by: NG KENG GUAN

Steve (LKR)

OD - Not Author (Rent)

EXCESS - \$500

L/S

Ry AL spj

10 days

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2020)

Parts: 144 HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Automotive Repair Centre Pte Ltd/KA6580S/03/01/2020 17:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER ✓ OR	0.00	0.00	*160.00 F
2	1		*FRONT BUMPER CLIPS X 10 / MC	0.00	0.00	*10.00 F
3	1		*FRONT BUMPER LOWER RUBBER LID / MIS	0.00	0.00	*40.00 F
4	1		*FRONT REINFORCEMENT / DD	0.00	0.00	*75.00 F
5	1		*FRONT BUMPER RETAINER RH / OR	0.00	0.00	*7.00 F
6	1		*FRONT BUMPER RETAINER LH / OR	0.00	0.00	*7.00 F
7	1		*FRONT BUMPER LOWER GRILLE / OR	0.00	0.00	*55.00 F
8	1		*FRONT GRILLE (CENTRE) / MIS	0.00	0.00	*60.00 F
9	1		*FRONT GRILLE CLIPS X 10 / MC	0.00	0.00	*10.00 F
10	1		*FRONT EMBLEM / MIS	0.00	0.00	*15.00 F
11	1		*FRONT BUMPER TOWING COVER / MIS	0.00	0.00	*10.00 F
12	1		*HEAD LAMP RH / OR	0.00	0.00	*320.00 F
13	1		*HEAD LAMP LH / OR	0.00	0.00	*320.00 F
14	1		*HEAD LAMP BRACKET RH / OR	0.00	0.00	*14.00 F
15	1		*HEAD LAMP BRACKET LH / OR	0.00	0.00	*14.00 F
16	1		*FRONT BONNET / DD	0.00	0.00	*200.00 F
17	1		*FRONT BONNET SEAL RH / MIS	0.00	0.00	*6.00 F
18	1		*FRONT BONNET SEAL LH / MIS	0.00	0.00	*6.00 F
19	1		*FRONT BONNET LOCK / OT	0.00	0.00	*65.00 F
20	1		*FRONT BONNET HINGE RH / OT	0.00	0.00	*16.00 F
21	1		*FRONT BONNET HINGE LH / OT	0.00	0.00	*16.00 F
22	1		*FRONT BONNET INSULATOR CLIPS X 4 / MC	0.00	0.00	*8.00 F
23	1		*FRONT UNDERCARRIAGE COVER RH ? X NN	0.00	0.00	*20.00 F X
24	1		*FRONT UNDERCARRIAGE COVER LH ? X NN	0.00	0.00	*20.00 F X
25	1		*FRONT UNDERCARRIAGE COVER CLIPS X 12 ? X NN	0.00	0.00	*12.00 F X
26	1		*FRONT FENDER RH / DD	0.00	0.00	*95.00 F
27	1		*FRONT FENDER LH / DD	0.00	0.00	*95.00 F
28	1		*FRONT FENDER SHIELD RH / OR	0.00	0.00	*25.00 F
29	1		*FRONT FENDER SHIELD LH / OR	0.00	0.00	*25.00 F
30	1		*FRONT FENDER CLIPS RH X 9 / MC	0.00	0.00	*9.00 F
31	1		*FRONT FENDER CLIPS LH X 9 / MC	0.00	0.00	*9.00 F
32	1		*FRONT FENDER CLIPS RH (SQUARE CLIPS) X 3 / MC	0.00	0.00	*6.00 F
33	1		*FRONT FENDER CLIPS LH (SQUARE CLIPS) X 3 / MC	0.00	0.00	*6.00 F
34	1		*WASHER TANK / CR4	0.00	0.00	*25.00 F
35	1		*WASHER TANK FILTER NECK / CR4	0.00	0.00	*10.00 F
36	1		*WASHER TANK PUMP ? X NN	0.00	0.00	*30.00 F X
37	1		*FRONT HORN SET / OR	0.00	0.00	*25.00 F
38	1		*AIR FILTER BOX LOWER ? X NN	0.00	0.00	*60.00 F X
39	1		*AIR FILTER BOX COVER X NN	0.00	0.00	*45.00 F X
40	1		*AIR INTAKE DUCT ? X NN	0.00	0.00	*18.00 F
41	1		*FRONT SUPPORT PANEL / DD	0.00	0.00	*130.00 F
42	1		*RADIATOR / DD	0.00	0.00	*230.00 F
43	1		*RADIATOR SHROUD ? / OR	0.00	0.00	*45.00 F
44	1		*RADIATOR FAN BLADE ? / CH	0.00	0.00	*35.00 F
45	1		*RADIATOR FAN MOTOR ? / JOMAR	0.00	0.00	*160.00 F
46	1		*RADIATOR SPARE TANK ? X NN	0.00	0.00	*20.00 F X
47	1		*RADIATOR SPARE TANK CAP ? X NN	0.00	0.00	*5.00 F X

48	1	*RADIATOR UPPER HOSE / <i>CU</i>	0.00	0.00	*13.00 F
49	1	*RADIATOR LOWER HOSE / <i>X NN</i>	0.00	0.00	*12.00 F X
50	1	*RADIATOR TOP BRACKET RH / <i>OT</i>	0.00	0.00	*10.00 F
51	1	*RADIATOR TOP BRACKET LH / <i>OT</i>	0.00	0.00	*10.00 F
52	1	*A/C CONDENSER / <i>DD</i>	0.00	0.00	*240.00 F
53	1	*A/C SHROUD / <i>OR</i>	0.00	0.00	*48.00 F
54	1	*A/C FAN BLADE / <i>CUT</i>	0.00	0.00	*30.00 F
55	1	*A/C FAN MOTOR / <i>Jam</i>	0.00	0.00	*95.00 F
56	1	*A/C PIPE DISCHARGE HOSE / <i>OT</i>	0.00	0.00	*80.00 F
57	1	*A/C OUTLET PIPE / <i>OT</i>	0.00	0.00	*70.00 F
58	1	*A/C COMPRESSOR SUCTION HOSE / <i>OT</i>	0.00	0.00	*80.00 F
59	1	*AIR FILTER TOP COVER REAR / <i>X NN</i>	0.00	0.00	*10.00 F X
60	1	*ENGINE BRACKET FOR MOUNTING RH / <i>OR</i>	0.00	0.00	*40.00 F
61	1	*ENGINE BRACKET FOR MOUNTING LH / <i>OT</i>	0.00	0.00	*40.00 F
62	1	*ENGINE MOUNTING RH / <i>OR</i>	0.00	0.00	*75.00 F
63	1	*ENGINE MOUNTING LH / <i>TN</i>	0.00	0.00	*75.00 F
64	1	*ENGINE MOUNTING REAR / <i>TN</i>	0.00	0.00	*70.00 F
65	1	*FRONT ABS SENSOR RH / <i>X NN</i>	0.00	0.00	*85.00 F X
66	1	*FRONT ABS SENSOR LH / <i>X NN</i>	0.00	0.00	*85.00 F X
67	1	*FRONT CROSS MEMBER / <i>X NN</i>	0.00	0.00	*280.00 F X
68	1	*FRONT AIR BAG RH / <i>OR</i>	0.00	0.00	*450.00 F
69	1	*FRONT AIR BAG LH / <i>OR</i>	0.00	0.00	*450.00 F
70	1	*FRONT SEAT BELT RH / <i>Jam</i>	0.00	0.00	*170.00 F
71	1	*FRONT SEAT BELT LH / <i>PU?</i>	0.00	0.00	*170.00 F
72	1	*REEL CABLE FOR AIR BAG AT STEERING WHEEL / <i>M</i>	0.00	0.00	*200.00 F
73	1	*SRS CONTROL UNIT / <i>MC</i>	0.00	0.00	*520.00 F
74	1	*FRONT BUMPER CRASH SENSOR RH / <i>MC</i>	0.00	0.00	*85.00 F
75	1	*FRONT BUMPER CRASH SENSOR LH / <i>MC</i>	0.00	0.00	*85.00 F
76	1	*FRONT WINDSCREEN / <i>OR</i>	0.00	0.00	*900.00 F
77	1	*FRONT WINDSCREEN MOULDING / <i>MC</i>	0.00	0.00	*50.00 F
78	1	*FRONT WINDSCREEN COWLING ASSY / <i>OR</i>	0.00	0.00	*220.00 F
79	1	*SIDE COWLING COVER RH / <i>OR</i>	0.00	0.00	*20.00 F
80	1	*SIDE COWLING COVER LH / <i>MS</i>	0.00	0.00	*20.00 F
81	1	*FRONT SIDE CORNER GLASS MOULDING RH / <i>OR</i>	0.00	0.00	*20.00 F
82	1	*FRONT SIDE CORNER GLASS MOULDING LH / <i>X NN</i>	0.00	0.00	*20.00 F X
83	1	*THROTTLE BODY / <i>X NN</i>	0.00	0.00	*250.00 F X
84	1	*INTAKE MANIFOLD ASSY / <i>CUT</i>	0.00	0.00	*250.00 F
85	1	*FOG LAMP RH / <i>X NN</i>	0.00	0.00	*190.00 F X
86	1	*FOG LAMP LH / <i>X NN</i>	0.00	0.00	*190.00 F X
87	1	*FOG LAMP GARNISH RH / <i>DD</i>	0.00	0.00	*55.00 F
88	1	*FOG LAMP GARNISH LH / <i>OR</i>	0.00	0.00	*55.00 F

F=Franchise part.

Total Parts (S\$)

8,412.00

Automotive Repair Centre Pte Ltd/SKA6580S/03/01/2020 17:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BATTERY / DR	120.00
2	1	COOLANT FLUID / MC	40.00
3	1	FRONT NUMBER PLATE WITH CASING / DR	35.00
4	1	SUPPLY OF IU BRACKET / MC	26.00
5	1	SUPPLY OF SEALANT (FRONT FENDER SIDE GLASS) / MC	40.00
6	1	SUPPLY OF SEALANT (FRONT WINDSCREEN) / MC	40.00
Sub Total (S\$)			301.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Spraying painting Whole Front	New	1,000.00
2	Remove, Replace, Refit and Repair Accident Affected Area	New	1,000.00
3	Remove and Refit Engine and Transmission to Facilitate Repair	New	350.00
4	Remove and Refit A/C Condenser, Radiator including A/C Gas	New	100.00
5	Remove and Replace Front Windscreen	New	120.00
6	Reset Fault Code and Sensors Replacement	New	150.00
7	Check and Rectify Electrical Wiring	New	20.00
8	Remove and Refit Dashboard to Facilitate Airbag Replacement	New	250.00
Gross Labour Cost (S\$)			2,990.00

Automotive Repair Centre Pte Ltd/SKA6580S/03/01/2020 17:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LIC Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Estimates are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Automotive Repair Centre Pte Ltd (Co. Reg. No. 201312913C)

38 Woodlands Industrial Park E1, #05-18

Singapore 757700

Tel: 64688834 Fax: 64622278 Email: raymond@automotiverepaircentre.com.sg

INSURER:

FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type	OD (Own Damage)	Ref. No:	
Policy No:	PNPV2019-00008856	Date of Loss:	30/12/2019
Vehicle Reg. No.:	SKA6580S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ADNAN MOHD ALI		
Make/Model:	HONDA JAZZ, 1.5 1.5L MT ABS D/AB	Vehicle Reg. Date:	20/11/2008
	HID 2WD 5DR (A)		
Vehicle Colour:	Red	Chassis No:	JHMGE88509S200779
Engine No:	L15A71000885		
Odometer:	0 KM		

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) 14

Remarks: VEHICLE IN WORKSHOP. PLEASE ARRANGE SURVEY SOONEST.

Present Location: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	8,412.00
Miscellaneous Items	301.00
Labour	2,990.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	11,703.00
- Excess (S\$)	500.00
(S\$)	11,203.00
+ GST 7.00% (S\$)	784.21
Nett Amount (S\$)	11,987.21

This claim is handled by: NG KENG GUAN

Steve (LKR)

Generated using Morimen e-Claims Internet Estimation & Adjusting System

6/1/20, 12:30pm
OD - Not Adjusted (Rev 1)

Excess - \$500

L/S

Ry AL sy

10 days

Automotive Repair Centre Pte Ltd (Co.Reg.No:201312913C)

38 Woodlands Industrial Park E1, #05-18

Singapore 757700

Tel: 64688834 Fax: 64622278 Email: raymond@automotiverepaircentre.com.sg

(SUPPLEMENTARY)

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNPV2019-00008656	Date of Loss:	30/12/2019
Vehicle Reg. No.:	SKA6580S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ADNAN MOHD ALI		
Make/Model:	HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)	Vehicle Reg. Date:	20/11/2008
Vehicle Colour:	RED		
Engine No:	L15A71000885	Chassis No:	JHMGE88509S200779
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	3,615.00
Miscellaneous Items	0.00
Labour	420.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,035.00
+ GST 7.00% (S\$)	282.45
Nett Amount (S\$)	4,317.45
+ Previous Estimates (S\$)	11,987.21

Claim Total (S\$)**16,304.66***Generated using Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2020)**Parts:** 144 HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Automotive Repair Centre Pte Ltd/SKA6580S/25/02/2020 17:28**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CHARGING ALTERNATOR / DT	0.00	0.00	*580.00 F
2	1		*ECU CONTROLLER / DT	0.00	0.00	*1,280.00 F
* 3	1		*ECU CONTROLLER BRACKET / DT	0.00	0.00	*40.00 F
4	1		*BATTERY BASE TRAY / DT	0.00	0.00	*60.00 F
5	1		*BATTERY BRACKET / DT	0.00	0.00	*25.00 F
6	1		*BATTERY SETTING / DT	0.00	0.00	*20.00 F
7	1		*CRANKSHAFT PULLEY / DT	0.00	0.00	*120.00 F
8	1		*CRANK SENSOR COVER / DT	0.00	0.00	*70.00 F
9	1		*AUTO TENSIONER ASSY / DT	0.00	0.00	*140.00 F
10	1		*AIR FILTER ASSY / DT	0.00	0.00	*60.00 F
* 11	1		*DRIVESHAFT LH X NIN	0.00	0.00	*680.00 F
* 12	1		*STABILISER LINKAGE LH X NIN	0.00	0.00	*80.00 F
* 13	1		*STARTER MOTOR ASSY X NIN	0.00	0.00	*280.00 F
14	1		*WATER PUMP PIPE / DT	0.00	0.00	*80.00 F
* 15	1		*AIR CON CONTROL GARNISH X NIN	0.00	0.00	*100.00 F
Total Parts (S\$)						3,615.00

F=Franchise part.

Automotive Repair Centre Pte Ltd/SKA6580S/25/02/2020 17:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE AND REFIT FRONT FRAME WITH BOTH FRONT UNDERCARRIAGE	New 200 / 300	350.00
2	COMPUTERIZED WHEEL ALIGNMENT	New 60 /	70.00
Gross Labour Cost (S\$)			420.00

Automotive Repair Centre Pte Ltd/SKA6580S/25/02/2020 17:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2020)
 Parts: 144 HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue Menmen Singapore 1.0)
 Labour: Repairer's (Price-dehominated Standard List)
 Print Code: Automotive Repair Centre Pte Ltd/5KA6580S/03/01/2020 17:38
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / OR	0.00	0.00	*160.00 F
2	1		*FRONT BUMPER CLIPS X 10 / MC	0.00	0.00	*10.00 F
3	1		*FRONT BUMPER LOWER RUBBER LID / MIS	0.00	0.00	*40.00 F
4	1		*FRONT REINFORCEMENT / DD	0.00	0.00	*75.00 F
5	1		*FRONT BUMPER RETAINER RH / OR	0.00	0.00	*7.00 F
6	1		*FRONT BUMPER RETAINER LH / OR	0.00	0.00	*7.00 F
7	1		*FRONT BUMPER LOWER GRILLE / OR	0.00	0.00	*55.00 F
8	1		*FRONT GRILLE (CENTRE) / MIS	0.00	0.00	*60.00 F
9	1		*FRONT GRILLE CLIPS X 10 / MC	0.00	0.00	*10.00 F
10	1		*FRONT EMBLEM / MIS	0.00	0.00	*15.00 F
11	1		*FRONT BUMPER TOWING COVER / MIS	0.00	0.00	*10.00 F
12	1		*HEAD LAMP RH / OR	0.00	0.00	*320.00 F
13	1		*HEAD LAMP LH / OR	0.00	0.00	*320.00 F
14	1		*HEAD LAMP BRACKET RH / OR	0.00	0.00	*14.00 F
15	1		*HEAD LAMP BRACKET LH / OR	0.00	0.00	*14.00 F
16	1		*FRONT BONNET / DD	0.00	0.00	*200.00 F
17	1		*FRONT BONNET SEAL RH / MIS	0.00	0.00	*6.00 F
18	1		*FRONT BONNET SEAL LH / MIS	0.00	0.00	*6.00 F
19	1		*FRONT BONNET LOCK / OT	0.00	0.00	*65.00 F
20	1		*FRONT BONNET HINGE RH / OT	0.00	0.00	*16.00 F
21	1		*FRONT BONNET HINGE LH / OT	0.00	0.00	*16.00 F
22	1		*FRONT BONNET INSULATOR CLIPS X 4 / MC	0.00	0.00	*8.00 F
23	1		*FRONT UNDERCARRIAGE COVER RH	0.00	0.00	*20.00 F
24	1		*FRONT UNDERCARRIAGE COVER LH	0.00	0.00	*20.00 F
25	1		*FRONT UNDERCARRIAGE COVER CLIPS X 12	0.00	0.00	*12.00 F
26	1		*FRONT FENDER RH / DD	0.00	0.00	*95.00 F
27	1		*FRONT FENDER LH / DD	0.00	0.00	*95.00 F
28	1		*FRONT FENDER SHIELD RH / OR	0.00	0.00	*25.00 F
29	1		*FRONT FENDER SHIELD LH / OR	0.00	0.00	*25.00 F
30	1		*FRONT FENDER CLIPS RH X 9 / MC	0.00	0.00	*9.00 F
31	1		*FRONT FENDER CLIPS LH X 9 / MC	0.00	0.00	*9.00 F
32	1		*FRONT FENDER CLIPS RH (SQUARE CLIPS) X 3 / MC	0.00	0.00	*6.00 F
33	1		*FRONT FENDER CLIPS LH (SQUARE CLIPS) X 3 / MC	0.00	0.00	*6.00 F
34	1		*WASHER TANK / CRU	0.00	0.00	*25.00 F
35	1		*WASHER TANK FILTER NECK / CRU	0.00	0.00	*10.00 F
36	1		*WASHER TANK PUMP	0.00	0.00	*30.00 F
37	1		*FRONT HORN SET / OR	0.00	0.00	*25.00 F
38	1		*AIR FILTER BOX LOWER	0.00	0.00	*60.00 F
39	1		*AIR FILTER BOX COVER / OR	0.00	0.00	*45.00 F
40	1		*AIR INTAKE DUCT	0.00	0.00	*18.00 F
41	1		*FRONT SUPPORT PANEL / DD	0.00	0.00	*130.00 F
42	1		*RADIATOR / DD	0.00	0.00	*230.00 F
43	1		*RADIATOR SHROUD	0.00	0.00	*45.00 F
44	1		*RADIATOR FAN BLADE	0.00	0.00	*35.00 F
45	1		*RADIATOR FAN MOTOR	0.00	0.00	*160.00 F
46	1		*RADIATOR SPARE TANK	0.00	0.00	*20.00 F
47	1		*RADIATOR SPARE TANK CAP	0.00	0.00	*5.00 F

48	1	*RADIATOR UPPER HOSE / CK	0.00	0.00	*13.00 F
49	1	*RADIATOR LOWER HOSE ?	0.00	0.00	*12.00 F
50	1	*RADIATOR TOP BRACKET RH / GT	0.00	0.00	*10.00 F
51	1	*RADIATOR TOP BRACKET LH / GT	0.00	0.00	*10.00 F
52	1	*A/C CONDENSER / ED	0.00	0.00	*240.00 F
53	1	*A/C SHROUD ?	0.00	0.00	*48.00 F
54	1	*A/C FAN BLADE ?	0.00	0.00	*30.00 F
55	1	*A/C FAN MOTOR ?	0.00	0.00	*95.00 F
56	1	*A/C PIPE DISCHARGE HOSE ?	0.00	0.00	*80.00 F
57	1	*A/C OUTLET PIPE ?	0.00	0.00	*70.00 F
58	1	*A/C COMPRESSOR SUCTION HOSE ?	0.00	0.00	*80.00 F
59	1	*AIR FILTER TOP COVER REAR ?	0.00	0.00	*10.00 F
60	1	*ENGINE BRACKET FOR MOUNTING RH / OR	0.00	0.00	*40.00 F
61	1	*ENGINE BRACKET FOR MOUNTING LH / ?	0.00	0.00	*40.00 F
62	1	*ENGINE MOUNTING RH / OR	0.00	0.00	*75.00 F
63	1	*ENGINE MOUNTING LH / ?	0.00	0.00	*75.00 F
64	1	*ENGINE MOUNTING REAR ?	0.00	0.00	*70.00 F
65	1	*FRONT ABS SENSOR RH X	0.00	0.00	*85.00 F
66	1	*FRONT ABS SENSOR LH X	0.00	0.00	*85.00 F
67	1	*FRONT CROSS MEMBER X	0.00	0.00	*280.00 F
68	1	*FRONT AIR BAG RH / OR	0.00	0.00	*450.00 F
69	1	*FRONT AIR BAG LH / OR	0.00	0.00	*450.00 F
70	1	*FRONT SEAT BELT RH / ?	0.00	0.00	*170.00 F
71	1	*FRONT SEAT BELT LH / ?	0.00	0.00	*170.00 F
72	1	*REEL CABLE FOR AIR BAG AT STEERING WHEEL / OR	0.00	0.00	*200.00 F
73	1	*SRS CONTROL UNIT / OR	0.00	0.00	*520.00 F
74	1	*FRONT BUMPER CRASH SENSOR RH / OR	0.00	0.00	*85.00 F
75	1	*FRONT BUMPER CRASH SENSOR LH / OR	0.00	0.00	*85.00 F
76	1	*FRONT WINDSCREEN / OR	0.00	0.00	*900.00 F
77	1	*FRONT WINDSCREEN MOULDING / OR	0.00	0.00	*50.00 F
78	1	*FRONT WINDSCREEN COWLING ASSY / OR	0.00	0.00	*220.00 F
79	1	*SIDE COWLING COVER RH / OR	0.00	0.00	*20.00 F
80	1	*SIDE COWLING COVER LH / OR	0.00	0.00	*20.00 F
81	1	*FRONT SIDE CORNER GLASS MOULDING RH / OR	0.00	0.00	*20.00 F
82	1	*FRONT SIDE CORNER GLASS MOULDING LH X	0.00	0.00	*20.00 F
83	1	*THROTTLE BODY ?	0.00	0.00	*250.00 F
84	1	*INTAKE MANIFOLD ASSY ?	0.00	0.00	*250.00 F
85	1	*FOG LAMP RH ?	0.00	0.00	*190.00 F
86	1	*FOG LAMP LH ?	0.00	0.00	*190.00 F
87	1	*FOG LAMP GARNISH RH / OR	0.00	0.00	*55.00 F
88	1	*FOG LAMP GARNISH LH / OR	0.00	0.00	*55.00 F

F=franchise part

Total Parts (\$\$)

8,412.00

Automotive Repair Centre Pte Ltd/SKA6580S/03/01/2020 17:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BATTERY / OR	120.00
2	1	COOLANT FLUID / MC	40.00
3	1	FRONT NUMBER PLATE WITH CASING / OR	35.00
4	1	SUPPLY OF IU BRACKET / MC	26.00
5	1	SUPPLY OF SEALANT (FRONT FENDER SIDE GLASS) / M	40.00
6	1	SUPPLY OF SEALANT (FRONT WINDSCREEN) / MC	40.00
Sub Total (S\$)			301.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Spraying painting Whole Front	New	1,000.00 900
2	Remove, Replace, Refit and Repair Accident Affected Area	New	1,000.00 900
3	Remove and Refit Engine and Transmission to Facilitate Repair	New	350.00 ?
4	Remove and Refit A/C Condenser, Radiator including A/C Gas	New	100.00 50
5	Remove and Replace Front Windscreen	New	120.00 /
6	Reset Fault Code and Sensors Replacement	New	150.00 120
7	Check and Rectify Electrical Wiring	New	20.00 /
8	Remove and Refit Dashboard to Facilitate Airbag Replacement	New	250.00 150
Gross Labour Cost (S\$)			2,990.00

Automotive Repair Centre Pte Ltd/SKA6580S/03/01/2020 17:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To spray damaged part(s) during resurvey
- Final prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2020 17:03	03 Jan 2020 17:38	03 Jan 2020 18:24	\$9,800.00	\$9,800.00		Pending for Survey Report
	Sendback Est	\$11,703.00	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	25 Feb 2020 17:12	25 Feb 2020 17:28	25 Feb 2020 17:28			(Combined)	Combined with Main
		\$4,035.00					Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	ADNAN MOHD ALI, ID: 58613762C		
Vehicle Reg. No.:	SKA6580S	Date of Loss:	30/12/2019 14:00 - :59 [133 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900042959	Policy/Cover Note No.:	PNPV2019-00008656 (Comprehensive) Coverage: 17/05/2019 - 17/05/2020
		Excess:	\$500.00
Repairer:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 14/01/2020]		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- FWD_SG (03/03/2020): Alert - Adj Mandate Approved (\$10100.00) - SKA6580S - Claim Handler: Eileen Bay
- FWD_SG (06/01/2020): Alert - Adj Mandate Approved (\$8750.00) - SKA6580S - Claim Handler: Eileen Bay

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKA6580S (1201900042959)
 OD
 Dec 30 2019 2:00PM
 [ADNAN MOHD ALI]
 Automotive Repair Centre Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)		Thumbnail	Print
1	03/01/20 17:38	Repairer Estimates	1	Load HTM	
2	25/02/20 17:28	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/01/20 17:22	Adjuster Immediate Advice	1	Load HTM	
2	27/02/20 12:12	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/01/20 18:11	General View	1	Load JPG	☒
2	06/01/20 18:11	General View	1	Load JPG	☒
3	06/01/20 18:11	General View	1	Load JPG	☒
4	06/01/20 18:11	General View	1	Load JPG	☒
5	06/01/20 18:11	General View	1	Load JPG	☒
6	06/01/20 18:11	General View	1	Load JPG	☒
7	06/01/20 18:11	General View	1	Load JPG	☒
8	06/01/20 18:11	General View	1	Load JPG	☒
9	06/01/20 18:11	General View	1	Load JPG	☒
10	06/01/20 18:11	General View	1	Load JPG	☒
11	06/01/20 18:11	General View	1	Load JPG	☒
12	06/01/20 18:11	General View	1	Load JPG	☒
13	06/01/20 18:11	General View	1	Load JPG	☒
14	06/01/20 18:11	General View	1	Load JPG	☒
15	06/01/20 18:11	General View	1	Load JPG	☒
16	06/01/20 18:11	General View	1	Load JPG	☒
17	06/01/20 18:11	General View	1	Load JPG	☒
18	06/01/20 18:11	General View	1	Load JPG	☒
19	06/01/20 18:11	General View	1	Load JPG	☒
20	06/01/20 18:11	General View	1	Load JPG	☒
21	06/01/20 18:11	General View	1	Load JPG	☒
22	06/01/20 18:11	General View	1	Load JPG	☒
23	06/01/20 18:11	General View	1	Load JPG	☒
24	06/01/20 18:11	General View	1	Load JPG	☒
25	06/01/20 18:11	General View	1	Load JPG	☒
26	06/01/20 18:11	General View	1	Load JPG	☒
27	06/01/20 18:11	General View	1	Load JPG	☒
28	06/01/20 18:11	General View	1	Load JPG	☒
29	06/01/20 18:11	General View	1	Load JPG	☒
30	06/01/20 18:11	General View	1	Load JPG	☒
31	06/01/20 18:11	General View	1	Load JPG	☒
32	06/01/20 18:11	General View	1	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)	Thumbnail	Print
33	06/01/20 18:11	General View	 Load JPG	☒
34	06/01/20 18:11	General View	 Load JPG	☒
35	06/01/20 18:11	General View	 Load JPG	☒
36	06/01/20 18:11	General View	 Load JPG	☒
37	06/01/20 18:11	General View	 Load JPG	☒
38	06/01/20 18:11	General View	 Load JPG	☒
39	06/01/20 18:11	General View	 Load JPG	☒
40	06/01/20 18:11	General View	 Load JPG	☒
41	06/01/20 18:11	General View	 Load JPG	☒
42	06/01/20 18:11	General View	 Load JPG	☒
43	06/01/20 18:11	General View	 Load JPG	☒
44	06/01/20 18:11	General View	 Load JPG	☒
45	06/01/20 18:11	General View	 Load JPG	☒
46	06/01/20 18:11	General View	 Load JPG	☒
47	06/01/20 18:11	General View	 Load JPG	☒
48	06/01/20 18:11	General View	 Load JPG	☒
49	06/01/20 18:11	General View	 Load JPG	☒
50	06/01/20 18:11	General View	 Load JPG	☒
51	06/01/20 18:11	General View	 Load JPG	☒
52	06/01/20 18:11	General View	 Load JPG	☒
53	06/01/20 18:11	Odometer Reading	 Load JPG	☒
54	06/01/20 18:11	General View	 Load JPG	☒
55	06/01/20 18:11	General View	 Load JPG	☒
56	06/01/20 18:11	Chassis Number	 Load JPG	☒
57	06/01/20 18:11	General View	 Load JPG	☒
58	06/01/20 18:11	General View	 Load JPG	☒
59	06/01/20 18:11	General View	 Load JPG	☒
60	06/01/20 18:11	General View	 Load JPG	☒
61	06/01/20 18:11	General View	 Load JPG	☒
62	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
63	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
64	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
65	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
66	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
67	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
68	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
69	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
70	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
71	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
72	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
73	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
74	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
75	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
76	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
77	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
78	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
79	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
80	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
81	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
82	27/02/20 13:19	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)	Thumbnail	Print
83	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
84	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
85	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
86	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
87	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
88	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
89	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
90	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
91	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
92	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
93	27/02/20 13:19	Reinspection Photo	 Load JPG	☒
94	11/03/20 13:29	After Repair Photo	 Load JPG	☒
95	11/03/20 13:29	After Repair Photo	 Load JPG	☒
96	11/03/20 13:29	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/01/20 14:27	ESTIMATE	 Load PDF	
2	06/01/20 14:27	SG CAR MART	 Load JPG	☒
3	06/01/20 15:24	Log card (if available)	 Load JPG	☒
4	07/01/20 10:24	lump sum letter	 Load JPG	☒
5	28/02/20 14:56	ESTIMATE AND SUPPLEMENTARY	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD20000232/ETF3E2

Date: 11/03/2020

REFERENCE

Insured/Claimant: ADNAN MOHD ALI Policy No: PNPV2019-00008656
Date of Loss: 30/12/2019 Nature of Claim: OD Claim No: 1201900042959

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA6580S**
Make & Model: HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) Engine No: L15A71000885
Reg. Date: 20/11/2008 (Man. Year: 2008) Chassis No: JHMGE88509S200779
Colour: Red Odometer: 250570 km
Engine Capacity: 1497 cc
Market Value/New Car Price: S\$23,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm
Front Right Side: Kumho 5 mm Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,027.00	9,535.00	2,492.00	20.72
Miscellaneous Items	301.00	301.00	0.00	0.00
Labour	3,410.00	2,770.00	640.00	18.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,738.00	12,606.00	3,132.00	19.90
Approved Total (Overridden) (S\$)		9,800.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	15,238.00	9,300.00	5,938.00	38.97
+ GST 7.00/7.00% (S\$)	1,066.66	651.00	415.66	38.97
Nett Amount (S\$)	16,304.66	9,951.00	6,353.66	38.97

INSPECTION

Date of Assignment: 03/01/2020 Present Location:
Date Inspected: 06/01/2020 Inspected At:

Automotive Repair Centre Pte Ltd (HQ)
Automotive Repair Centre Pte Ltd (HQ)
38 Woodlands Industrial Park E1, #05-18
Singapore 757700

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2020)
Parts:	144	HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA6580S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	160.00 F	*160.00 F
2	1		*FRONT BUMPER CLIPS X 10	Necessary	10.00 F	*10.00 F
3	1		*FRONT BUMPER LOWER RUBBER LID	Missing	40.00 F	*40.00 F
4	1		*FRONT REINFORCEMENT	Dented	75.00 F	*75.00 F
5	1		*FRONT BUMPER RETAINER RH	Broken	7.00 F	*7.00 F
6	1		*FRONT BUMPER RETAINER LH	Broken	7.00 F	*7.00 F
7	1		*FRONT BUMPER LOWER GRILLE	Broken	55.00 F	*55.00 F
8	1		*FRONT GRILLE (CENTRE)	Missing	60.00 F	*60.00 F
9	1		*FRONT GRILLE CLIPS X 10	Necessary	10.00 F	*10.00 F
10	1		*FRONT EMBLEM	Missing	15.00 F	*15.00 F
11	1		*FRONT BUMPER TOWING COVER	Missing	10.00 F	*10.00 F
12	1		*HEAD LAMP RH	Broken	320.00 F	*320.00 F
13	1		*HEAD LAMP LH	Broken	320.00 F	*320.00 F
14	1		*HEAD LAMP BRACKET RH	Broken	14.00 F	*14.00 F
15	1		*HEAD LAMP BRACKET LH	Broken	14.00 F	*14.00 F
16	1		*FRONT BONNET	Dented	200.00 F	*200.00 F
17	1		*FRONT BONNET SEAL RH	Missing	6.00 F	*6.00 F
18	1		*FRONT BONNET SEAL LH	Missing	6.00 F	*6.00 F
19	1		*FRONT BONNET LOCK	Bent	65.00 F	*65.00 F
20	1		*FRONT BONNET HINGE RH	Bent	16.00 F	*16.00 F
21	1		*FRONT BONNET HINGE LH	Bent	16.00 F	*16.00 F
22	1		*FRONT BONNET INSULATOR CLIPS X 4	Necessary	8.00 F	*8.00 F
23	1		*FRONT UNDERCARRIAGE COVER RH	Not Necessary	20.00 F	*- F
24	1		*FRONT UNDERCARRIAGE COVER LH	Not Necessary	20.00 F	*- F
25	1		*FRONT UNDERCARRIAGE COVER CLIPS X 12	Not Necessary	12.00 F	*- F
26	1		*FRONT FENDER RH	Dented	95.00 F	*95.00 F
27	1		*FRONT FENDER LH	Dented	95.00 F	*95.00 F
28	1		*FRONT FENDER SHIELD RH	Broken	25.00 F	*25.00 F
29	1		*FRONT FENDER SHIELD LH	Broken	25.00 F	*25.00 F
30	1		*FRONT FENDER CLIPS RH X 9	Necessary	9.00 F	*9.00 F
31	1		*FRONT FENDER CLIPS LH X 9	Necessary	9.00 F	*9.00 F
32	1		*FRONT FENDER CLIPS RH (SQUARE CLIPS) X 3	Necessary	6.00 F	*6.00 F
33	1		*FRONT FENDER CLIPS LH (SQUARE CLIPS) X 3	Necessary	6.00 F	*6.00 F
34	1		*WASHER TANK	Crushed	25.00 F	*25.00 F
35	1		*WASHER TANK FILTER NECK	Crushed	10.00 F	*10.00 F
36	1		*WASHER TANK PUMP	Not Necessary	30.00 F	*- F
37	1		*FRONT HORN SET	Broken	25.00 F	*25.00 F
38	1		*AIR FILTER BOX LOWER	Not Necessary	60.00 F	*- F
39	1		*AIR FILTER BOX COVER	Not Necessary	45.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*AIR INTAKE DUCT	Not Necessary	18.00 F	*- F
41	1		*FRONT SUPPORT PANEL	Dented	130.00 F	*130.00 F
42	1		*RADIATOR	Dented	230.00 F	*230.00 F
43	1		*RADIATOR SHROUD	Broken	45.00 F	*45.00 F
44	1		*RADIATOR FAN BLADE	Cut	35.00 F	*35.00 F
45	1		*RADIATOR FAN MOTOR	Jammed	160.00 F	*160.00 F
46	1		*RADIATOR SPARE TANK	Not Necessary	20.00 F	*- F
47	1		*RADIATOR SPARE TANK CAP	Not Necessary	5.00 F	*- F
48	1		*RADIATOR UPPER HOSE	Crushed	13.00 F	*13.00 F
49	1		*RADIATOR LOWER HOSE	Not Necessary	12.00 F	*- F
50	1		*RADIATOR TOP BRACKET RH	Bent	10.00 F	*10.00 F
51	1		*RADIATOR TOP BRACKET LH	Bent	10.00 F	*10.00 F
52	1		*A/C CONDENSER	Dented	240.00 F	*240.00 F
53	1		*A/C SHROUD	Broken	48.00 F	*48.00 F
54	1		*A/C FAN BLADE	Cut	30.00 F	*30.00 F
55	1		*A/C FAN MOTOR	Jammed	95.00 F	*95.00 F
56	1		*A/C PIPE DISCHARGE HOSE	Bent	80.00 F	*80.00 F
57	1		*A/C OUTLET PIPE	Bent	70.00 F	*70.00 F
58	1		*A/C COMPRESSOR SUCTION HOSE	Bent	80.00 F	*80.00 F
59	1		*AIR FILTER TOP COVER REAR	Not Necessary	10.00 F	*- F
60	1		*ENGINE BRACKET FOR MOUNTING RH	Broken	40.00 F	*40.00 F
61	1		*ENGINE BRACKET FOR MOUNTING LH	Bent	40.00 F	*40.00 F
62	1		*ENGINE MOUNTING RH	Broken	75.00 F	*75.00 F
63	1		*ENGINE MOUNTING LH	Torn	75.00 F	*75.00 F
64	1		*ENGINE MOUNTING REAR	Torn	70.00 F	*70.00 F
65	1		*FRONT ABS SENSOR RH	Not Necessary	85.00 F	*- F
66	1		*FRONT ABS SENSOR LH	Not Necessary	85.00 F	*- F
67	1		*FRONT CROSS MEMBER	Not Necessary	280.00 F	*- F
68	1		*FRONT AIR BAG RH	Broken	450.00 F	*450.00 F
69	1		*FRONT AIR BAG LH	Broken	450.00 F	*450.00 F
70	1		*FRONT SEAT BELT RH	Jammed	170.00 F	*170.00 F
71	1		*FRONT SEAT BELT LH	Jammed	170.00 F	*170.00 F
72	1		*REEL CABLE FOR AIR BAG AT STEERING WHEEL	Necessary	200.00 F	*200.00 F
73	1		*SRS CONTROL UNIT	Necessary	520.00 F	*520.00 F
74	1		*FRONT BUMPER CRASH SENSOR RH	Necessary	85.00 F	*85.00 F
75	1		*FRONT BUMPER CRASH SENSOR LH	Necessary	85.00 F	*85.00 F
76	1		*FRONT WINDSCREEN	Broken	900.00 F	*900.00 F
77	1		*FRONT WINDSCREEN MOULDING	Necessary	50.00 F	*50.00 F
78	1		*FRONT WINDSCREEN COWLING ASSY	Broken	220.00 F	*220.00 F
79	1		*SIDE COWLING COVER RH	Broken	20.00 F	*20.00 F
80	1		*SIDE COWLING COVER LH	Missing	20.00 F	*20.00 F
81	1		*FRONT SIDE CORNER GLASS MOULDING RH	Broken	20.00 F	*20.00 F
82	1		*FRONT SIDE CORNER GLASS MOULDING LH	Not Necessary	20.00 F	*- F
83	1		*THROTTLE BODY	Not Necessary	250.00 F	*- F
84	1		*INTAKE MANIFOLD ASSY	Cut	250.00 F	*250.00 F
85	1		*FOG LAMP RH	Not Necessary	190.00 F	*- F
86	1		*FOG LAMP LH	Not Necessary	190.00 F	*- F
87	1		*FOG LAMP GARNISH RH	Broken	55.00 F	*55.00 F
88	1		*FOG LAMP GARNISH LH	Broken	55.00 F	*55.00 F
Supplementary #1						
89	1		*CHARGING ALTERNATOR	Bent	580.00 F	*580.00 F
90	1		*ECU CONTROLLER	Necessary	1,280.00 F	*1,280.00 F
91	1		*ECU CONTROLLER BRACKET	Bent	40.00 F	*40.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
92	1		*BATTERY BASE TRAY	Bent	60.00 F	*60.00 F
93	1		*BATTERY BRACKET	Bent	25.00 F	*25.00 F
94	1		*BATTERY SETTING	Bent	20.00 F	*20.00 F
95	1		*CRANKSHAFT PULLEY	Bent	120.00 F	*120.00 F
96	1		*CRANK SENSOR COVER	Broken	70.00 F	*70.00 F
97	1		*AUTO TENSIONER ASSY	Jammed	140.00 F	*140.00 F
98	1		*AIR FILTER ASSY	Broken	60.00 F	*60.00 F
99	1		*DRIVESHAFT LH	Not Necessary	680.00 F	*- F
100	1		*STABILISER LINKAGE LH	Not Necessary	80.00 F	*- F
101	1		*STARTER MOTOR ASSY	Not Necessary	280.00 F	*- F
102	1		*WATER PUMP PIPE	Broken	80.00 F	*80.00 F
103	1		*AIR CON CONTROL GARNISH	Not Necessary	100.00 F	*- F
				Total Parts (\$\$)	12,027.00	9,535.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BATTERY (BROKEN)	120.00	120.00
2	1	COOLANT FLUID (NECESSARY)	40.00	40.00
3	1	FRONT NUMBER PLATE WITH CASING (BROKEN)	35.00	35.00
4	1	SUPPLY OF IU BRACKET (NECESSARY)	26.00	26.00
5	1	SUPPLY OF SEALANT (FRONT FENDER SIDE GLASS) (NECESSARY)	40.00	40.00
6	1	SUPPLY OF SEALANT (FRONT WINDSCREEN) (NECESSARY)	40.00	40.00
Sub Total (S\$)			301.00	301.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Spraying painting Whole Front	New	1,000.00	900.00
2	Remove, Replace, Refit and Repair Accident Affected Area	New	1,000.00	900.00
3	Remove and Refit Engine and Transmission to Facilitate Repair	New	350.00	250.00
4	Remove and Refit A/C Condenser, Radiator including A/C Gas	New	100.00	50.00
5	Remove and Replace Front Windscreen	New	120.00	120.00
6	Reset Fault Code and Sensors Replacement	New	150.00	120.00
7	Check and Rectify Electrical Wiring	New	20.00	20.00
8	Remove and Refit Dashboard to Facilitate Airbag Replacement	New	250.00	150.00
Supplementary #1				
Labour Items				
9	REMOVE AND REFIT FRONT FRAME WITH BOTH FRONT UNDERCARRIAGE	New	350.00	200.00
10	COMPUTERIZED WHEEL ALIGNMENT	New	70.00	60.00
Gross Labour Cost (S\$)			3,410.00	2,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >