



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel: 6702 4282 Fax: 6702 4202

TPA 16
 Justin

MHFZ28H3100076701

Vehicle No. SLU5118J TOYOTA SIENTA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT SIDE MIRROR COVER LH <i>could</i>		81.00	✓
1	FRONT SIDE MIRROR MOTOR LH ASSY <i>Dmgd.</i>		635.00	✓
1	FRONT DOOR LH <i>Repair</i>		1280.00	X
1	FRONT DOOR INNER TRIM BOARD ASSY LH <i>Not rec</i>		730.00	X
1	FRONT DOOR FRAME GARNISH LH		125.00	X
1	FRONT DOOR HINGE (UPPER) LH <i>new</i>		70.00	+
1	FRONT DOOR HINGE (LOWER) LH <i>new</i>		70.00	+
1	FRONT DOOR HANDLE LH <i>new</i>		250.00	X
1	FRONT DOOR LOCK		350.00	X
1	REAR DOOR LH <i>Repair</i>		1250.00	X
1	REAR DOOR INNER TRIM BOARD ASSY RH		680.00	X
1	REAR DOOR FRAME GARNISH RH		80.00	+
1	REAR POWER SLIDE DOOR SENSOR ASSY RH		400.00	+
1	REAR SLIDE DOOR OUTSIDE HANDLE RH		250.00	+
1	REAR SLIDE DOOR LOCK ASSY		550.00	+
1	REAR DOOR CONTROL SWITCH		110.00	+
1	REAR SLIDE DOOR PROTECT PLATE		40.00	+
1	REAR DOOR HINGE ASSY CENTRE RH		155.00	+
1	REAR QUARTER PANEL RH		780.00	X
1	REAR FENDER LH <i>Repair</i>		1151.00	X
1	REAR FENDER INNER SHIELD LH <i>Not rec</i>		269.50	X
1	REAR BUMPER <i>Debond</i>		1355.20	X
1	REAR BUMPER SIDE GARNISH RH <i>at</i>		160.80	+
2	REAR BUMPER SIDE RETAINER LH & RH <i>@\$85.40 LH Not rec</i>		170.80	+
1	REAR TAILLAMP LH <i>at</i>		657.20	X
1	REAR TAILLAMP PANEL LH <i>Not rec</i>		250.00	X
			11900.50	
		less 25%	2975.13	25%
			8925.38	
	SPECIAL NETT ITEMS			
1 SET	REAR BUMPER CLIPS <i>new</i>		100.00	30
1	REAR BODY SEALANT <i>new</i>		100.00	X
1 SET	REAR DOOR INNER TRIM BOARD CLIPS <i>Not rec</i>		80.00	X
1	REAR FENDER SELANT <i>Not rec</i>		120.00	X
	Total Parts		9325.38	

1191.20
 893.40

30



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

Vehicle No. SLU5118J TOYOTA SIENTA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	1000
3	To remove , fefix wiring system at accident damage areas and check for proper function	150.00	30
4	To remove rear bootlid mechanism	120.00	+
5	To perform anti-rust treatment on affected areas	150.00	50
6	Cavity treatment on New parts	120.00	X
7	To remove and refix fender upper glass	120.00	X
8	To remove and refix passenger seat	150.00	X
9	To conduct water seepage test	120.00	+
	Labour Total :	3730.00	
	TOTAL (PARTS & LABOUR):	13055.38	

1380

total: 2503.40
 1/s: 2K
 04 Days.

2K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: