

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WONG SHIAU TIM
 BLK 252 BANGKIT ROAD #08-390
 SINGAPORE 670252

TPM

Xiao Tony

ESTIMATE

Repair Code : CLM15906

Date in : 02/01/2020

Vehicle Num. : SKB8568K

Model : TOYOTA ESTIMA AERAS G-EDITION 2.4 A

Chassis/Eng# : ACR507090896/2AZF438565

Contact : 90452256, 98741185

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR CLENAER RESONATOR <i>cracked.</i>	1	185.00	✓ 185.00
FRONT BUMPER <i>Debond</i>	1	1731.35	866 1,731.35
FRONT BUMPER SIDE RETAINER L/R <i>LH Pong d</i>	2	172.50	116. 345.00
FRONT LH BUMPER FOGLAMP <i>cracked.</i>	1	371.70	✓ 371.70
FRONT LH BUMPER FOGLAMP BRACKET <i>cracked</i>	1	172.45	✓ 172.45
FRONT LH BUMPER FOGLAMP COVER <i>new</i>	1	172.50	X 172.50
FRONT LH DOOR <i>Dented</i>	1	1712.40	1481 1,712.40
FRONT LH DOOR FRAME UPPER STICKER (INNER)	1	181.90	60(SN) 181.90
FRONT LH DOOR FRAME UPPER STICKER (OUTER)	1	172.50	60(SN) 172.50
FRONT LH DOOR FRAME VERTICAL STICKER (INNER)	1	177.70	60(SN) 177.70
FRONT LH DOOR FRAME VERTICAL STICKER (OUTER)	1	177.70	60(SN) 177.70
FRONT LH DOOR INNER PLASTIC SEAL COVER <i>new</i>	1	72.10	X 72.10
FRONT LH DOOR PROTECTOR <i>Debond</i>	1	978.10	688 978.10
FRONT LH FENDER <i>Distorted</i>	1	981.70	782 981.70
FRONT LH FENDER INNER SEAL COVER <i>new</i>	1	174.45	X 174.45
FRONT LH FENDER INNER SHIELD <i>Debond</i>	1	371.70	✓ 371.70
FRONT LH FENDER PROTECTOR <i>cracked</i>	1	374.50	184 374.50
FRONT LH FENDER SIDE BRACKET <i>Bent</i>	1	171.50	95 171.50

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

WONG SHIAU TIM

BLK 252 BANGKIT ROAD #08-390

SINGAPORE 670252

Contact : 90452256, 98741185

ESTIMATE

Repair Code : CLM15906

Date in : 02/01/2020

Vehicle Num. : SKB8568K

Model : TOYOTA ESTIMA AERAS G-EDITION 2.4 A

Chassis/Eng# : ACR507090896/2AZF438565

FRONT LH HEADLAMP (HID) <i>cmhd</i>	1	2712.45	2190	2712.45
LH SLIDING DOOR PROTECTOR <i>del</i>	1	972.50	695	972.50
LH SLIDING DOOR RUBBER SEAL (FRONT) <i>xre m</i>	1	174.10	X	174.10
Subtotal before discount				12,383.30
Percentage discount 25%				3,095.83
Sub-total 1				9,287.48
FRONT BUMPER CLIPS - SET <i>Nu</i>	1	50.00	30	50.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>Nu m</i>	1	50.00	X	50.00
FRONT LH DOOR PROTECTOR CLIPS - SET <i>Nu</i>	1	80.00	20	80.00
FRONT LH FENDER INNER SEAL COVER CLIPS - SET <i>Nu m</i>	1	20.00	+	20.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>Nu</i>	1	50.00	30	50.00
FRONT LH FENDER PROTECTOR CLIPS - SET <i>Nu</i>	1	40.00	10	40.00
LH SLIDING DOOR PROTECTOR CLIPS - SET <i>Nu</i>	1	80.00	20	80.00
Subtotal before discount				370.00
Percentage discount 0%				0.00
Sub-total 2				370.00
Parts-total				9,657.48

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WONG SHIAU TIM
 BLK 252 BANGKIT ROAD #08-390
 SINGAPORE 670252

Contact : 90452256, 98741185

ESTIMATE

Repair Code : CLM15906
 Date in : 02/01/2020
 Vehicle Num. : SKB8568K
 Model : TOYOTA ESTIMA AERAS G-EDITION 2.4 A
 Chassis/Eng# : ACR507090896/2AZF438565

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)	30	50.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	80	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	700	1,000.00
To apply anti-rust chemical on repaired and replaced panel.	30	80.00
Labour Total		2,430.00
Parts & Labour Total		12,087.48

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 8138.38
 1/8: 6.5K
 06 Days
 6-5K