

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: SJP7805X191224

Estimate

Customer	Page 01 - 02
Name: AIG Asia Pacific Insurance Pte Ltd	Date: 04-01-20
Address: Motor Claims Department	Vehicle No: SJP7805X
78 Shenton Way #07-16	Model/Make: Kia Cerato Forte
AIG Building Singapore 079120	2.0 L SX A/T SR

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bootlid <i>Bent/Scr</i>	\$ 793.80	
2	Bootlid Inner Lock <i>twl</i>	\$ 91.60	
3	Bootlid Weatherstrip <i>twl</i>	\$ 128.50	
4	Bootlid Inner Trim <i>de/to.n</i>	\$ 211.20	
5	Bootlid Inner Trim 1 Set <i>11</i>	\$ 40.00	X
6	Bootlid "KIA" Motif <i>noc</i>	\$ 42.50	
7	Botlid "2.0" Emblem <i>rec</i>	\$ 45.00	
8	Botlid "Cerato" Emblem <i>rec</i>	\$ 43.20	
9	Botlid "Forte" Emblem <i>rec</i>	\$ 40.80	
10	Bumper <i>de</i>	\$ 658.00	
11	Bumper Lower Garnish <i>de/cne</i>	\$ 198.50	
12	Bumper Sponge <i>to.n</i>	\$ 145.50	
13	Bumper Reinforcement <i>cne</i>	\$ 356.00	
14	Bumper Reinforcement Bracket 02 pcs (@ S\$65.00) <i>N/Issy</i>	\$ 130.00	17C
15	Tail Lamp 02 pcs (@ S\$368.00) <i>su</i>	\$ 736.00	X
16	End Panel <i>scr/ty</i>	\$ 598.50	
17	End Panel Top Garnish <i>twl</i>	\$ 152.50	
18	Fender Inner Trim <i>de/to.n</i>	\$ 211.30	
19	Exhaust <i>n</i>	\$ 762.00	X
20	Front Bumper <i>de/to.n</i>	\$ 562.00	
21	Bumper Sponge <i>to.n</i>	\$ 123.60	
22	Bumper Reinforcement <i>scr</i>	\$ 396.50	
23	Bumper Lower Garnish <i>11</i>	\$ 450.00	X
24	Bumper Clips 1 set <i>rec</i>	\$ 50.00	
25	Bumper Licence Holder <i>to.n</i>	\$ 66.80	
26	Support Panel <i>scr</i>	\$ 671.00	X
27	Head Lamp 02 pcs (@ S\$546.00) <i>cne</i>	\$ 1,092.00	
28	Grille <i>cne</i>	\$ 285.30	
29	Grille "KIA" Motif <i>rec</i>	\$ 42.50	
30	Bonnet <i>n</i>	\$ 778.80	X
31	Rear Bumper Reverse Sensor <i>should</i>	\$ 280.00	SN 2005.~
32	End Panel Sealant <i>rec</i>	\$ 50.00	SN ✓ 5.~
33	front Number Plate	\$ 50.00	SN 155.~
C/F Balance ---->		\$ 10,283.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

6400.60

102
5760.54
6785.54
7028.43

not Authorized
LKK
6/1/20
L/S \$ 7000/
Sdy.

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com

Invoice/Ref No: SJP7805X191224

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Address Motor Claims Department

78 Shenton Way #07-16

AIG Building Singapore 079120

Page 02 - 02

Date: 04-01-20

Vehicle No: SJP7805X

Model/Make: Kia Cerato Forte
2.0 L SX A/T SR

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 10,283.40	
	To check all wiring & electrical component for proper function	\$ 80.00	- 30
	Remove and refix rear bumper reverse sensor	\$ 50.00	- ✓
	Remove and refix rear bootlid mechanism	\$ 80.00	- 60
	Remove & refix cushion upholstery to facilitate repair	\$ 80.00	- ✓
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 80.00	- X
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 100.00	- 11X
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	- 60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	- 1000
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,800.00	- 1480

Total Parts & Labour of estimate for damaged vehicle

\$ 13,833.40

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks