



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20000248/Bvf3e2

3 ANSON ROAD #28-01  
SPRINGLEAF TOWER SINGAPORE 079909

Date : 06-05-2020



Code : UOI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GY 5899B	<b>Veh. Inspected</b>	YP 3048M
<b>Policy No.</b>	DHOM11017167D1900	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	M11D09132001	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	FELIS	<b>Assign Date</b>	06/01/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HINO XZU710R	<b>c.c</b>	4009
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	JHHUCS3H10K017266	<b>Colour</b>	WHITE
<b>Odometer</b>	197362	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	7.0X16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	7.0X16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	7.0X16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	7.0X16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/01/2020	<b>Inspection Date</b>	06/01/2020
<b>Survey held at</b>	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **14 Working Days**