

ASS. REC. BY:

REF: CS / SMD 2 000025 / 1 Estⁿ²

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Graa Tio

of

SMD

Date/Time: 6. Jan. 20 11:30 AM

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 62555

Insured:

CB 701821

at Workshop m/s Automobile Repair

Tel:

of 36 Woodland Industrial Park E / #05-18

Policy No:

Claim No: (MTD) 7000068 / LOR

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3.1.2020

CA / REV / REP. / REV 24 HRS

Date/Time: 6.1.2020 11:50 AM

Person Contacted:

Siu Juan

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMD 62555 - X

CB 701821 - X


07/01/20

@ 16:43 pm revised RA to Lorraine via email

File No: Steve | SMD

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
UD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD62555 Yr Regn: 28/8/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Freed c.c. 1496
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 086946 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 6871068296
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/60R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Petlas

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 3/1/20 D.O.I. 6/1/20
 Survey held at Automotive Repair Centre

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV- 92K</u>
<u>23/1/20</u>	<u>Finalize \$8454.08, 6 days (km)</u>
	<u>(\$ 9,490.02 Red - 53%)</u>
	<u>30/1/2020</u>
	<u>RECEIVED 30 JAN 2020</u>

Date/Time, File Prep by?

30/01/20

by Typist

Date/Time, File Return to?

3

Report Format:

Final Sum \$ 8,454.08 plp

☐ : Prel. Report
☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Witnessing (\$)

Survey Fee:

Transportation:

S + RS \$

Parking

Other

450

Total



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000068/LOR

Date: 07 January 2020

Our Ref: CS/SMO20000251/Esf3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


PRELIMINARY ADVISE REPORT OF VEHICLE NO. SMD 6255S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/01/2020 at the premises of M/s Automotive Repair Centre Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 17,490.00
Revised Estimate Amount	: S\$ 8,520.00
"Check" Items Amount	: S\$ 7,350.00
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 6 days

Yours faithfully

Chen Tsue Yee
Automotive Assessor

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 6 January 2020 11:33 AM
To: raymond@automotiverepaircentre.com.sg; Wong, Lorriance; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: kenguan@automotiverepaircentre.com.sg; 'Lin Shu Juan'; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD2000068/LOR - LKK/ CB7018H & SMD6255S ACC ON 03.01.20 - VEH IN
Attachments: EST2001-001 SMD6255S.pdf; SAS2727999.PDF

Our Reference: CMTD2000068/LOR
Your Reference: SMD6255S

Without Prejudice
EMAIL ONLY

Date: 06/01/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S AUTOMOTIVE REPAIR CENTRE PTE LTD

Dear Raymond,

ACCIDENT INVOLVING CB7018H & SMD6255S ON 03.01.2020

We refer to your email reply of today.

We will appoint Mr. Kenneth Kong of LKK Auto to conduct the survey.

Hi LKK AUTO,

Please make the arrangement to survey for **SMD6255S** on a without prejudice basis and revert your report upon completion of survey to my colleague, **Ms. Lorriance**.

Thank you.

Please note our office will be closed on 24th January 2020 (Friday). Business will resume on 28th January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: raymond@automotiverepaircentre.com.sg <raymond@automotiverepaircentre.com.sg>

Sent: Monday, January 6, 2020 11:30 AM

To: Teo, Grace <grace.teo@sompo.com.sg>; Wong, Lorriance <lorriance.wong@sompo.com.sg>

Cc: kenguan@automotiverepaircentre.com.sg; 'Lin Shu Juan' <shujuan@automotiverepaircentre.com.sg>;

Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE: CMTD2000068/LOR - PRI(LIA)/ CB7018H & SMD6255S ACC ON 03.01.20

Dear Grace,

We shall select below surveyor:

2	LKK Auto Consultants	Kenneth Kong (North area)	
---	----------------------	---------------------------	--

Kindly arrange soonest possible.

Thank you.

Best Regards,

Raymond Tan

Automotive Repair Centre Pte Ltd

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: +65 64688834

Fax: +65 64622278

From: Teo, Grace <grace.teo@sompo.com.sg>

Sent: Monday, 6 January 2020 10:40 AM

To: raymond@automotiverepaircentre.com.sg; Wong, Lorriance <lorriance.wong@sompo.com.sg>

Cc: kenguan@automotiverepaircentre.com.sg; Lin Shu Juan <shujuan@automotiverepaircentre.com.sg>;

Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD2000068/LOR - PRI(LIA)/ CB7018H & SMD6255S ACC ON 03.01.20

Our Reference: CMTD2000068/LOR

Your Reference: SMD6255S

Without Prejudice

EMAIL ONLY

Date: 06/01/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S AUTOMOTIVE REPAIR CENTRE PTE LTD

Dear Raymond,

ACCIDENT INVOLVING CB7018H & SMD6255S ON 03.01.2020

We refer to your Notice of Accident dated 05/01/2020.

Please be informed that **Ms. Lorriance Wong** is the handler of this case who can be contacted at 63295 175/
lorriance.wong@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Aside to Lorriance,

Please assist on the liability request from Automotive Repair Centre Pte Ltd.

Please note our office will be closed on 24th January 2020 (Friday). Business will resume on 28th January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Raymond Tan <raymond@automotiverepaircentre.com.sg>

Sent: Sunday, January 5, 2020 8:28 PM

To: claimsreport <claimsreport@sompo.com.sg>; Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: kenguan@automotiverepaircentre.com.sg; Lin Shu Juan <shujuan@automotiverepaircentre.com.sg>

Subject: SMD6255S - TP Claim against CB7018H

Dear Claim Officer in-charge,

Our client's vehicle **SMD6255S** wants to make a third party claim against **CB7018H** which is insured by **Sompo Insurance Singapore Pte. Ltd.**

Attached are the accident report and estimate.

Kindly acknowledge claim officer in-charge as we would like to know the **liability details**.

***Vehicle SMD6255S currently at our workshop, survey to arrange soonest as possible.**

Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278

Steve Chen (LKK Auto)

From: ARC Ken <kenguan@automotiverepaircentre.com.sg>
Sent: Thursday, January 23, 2020 9:50 AM
To: Steve Chen (LKK Auto)
Cc: 'ARC Raymond'; 'ARC ShuJuan'
Subject: RE: SMD6255S - TP Claim against CB7018H (Sompo)

Dear Steve

Thank you for the call.

Confirm finalized at \$8,454.08 (P/P, before GST). 6 repair days.

With best regards,
Ken Ng

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Thursday, 23 January 2020 9:30 AM
To: kenguan@automotiverepaircentre.com.sg
Cc: 'ARC Raymond' <raymond@automotiverepaircentre.com.sg>; 'ARC ShuJuan' <shujuan@automotiverepaircentre.com.sg>
Subject: SMD6255S - TP Claim against CB7018H (Sompo)

Dear Ken,

As per our communicate earlier. Revise the finalize \$8,454.08 (P/P, before GST). 6 repair days.

Kindly confirm.

Thanks.

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ARC Ken [<mailto:kenguan@automotiverepaircentre.com.sg>]
Sent: Tuesday, January 21, 2020 11:06 AM
To: Steve Chen (LKK Auto)
Cc: 'ARC Raymond'; 'ARC ShuJuan'
Subject: RE: SMD6255S - TP Claim against CB7018H (Sompo)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 7 January 2020 4:43 pm
To: 'Wong, Lorriance'
Cc: SUR; assignments; 'Teo, Grace'; 'Ye, Yong Kang Melvin'; 'Henry, Irene James'
Subject: RE: CMTD2000068/LOR - LKK/ CB7018H & SMD6255S ACC ON 03.01.20 - VEH IN
Attachments: PRELI ADVISE - SMD 6255S.pdf

Dear Lorriance,

Enclosed preliminary revised of vehicle SMD 6255S.

"Wishing you a Happiness and Prosperity New Year"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 6 January 2020 11:55 am
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; SUR <sur@lkkauto.com>; 'Wong, Lorriance' <lorriance.wong@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: kenguan@automotiverepaircentre.com.sg; 'Lin Shu Juan' <shujuan@automotiverepaircentre.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>
Subject: RE: CMTD2000068/LOR - LKK/ CB7018H & SMD6255S ACC ON 03.01.20 - VEH IN

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	466J
Vehicle Details	
Vehicle No.:	SMD62555
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	LEB5601783
Chassis No.:	GB71068296
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$25,820.00
Original Registration Date:	28 Aug 2018
First Registration Date:	28 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$18,148.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2028
PARF Rebate Amount:	\$13,611.00
Intended COE Rebate Details	
COE Expiry Date:	27 Aug 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$33,420.00
COE Rebate Amount:	\$28,874.00
Total Rebate Amount:	\$42,485.00

The information contained herein is correct as at 06 Jan 2020

OK

ARC**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2001-001

DATE : 3-Jan-2020

POLICY NO. : PNCV2019-00001007

VEHICLE REG. NO. : SMD62555

VEHICLE MAKE : HONDA FREED HYBRID 1.5G AUTO

FOR SURVEYOR

TO Motor Claim Department

Sompo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06 Singapore Land Tower

Tel: 6221 2211, Fax: 6221 3147

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / <i>DR</i>	1	\$ 1,250.00	\$ 1,250.00
2	Rear Bumper Clips / <i>Mc</i>	10	\$ 6.00	\$ 60.00
3	Rear Bumper Upper Retainer RH / <i>DR</i>	1	\$ 30.00	\$ 30.00
4	Rear Bumper Upper Retainer LH / <i>DR</i>	1	\$ 30.00	\$ 30.00
5	Rear Bumper Lower Retainer RH / <i>CRU</i>	1	\$ 40.00	\$ 40.00
6	Rear Bumper Lower Retainer LH / <i>CRU</i>	1	\$ 40.00	\$ 40.00
7	Rear Bumper LH Bracket / <i>X NN</i>	1	\$ 40.00	\$ 40.00
8	Rear Bumper Tow Eye Cover / <i>CRU</i>	1	\$ 30.00	\$ 30.00
9	Rear Bumper Reflector RH / <i>X NN</i>	1	\$ 60.00	\$ 60.00
10	Rear Bumper Reflector LH / <i>X NN</i>	1	\$ 60.00	\$ 60.00
11	Rear Tail Lamp RH / <i>X NN</i>	1	\$ 600.00	\$ 600.00
12	Rear Tail Lamp LH / <i>X NN</i>	1	\$ 600.00	\$ 600.00
13	Rear Tailgate / <i>DR</i>	1	\$ 1,000.00	\$ 1,000.00
14	Rear Tailgate Rubber Seal / <i>TN</i>	1	\$ 120.00	\$ 120.00
15	Rear Tailgate Chrome Garnish / <i>DR</i>	1	\$ 240.00	\$ 240.00
16	Rear Tailgate License Plate Lamp / <i>X NN</i>	2	\$ 60.00	\$ 120.00
17	Rear Tailgate Lamp RH / <i>DR</i>	1	\$ 450.00	\$ 450.00
18	Rear Tailgate Lamp LH / <i>DR</i>	1	\$ 450.00	\$ 450.00
19	Rear Tailgate Honda Emblem / <i>Mc</i>	1	\$ 50.00	\$ 50.00
20	Rear Tailgate Freed Emblem / <i>Mc</i>	1	\$ 60.00	\$ 60.00
21	Rear Tailgate Hybrid Emblem / <i>Mc</i>	1	\$ 70.00	\$ 70.00
22	Rear Tailgate Lock Assy / <i>DT</i>	1	\$ 100.00	\$ 100.00
23	Rear Tailgate Lock Cover / <i>X NN</i>	1	\$ 40.00	\$ 40.00
24	Rear Tailgate Lock Latch / <i>X NN</i>	1	\$ 40.00	\$ 40.00
25	Rear Tailgate Absorber RH / <i>X NN</i>	1	\$ 150.00	\$ 150.00
26	Rear Tailgate Absorber LH / <i>X NN</i>	1	\$ 150.00	\$ 150.00
27	Rear Tailgate Cable / <i>X NN</i>	1	\$ 200.00	\$ 200.00
28	Rear Tailgate Inner Trim / <i>CRU</i>	1	\$ 300.00	\$ 300.00
29	Rear Tailgate Inner Trim RH Cover No. 4 / <i>X NN</i>	1	\$ 60.00	\$ 60.00
30	Rear Tailgate Inner Trim Bottom Cover No. 3 / <i>X NN</i>	1	\$ 30.00	\$ 30.00
31	Rear Tailgate Inner Trim LH Cover No. 2 / <i>X NN</i>	1	\$ 60.00	\$ 60.00
32	Rear Fender Inner Trim RH / <i>CRU</i>	1	\$ 500.00	\$ 500.00
33	Rear Fender Inner Trim LH / <i>CRU</i>	1	\$ 500.00	\$ 500.00

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2001-001

DATE : 3-Jan-2020

POLICY NO. : PNCV2019-00001007

VEHICLE REG. NO. : SMD62555

VEHICLE MAKE : HONDA FREED HYBRID 1.5G AUTO

FOR SURVEYOR

TO Motor Claim Department

Sompo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06 Singapore Land Tower

Tel: 6221 2211, Fax: 6221 3147

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
34	Rear / End Panel Side Garnish No. 6 <i>X NN</i>	1	\$ 80.00	\$ 80.00 <i>X</i>
35	Rear / End Panel Garnish Cover No. 7 <i>/ CRU</i>	1	\$ 150.00	\$ 150.00 <i>119 /</i>
36	End Panel <i>/ DO</i>	1	\$ 450.00	\$ 450.00 <i>/</i>
37	Rear Floor Panel Sink <i>X R</i>	1	\$ 1,000.00	\$ 1,000.00 <i>X</i>
38	Insulator Coat For Rear Floor Panel <i>X NN</i>	1	\$ 50.00	\$ 50.00 <i>X</i>
39	Rear Spare Tyre Board Cover <i>X NN</i>	1	\$ 650.00	\$ 650.00 <i>X</i>
40	Rear Exhaust Muffler <i>/ BT</i>	1	\$ 750.00	\$ 750.00 <i>661 /</i>
41	Rear Windscreen <i>/ OR</i>	1	\$ 1,250.00	\$ 1,250.00 <i>1055 /</i>
42	Rear Windscreen Moulding <i>/ MC</i>	1	\$ 100.00	\$ 100.00 <i>/</i>
43	Rear Windscreen Wiper Arm <i>/ CRU</i>	1	\$ 100.00	\$ 100.00 <i>/</i>
44	Rear Windscreen Wiper Motor <i>X NN</i>	1	\$ 550.00	\$ 550.00 <i>X</i>
45	Longitudinal Acceleration Sensor <i>X NN</i>	1	\$ 750.00	\$ 750.00 <i>X</i>
Total Spare Parts				\$ 13,410.00
SPECIAL NETT				
46	Rear Number Plate with Casing <i>/ CRU</i>	1	\$ 40.00	\$ 40.00 <i>/</i>
47	Rear Windscreen Sealant <i>/ MC</i>	1	\$ 40.00	\$ 40.00 <i>/</i>
48	Supply and Installation of Solar film <i>/ MC</i>	1	\$ 280.00	\$ 280.00 <i>150 /</i>
49	Reverse Sensor <i>/ SH (1 Set)</i>	2	\$ 200.00	\$ 400.00 <i>200 /</i>
Total Special Nett				\$ 760.00
LABOUR				
50	Spray painting Rear Bumper, Tailgate, Fenders & Inner Panels	1	\$ 1,000.00	\$ 800 1,000.00 <i>50</i>
51	Remove, Replace, Repair and Refit Affected Area	1	\$ 1,200.00	\$ 900 1,200.00 <i>120</i>
52	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00 <i>8 /</i>
53	Remove and Refit Rear Windscreen	1	\$ 150.00	\$ 150.00 <i>30</i>
54	Remove, Refit & Re-Align Rear Exhaust Pipe and Silencer	1	\$ 80.00	\$ 80.00 <i>7 X</i>
55	Remove and Refit Rear Reverse Sensor	2	\$ 80.00	\$ 160.00 <i>30</i>
56	Diagnose and Rectify Fault Code and Calibrate Sensors	1	\$ 500.00	\$ 500.00 <i>17984</i>
57	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00 <i>30</i>
58	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 <i>/</i>
Total Labour				\$ 3,320.00
Amount Before Excess				\$ 17,490.00
Add GST @ 7%				1,224.30
Total Amount Payable				\$ 18,714.30

LKK Auto Consultants Pte Ltd

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any

additional parts or labour which may be required after work has been started.

Occasionally, worn or damaged parts are discovered which may not be evident on

the first inspection. Because of this, the above price are not guaranteed.

Quotation on parts and labour are current and subject to change.

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Printed

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

TO Motor Claim Department

Sompo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06 Singapore Land Tower

Tel: 6221 2211, Fax: 6221 3147

Supplementary Estimate

ESTIMATE NO. : EST2001-001 (SUP)

DATE : 8-Jan-2020

POLICY NO. : PNCV2019-00001007

VEHICLE REG. NO. : SMD6255S

VEHICLE MAKE : HONDA FREED HYBRID 1.5G AUTO

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Tailgate Brake Light Top (Centre) / CRA A	1	\$ 180.00 220	\$ 180.00 220
2	Exhaust Bush / TN A	1	\$ 32.00	\$ 32.00
3	Rear Undercover / CRN A	1	\$ 180.00	\$ 180.00
4.	Exhaust Silencer heat shield \$62-10 / 00 A		Total Spare Parts	\$ 392.00
	<u>SPECIAL NETT</u>			
			Total Special Nett	\$ -
	<u>LABOUR</u>			
			Total Labour	\$ -
			Amount Before Excess	\$ 392.00
			Add GST @ 7%	27.44
			Total Amount Payable	\$ 419.44

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

494.10
-297.
395.28



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20000251/Esf3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 31-01-2020	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	CB 7018H	Veh. Inspected	SMD 6255S
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000068/LOR	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/01/2020
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GB71068296	Colour	WHITE
Odometer	86046	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	PETLAS	5 mm
L/H Front Tyre	195/60 R15	PETLAS	5 mm
R/H Rear Tyre	195/60 R15	PETLAS	5 mm
L/H Rear Tyre	195/60 R15	PETLAS	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/01/2020	Inspection Date	06/01/2020
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 6255S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED	1,250.00	925.00
10	REAR BUMPER CLIPS @\$6.00	NECESSARY	60.00	30.00
1	REAR BUMPER UPPER RETAINER RH	BROKEN	30.00	30.00
1	REAR BUMPER UPPER RETAINER LH	BROKEN	30.00	30.00
1	REAR BUMPER LOWER RETAINER RH	CRUSHED	40.00	40.00
1	REAR BUMPER LOWER RETAINER LH	CRUSHED	40.00	40.00
1	REAR BUMPER LH BRACKET	NOT NECESSARY	40.00	-
1	REAR BUMPER TOW EYE COVER	CRUSHED	30.00	30.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	60.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	60.00	-
1	REAR TAIL LAMP RH	NOT NECESSARY	600.00	-
1	REAR TAIL LAMP LH	NOT NECESSARY	600.00	-
1	REAR TAILGATE	DENTED	1,000.00	1,000.00
1	REAR TAILGATE RUBBER SEAL	TORN	120.00	120.00
1	REAR TAILGATE CHROME GARNISH	BROKEN	240.00	240.00
2	REAR TAILGATE LICENSE PLATE LAMP @\$60.00	NOT NECESSARY	120.00	-
1	REAR TAILGATE LAMP RH	BROKEN	450.00	450.00
1	REAR TAILGATE LAMP LH	BROKEN	450.00	450.00
1	REAR TAILGATE HONDA EMBLEM	NECESSARY	50.00	50.00
1	REAR TAILGATE FREED EMBLEM	NECESSARY	60.00	60.00
1	REAR TAILGATE HYBRID EMBLEM	NECESSARY	70.00	70.00
1	REAR TAILGATE LOCK ASSY	BENT	100.00	100.00
1	REAR TAILGATE LOCK COVER	NOT NECESSARY	40.00	-
1	REAR TAILGATE LOCK LATCH	NOT NECESSARY	40.00	-
1	REAR TAILGATE ABSORBER RH	NOT NECESSARY	150.00	-
1	REAR TAILGATE ABSORBER LH	NOT NECESSARY	150.00	-
1	REAR TAILGATE CABLE	NOT NECESSARY	200.00	-
1	REAR TAILGATE INNER TRIM	CRUSHED	300.00	300.00
1	REAR TAILGATE INNER TRIM RH COVER NO.4	NOT NECESSARY	60.00	-
1	REAR TAILGATE INNER TRIM BOTTOM COVER NO.3	NOT NECESSARY	30.00	-
1	REAR TAILGATE INNER TRIM LH COVER NO.2	NOT NECESSARY	60.00	-

Report Ref No. CS/SMO20000251/Esf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER TRIM RH	CRUSHED	500.00	268.00
1	REAR FENDER INNER TRIM LH	CRUSHED	500.00	268.00
1	REAR/END PANEL SIDE GARNISH NO.6	NOT NECESSARY	80.00	-
1	REAR/END PANEL GARNISH COVER NO.7	CRUSHED	150.00	119.00
1	END PANEL	DENTED	450.00	450.00
1	REAR FLOOR PANEL SINK	TO REPAIR SEE LABOUR	1,000.00	-
1	INSULATOR COAT FOR REAR FLOOR PANEL	NOT NECESSARY	50.00	-
1	REAR SPARE TYRE BOARD COVER	NOT NECESSARY	650.00	-
1	REAR EXHAUST MUFFLER	BENT	750.00	661.00
1	REAR WINDSCREEN	BROKEN	1,250.00	1,055.00
1	REAR WINDSCREEN MOULDING	NECESSARY	100.00	100.00
1	REAR WINDSCREEN WIPER ARM	CUT	100.00	100.00
1	REAR WINDSCREEN WIPER MOTOR	NOT NECESSARY	550.00	-
1	LONGITUDINAL ACCELERATION SENSOR	NOT NECESSARY	750.00	-
1	TAILGATE BRAKE LIGHT TOP (CENTRE)(ADDITIONAL)	CRACKED	220.00	220.00
1	EXHAUST BUSH (ADDITIONAL)	TORN	32.00	32.00
1	REAR UNDERCOVER (ADDITIONAL)	CRUSHED	180.00	180.00
1	EXHAUST SILENCER HEAT SHIELD (ADDITIONAL)	DENTED	62.10	62.10
	LESS 20% DISCOUNT		-	-1,496.02
			13,904.10	5,984.08
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE WITH CASING (SN)	CUT	40.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	SOLAR FILM (SN)	NECESSARY	280.00	150.00
2	SET REVERSE SENSOR @\$200.00 (SN)	SHORTED	400.00	200.00
			760.00	430.00
	LABOUR			
	SPRAY PAINTING REAR BUMPER, TAILGATE, FENDERS & INNER PANELS.		1,000.00	800.00
	REMOVE, REPLACE, REPAIR AND REFIT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL SINK.		1,200.00	900.00

Report Ref No. CS/SMO20000251/Esf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR.	NOT NECESSARY	100.00	50.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	REMOVE,REFIT & RE-ALIGN REAR EXHAUST PIPE AND SILENCER.		80.00	80.00
	REMOVE AND REFIT REAR REVERSE SENSOR.		160.00	30.00
	DIAGNOSE AND RECTIFY FAULT CODE AND CALIBRATE SENSORS.		500.00	-
	APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL.		100.00	30.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			3,320.00	2,040.00
GRAND TOTAL			17,984.10	8,454.08
RECOMMENDED COST OF REPAIRS				8,454.08

Report Ref No. CS/SMO20000251/Esf3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.