

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20000258/UGA3N2

Date: 19/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKT2192E	Insured Vehicle No :	SHA7593J
Date of Loss: 12/12/2019	Nature of Claim: TP	Claim No: MCT19120582

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT2192E	Engine No:	CAV424936
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WVWZZZ13ZDV000404
Reg. Date:	28/08/2012 (Man. Year: 2012)	Odometer:	133205 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/35R19	Rear Tyre Size:	235/35R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,592.00	1,658.70	4,933.30	74.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	860.00	2,270.00	72.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,722.00	2,518.70	7,203.30	74.09
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	9,722.00	2,000.00	7,722.00	79.43
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,229.00		
Global Sum Settlement (S\$)		2,200.00		

INSPECTION

Date of Assignment:	06/01/2020	
Date Inspected:	06/01/2020 Inspected At:	Nineteen Autowerks Pte Ltd (HQ) BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE Singapore 417808
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2020)	
Parts: 144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SKT2192E)		
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP -R/H	Not Necessary	952.00 FL	*- FL
2	1		*FRONT BUMPER	Torn	1,088.00 FL	*1,088.00 FL
3	1		*FRONT BUMPER FOG LAMP EXTERNAL COVERING	Not Necessary	175.00 FL	*- FL
4	1		*FRONT BUMPER INNER SPONGE	Not Necessary	210.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	554.00 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER	Bent	35.00 FL	*35.00 FL
7	1		*FRONT FENDER -R/H	Dented	670.00 FL	*670.00 FL
8	1		*FRONT FENDER INNER SHIELD	Not Necessary	189.00 FL	*- FL
9	1		*FRONT WHEEL HUB WITH BEARING	Not Necessary	520.00 FL	*- FL
10	1		*FRONT SHOCK ABSORBER	Not Necessary	450.00 FL	*- FL
11	1		*FRONT KNUCKLE ARM	Not Necessary	625.00 FL	*- FL
12	1		*FRONT LOWER ARM	Not Necessary	362.00 FL	*- FL
13	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
14	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	850.00 FS	*- FS
15	1		*FRONT TYRE (CUT)	Not Consistent With The Impact	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,175.00	1,838.00
- List Item Discount on L Items 10.00/10.00% (\$)	583.00	179.30
Total Parts (\$)	6,592.00	1,658.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	350.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
4	TO APPLY UNDERCOATING	New	150.00	30.00
5	PANEL BEATING	New	1,200.00	350.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	400.00
Gross Labour Cost (\$)			3,130.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >