

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Tel : 6341 6789 Fax: 6341 6778
E-mail: visionautowork@gmail.com

DATE : 13.01.20

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : SMM5359K
MODEL : HONDA SHUTTLE
DATE OF ACCIDENT : 02.01.20
TIME OF ACCIDENT : 15:45HRS

Khanchana.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>torn</i>	1	\$ 1,150.60	\$ 1,150.60
2	REAR BUMPER REFLECTOR LH <i>crushed</i>	1	\$ 43.80	\$ 43.80
3	REAR BUMPER REFLECTOR GARNISH LH <i>crushed</i>	1	\$ 45.10	\$ 45.10
4	REAR BUMPER SIDE INNER GARNISH <i>torn</i>	2	\$ 98.40	\$ 196.80
5	REAR BUMPER SIDE RETAINER LH <i>crushed</i>	2	\$ 26.50	\$ 53.00
6	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 24.00	\$ 48.00
7	REAR BUMPER SPONGE LH <i>crushed</i>	2	\$ 47.00	\$ 94.00
8	TAIL GATE EMBLEM SHUTTLE' <i>new</i>	1	\$ 55.70	\$ 55.70
9	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 168.10	\$ 168.10
10	TAIL LAMP LH <i>crushed</i>	1	\$ 520.50	\$ 520.50
11	TAIL LAMP LOWER PANEL LH <i>Repair</i>	1	\$ 235.20	\$ 235.20
12	REAR FENDER LH <i>Repair</i>	1	\$ 1,610.90	\$ 1,610.90
13	REAR FENDER COWLING LH <i>torn new</i>	1	\$ 147.50	\$ 147.50
14	REAR FENDER AIR VENT LH <i>new</i>	1	\$ 64.80	\$ 64.80
15	REAR QUATER GLASS C/W MOULDING LH <i>new</i>	1	\$ 720.40	\$ 720.40
16	REAR END PANEL <i>Dented</i>	1	\$ 685.10	\$ 685.10

276410.

221128

TOTAL PRICE \$ 5,839.50
LESS 20% \$ 1,167.90
SUB TOTAL PRICE \$ 4,671.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER REFLECTOR GARNISH CLIP LH (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	TAIL GATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
4	TAIL GATE LAMP LOWER PANEL LH <i>new</i>	1	\$ 80.00	\$ 80.00
5	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
6	TAIL LAMP LOWER PANEL SEALANT LH <i>new</i>	1	\$ 60.00	\$ 60.00
7	REAR FENDER SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SMM5359K
 MODEL : HONDA SHUTTLE

8	REAR FENDER INNER COWLING (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 30
9	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 +
10	REAR QUATER GLASS SEALANT LH <i>70</i>	1	\$ 60.00	\$ 60.00 +
11	REAR QUATER GLASS INNER SEAL LH <i>AP</i>	1	\$ 40.00	\$ 40.00 +
12	REAR QUATER GLASS SOLAR FILM LH <i>AP</i>	1	\$ 250.00	\$ 250.00 +
13	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00 60
14	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00 10
15	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00 +
			TOTAL	\$ 1,400.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	600
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
4	TRANSFER TAILGATE MECHANISM	\$ 80.00	x
5	REMOVE AND REFIX REAR FENDER GLASS LH	\$ 120.00	x
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 300.00	x

TOTAL 3380

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,071.60
 TOTAL LABOUR COST : \$ 3,380.00
 TOTAL REPAIR COST : \$ 9,451.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Admin LJ
H/s 14/01/20
04 Days

total: 3611.28

H/s: 2.8/c