

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1912-157

DATE : 26-Dec-2019

POLICY NO. : FWD PNPV2019-00003262

VEHICLE REG. NO. : SLX789P

VEHICLE MAKE : HONDA SHUTTLE HYBRID 1.5 A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 1,200.00	\$ 1,200.00
2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer LH	1	\$ 30.00	\$ 30.00
4	Front Bumper Retainer RH	1	\$ 30.00	\$ 30.00
5	Front Bumper Tow Eye Cover	1	\$ 20.00	\$ 20.00
6	Front Upper Grille Beam Bracket (Center) No. 4	1	\$ 60.00	\$ 60.00
7	Front Upper Grille (Center)	1	\$ 400.00	\$ 400.00
8	Front Upper Grille Chrome	1	\$ 380.00	\$ 380.00
9	Front Upper Grille Clips	6	\$ 5.00	\$ 30.00
10	Front Honda H Emblem with base	1	\$ 30.00	\$ 30.00
11	Front Head Lamp RH	1	\$ 2,200.00	\$ 2,200.00
12	Front Head Lamp LH	1	\$ 2,200.00	\$ 2,200.00
Total Spare Parts				\$ 6,630.00
	<u>SPECIAL NETT</u>			
13	Front License Plate with Frame	1	\$ 40.00	\$ 40.00
Total Special Nett				\$ 40.00
	<u>LABOUR</u>			
14	Spray Painting Front Bumper, Bonnet and Inner Panel	1	\$ 600.00	\$ 600.00
15	Replace Front Affected including Fitting, Cut, Weld and Re-align	1	\$ 600.00	\$ 600.00
16	Remove and Refit Front Bumper Parking Sensor	1	\$ 100.00	\$ 100.00
17	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,330.00
Amount Before Excess				\$ 8,000.00
Add GST @ 7%				560.00
Total Amount Payable				\$ 8,560.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.