

Date: 19.12.2019
Vehicle No: SLM381P
Model: TOYOTA AQUA HYBRID 1.5S
Chassis: NHP102538198 - 2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SKC5599K
Date of Accident: 16.12.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>~</i> \$608.31
2	REAR BUMPER CLIPS	8	\$5.50	<i>~</i> \$44.00
3	REAR BUMPER REINFORCEMENT			REPAIR
			SUB TOTAL	\$652.31
			LESS 25%	-\$163.08
			PARTS TOTAL	\$489.23

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC *~* \$250.00 X

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC \$250.00 *2000*

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC *~* \$80.00 X

LABOUR TOTAL \$580.00

ONG TOTAL \$1,069.23

*Not Authorised
Resurvey After Paint
1 day*