



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2003393
INV Date 23/04/2020
Reference CS/SMO20000281/R1td3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. GBF 2221K
Insured Veh. GBD 4813A
Claim No. CMTD190599/SYH
Policy No.
Accident Date 23/12/2019
Inspection Date 08/01/2020

Description	Total
Survey Inspection	350.00
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20000281/R1td3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 23-04-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 4813A	Veh. Inspected	GBF 2221K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD190599/SYH	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/01/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350 PANEL VAN 2.5	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JN1MC2E26Z0006906	Colour	GREY
Odometer	140908	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/12/2019	Inspection Date	08/01/2020
Survey held at	5 SOON LEE STREET #01-62		
Repairer	CHENG AUTO BODYWORKS		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 2221K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	2,038.25	2,038.25
1	TAILGATE RUBBER	NECESSARY	130.05	130.05
1	TAILGATE LOCK ASSY	SERVICEABLE	266.20	-
1	TAILGATE LOCK CATCH	SERVICEABLE	37.80	-
1	TAILGATE ABSORBER RH	SERVICEABLE	203.20	-
1	TAILGATE ABSORBER LH	SERVICEABLE	203.20	-
1	TAILGATE HINGE RH	SERVICEABLE	57.10	-
1	TAILGATE HINGE LH	SERVICEABLE	57.10	-
1	TAILGATE LOGO	NECESSARY	60.80	60.80
1	TAILGATE EMBLEM NV350	NECESSARY	103.30	103.30
1	TAILGATE INNER TRIM BOARD	SERVICEABLE	192.70	-
1	TAILLAMP RH	CRACKED	214.10	214.10
1	REAR BUMPER	DEFORMED	612.50	306.25
1	REAR BUMPER RETAINER RH	NECESSARY	17.40	17.40
1	REAR BUMPER RETAINER LH	SERVICEABLE	17.40	-
1	REAR FENDER PANEL RH	BUCKLED	1,829.20	1,829.20
1	REAR PETROL COVER RH	SERVICEABLE	96.90	-
1	REAR AIRDUCT RH	SERVICEABLE	59.40	-
1	REAR CABIN FLOOR PANEL	TO REPAIR SEE LABOUR	1,579.70	-
1	END PANEL INNER	BENT	187.20	187.20
1	END PANEL OUTER	BENT	155.45	155.45
	LESS 30% DISCOUNT		-2,435.69	-1,512.60
			5,683.26	3,529.40
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	50.00
1	REAR TAILGATE TRIM BOARD CLIPS (SN)	NECESSARY	100.00	50.00
1	REAR FENDER RH INNER SHIELD CLIPS (SN)	NECESSARY	100.00	50.00
1	END PANEL SEALANT (SN)	NECESSARY	100.00	60.00
1	REAR FENDER RH SEALANT (SN)	NECESSARY	100.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR PARKING SENSOR (SN)	NOT WORKING	250.00	200.00
			750.00	470.00
	LABOUR			
	LABOUR.INCLUSIVE OF THE REPAIR OF REAR CABIN FLOOR PANEL.		1,800.00	1,000.00
	SPRAYPAINTING.		1,600.00	700.00
	DISCONNECT & CHECK ELECTRICAL WIRING,HARNESS,WIRE SOCKETS,ETC,REMOVE & REINSTALL DAMAGED PARTS,TEST & RECTIFY FOR PROPER FUNCTIONING.		120.00	30.00
	REMOVE AND REINSTALL PETROL TANK TO FACILITATE REPAIR.		400.00	80.00
	REMOVE AND REINSTALL TAILGATE MECHANISM TO NEW.		200.00	80.00
	REMOVE AND REPLACE PARKING SENSOR AND TEST.		100.00	60.00
	REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING AND/OR UPHOLSTERY TO FACILITATE REAR FENDER REPAIRS.		400.00	100.00
			4,620.00	2,050.00
GRAND TOTAL			11,053.26	6,049.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CS/SMO20000281/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 2221K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

