

22/03/2002

ASS. REC. BY:

REF: CS/SMO20000281/RH23

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Gwee Teo

of

SMO

Date/Time: 6/1/2020 @ 2:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 2221 K

Insured:

GBD 4813A

at Workshop m/s

Cheng Auto bodyworks

Tel:

8666 7775

of

5 Soon Lee Street # 01-62

Policy No:

Claim No:

CM7D1905999 / SYH

Sum Insured:

Excess:

D.O.A.

23/12/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:12pm @ 6/1/2020

Person Contacted:

Mum

Vehicle IN / OUT

Date/Time	Action/Instruction
	Johny /
	GBD 4813A CA/GBE 16001515/020352 DOP: 22/01/2016
	GBF 2221K NAA/TMJ17022038/Y DOP: 17/11/2017

9/1 @ 4:31pm revised via preli advise. email

13/1 @ 2:49pm inform Shang Yi bumper will be payable Y2
base on the accident, workshop agree.

DATE: 27/12/2019

REPAIR DETAILS	
REFERENCE	
Vehicle Reg No.	: GBF2221K
Make & Model	: NISSAN / NV350 PANEL VAN 2.5 SAT SDR EURO V
Chassis No.	: JN1MC2E26Z0006906
Engine No.	: YD25402913A
Manufactured Year	: 2016
Labour	: REPAIRER'S
TP Vehicle Reg No.	: GBD4813A
DOA & Location	: 23/12/2019 BOON LAY AVENUE - CORPORATION RD JUNCTION
Our Ref	: GBF2221K / SOLE FITNESS

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	TAILGATE <i>bt</i>		\$ 2,038.25
2	1	TAILGATE RUBBER <i>new</i>		\$ 130.05
3	1	TAILGATE LOCK ASSY <i>X</i>		\$ 266.20
4	1	TAILGATE LOCK CATCH <i>X</i>		\$ 37.80
5	1	TAILGATE ABSORBER RH <i>X</i>		\$ 203.20
6	1	TAILGATE ABSORBER LH <i>X</i>		\$ 203.20
7	1	TAILGATE HINGE RH <i>X</i>		\$ 57.10
8	1	TAILGATE HINGE LH <i>X</i>		\$ 57.10
9	1	TAILGATE LOGO <i>new</i>		\$ 60.80
10	1	TAILGATE EMBLEM NV350 <i>new</i>		\$ 103.30
11	1	TAILGATE INNER TRIM BOARD <i>X</i>		\$ 192.70
12	1	TAILLAMP RH <i>cn</i>		\$ 214.10
13	1	REAR BUMPER <i>de</i>		\$ 612.50
14	1	REAR BUMPER RETAINER RH <i>na</i>		\$ 17.40
15	1	REAR BUMPER RETAINER LH <i>X</i>		\$ 17.40
16	1	REAR FENDER PANEL RH <i>buc</i>		\$ 1,829.20
17	1	REAR PETROL COVER RH <i>X</i>		\$ 96.90
18	1	REAR AIRDUCT RH <i>X</i>		\$ 59.40
19	1	REAR CABIN FLOOR PANEL <i>SA repair</i>		\$ 1,579.70
20	1	END PANEL INNER <i>SA</i>		\$ 187.20
21	1	END PANEL OUTER <i>bt</i>		\$ 155.45

Sub-Total (S\$) \$ 8,118.95

SAAA List Item Discount 30% (S\$) \$ 2,435.69

Sub-Total (S\$) \$ 5,683.27

* 306.25

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,800.00 <i>1000</i>
2	SPRAYPAINTING	\$ 1,600.00 <i>800 \$ 700</i>
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 120.00 <i>30</i>
4	REMOVE AND REINSTALL PETROL TANK TO FACILITATE REPAIR	\$ 400.00 <i>80</i>
5	REMOVE AND REINSTALL TAILGATE MECHANISM TO NEW	\$ 200.00 <i>80</i>
6	REMOVE AND REPLACE PARKING SENSOR AND TEST	\$ 100.00 <i>60</i>
7	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING AND/OR UPHOLSTERY TO FACILITATE REAR FENDER REPAIRS	\$ 400.00 <i>100</i>
Total Labour (S\$)		\$ 4,620.00

MISCELLANEOUS ITEMS

No.	Description	Price
1	REAR BUMPER CLIPS SET	\$ 100.00 <i>50</i>
2	REAR TAILGATE TRIM BOARD CLIPS	\$ 100.00 <i>50</i>
3	REAR FENDER RH INNER SHIELD CLIPS	\$ 100.00 <i>50</i>
4	END PANEL SEALANT	\$ 100.00 <i>60</i>
5	REAR FENDER RH SEALANT	\$ 100.00 <i>60</i>
6	REAR PARKING SENSOR SET	\$ 250.00 <i>200.00</i>
Total Miscellaneous Items (S\$)		\$ 750.00

Total Parts (S\$)	\$ 5,683.27
Total Labour (S\$)	\$ 4,620.00
Total Miscellaneous (S\$)	\$ 750.00
Total (S\$)	\$ 11,053.27
GST 7% (S\$)	\$ 773.73
Grand Total (S\$)	\$ 11,826.99

9/1/2020
Hp 90010068

8 days

4/5

08/01/2020 @1450

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurer

Acknowledged by Repairer
 Signature:
 Date: