

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9946G**AAD2001-011***Not Notified**21 Sep 812004*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

03 JAN 2020

SHB 9946G

VF1ABL15AUC273368

RENAULT

LATITUDE

31.12.19

CHINA TAIPING

16/9/2013

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>M</i> 561.70	✓
2	1	BUMPER LOWER REAR	\$	<i>not listed</i> 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10	}
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10	
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80	
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60	
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80	
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20	
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 16.60	
10	1	BUMPER BEAM REAR	\$	<i>M</i> 547.80	
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>M</i> 114.50	
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>M</i> 100.90	
13	1	BUMPER BLOCK RH REAR	\$	<i>M</i> 76.50	} X
14	1	BUMPER HARNESS REAR	\$	<i>SL</i> 301.10	
15	1	OUTER PANEL REAR (End Panel)	\$	<i>M</i> 745.80	
16	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>SL</i> 404.56	
17	1	TAILLAMP RH	\$	<i>SL</i> 313.10	
18	1	TAILLAMP PANEL RH	\$	<i>M</i> 401.40	
19	1	TAILLAMP LH	\$	<i>SL</i> 401.40	
20	1	TAILLAMP PANEL LH	\$	<i>M</i> 401.40	
21	1	BOOT REAR	\$	<i>M</i> 1,677.20	
22	1	BOOT FINISHER	\$	<i>SL</i> 344.70	}
23	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 178.20	
24	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70	
25	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 277.70	
26	1	BOOT BADGE 'RENAULT'	\$	<i>na</i> 82.40	
27	1	BOOT BADGE	\$	<i>na</i> 95.80	

Trans-cab Auto Services Pte Ltd**AAD2001-011**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9946G

28	1	BOOT STRUT LH	\$	Sn	145.10	}
29	1	BOOT STRUT RH	\$	Sn	145.10	
30	1	BOOT HINGE LH	\$	n	254.20	
31	1	BOOT HINGE RH	\$	n	253.80	
32	2	BOOT RUBBER PLUG	\$	Sn	139.90	
33	1	SPARE TYRE BOARD	\$	Sn	680.90	
34	1	BOOT LOCK LINKAGE	\$	Sn	20.60	
35	1	BOOT LOCK LINKAGE HOLDER	\$	Sn	99.50	
36	1	BOOT INNER TRIM BOARD	\$	Sn	611.00	
37	1	BOOT SWITCH	\$	Sn	113.00	
38	1	BOOT LOCK	\$	n	246.60	
39	1	BOOT LOCK CATCH	\$	n	41.70	
40	1	EXHAUST REAR	\$	n	5,263.60	}
41	1	EXHAUST CAP REAR	\$	n	125.40	
TOTAL			\$		16,264.36	
10%			\$		1,626.44	
			\$		14,637.92	

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	}
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
13	1	WINDSCREEN MOULDING	\$	na	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
15	1	BOOT INNER TRIM CLIP	\$	na	45.00	}
16	1SET	BOOT FINISHER CLIP	\$	na	24.20	

Trans-cab Auto Services Pte Ltd**AAD2001-011**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9946G

17	1	TAILLAMP CLIP LH	\$	5.00	} Bux
18	1	TAILLAMP CLIP RH	\$	5.00	
19	1	Rear Bumper Protector	\$	100.00	
20	1	EXHAUST MOUNTING REAR	\$	16.00	
21	1	REAR LICENCE PLATE WITH HOLDER	\$	80.00	
22	1	EXHAUST BRACKET REAR	\$	24.80	
TOTAL			\$	1,587.00	

TOTAL PARTS \$ 16,224.92**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	4 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9946G**AAD2001-011**

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	na	170.00	X
To check steering geometry and computer wheel alignment	\$	na	220.00	X
To reinstall rear bumper parking sensor.	\$		170.00	601
Putty and spray painting of the affected portion.	\$		7,500.00	2201
To repair and realign rear exhaust pipe.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$	na	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00	X
TOTAL	\$		17,680.00	
Over All Total	\$		33,904.92	

LUMP SUM (REPAIR DAY)**25 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: