

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 212P**AAD2001-002***Not Available**L/Up @ 3150/h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 212P

VF1ABL15AUC283196

RENAULT

LATITUDE

1.1.2020

CHINA TAIPING

31/8/2016

PART**LIST**

1	BUMPER COVER FRT	\$	CM	747.20	✓
1	BUMPER SPOILER FRT	\$	DI	344.70	✓
1	BUMPER ABSORBER FRT	\$	CM	394.68	✓
1	BUMPER RETAINER FRT LH	\$	DI	101.40	✓
1	BUMPER SUPPORT FRT	\$	CM	10.70	✓
1	BUMPER RETAINER FRT RH	\$	SL	101.40	X
1	BUMPER SUPPORT FRT	\$	SL	10.70	X
1	BUMPER UNDERTRAY FRT	\$	SL	292.50	✓
1	BUMPER GRILLE LOWER FRT	\$	SL	147.00	X
1	BUMPER FOG LAMP GRILLE LH	\$	DI	207.21	✓
1	BUMPER FOG LAMP GRILLE RH	\$	SL	207.21	X
1	BUMPER BEAM FRT	\$	R	663.70	✓
1	TOW COVER FRT	\$	SL	60.90	X
1	FRONT BRACE PANEL	\$	R	177.22	X
1	RADIATOR GRILLE	\$	SL	969.90	X
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL	225.36	X
1	RADIATOR GRILLE FRAME	\$	SL	686.00	X
1	FRAME FULL SUPPORT PANEL	\$	SL	592.70	X
1	FRAME FULL SUPPORT BRACKET	\$	R	41.60	X
1	HEADLAMP LH	\$	CM	743.60	✓
1	HEADLAMP RH	\$	SL	743.60	} X
1	HEADLAMP PANEL FRT LH	\$	R	127.70	
1	HEADLAMP PANEL FRT RH	\$	R	128.30	
2	HEADLAMP ADJUST MOTOR	\$	SL	313.90	
1	BONNET	\$	R	1,312.70	
1	BONNET INSULATOR	\$	SL	294.30	

Trans-cab Auto Services Pte Ltd**AAD2001-002**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 212P

1	BONNET STRUT LH	\$	S _L	53.30	}	X
1	BONNET STRUT RH	\$	S _R	53.30		
1	BONNET HINGE LH	\$	N	236.50		
1	BONNET HINGE RH	\$	N	237.40		
1	BONNET LOCK	\$	N	152.80		
1	BONNET CABLE	\$	S _L	55.20		
1	BONNET CABLE COVER	\$	S _L	80.60		
1	BONNET SEAL OUTER	\$	S _L	83.20		
1	BONNET SEAL INNER	\$	S _L	70.10		
1	FENDER PANEL FRT LH	\$	N	414.40		
1	WHEELARCH FRT LH	\$	S _L	112.30		
1	FENDER BRACKET LOWER LH	\$	S _L	11.80		
1	FENDER BRACKET FRT LH	\$	S _L	38.90		
1	FENDER INSULATOR LH	\$	S _L	65.50		
1	FENDER PANEL FRT RH	\$	N	437.10		
1	WHEELARCH FRT RH	\$	S _L	191.40		
1	FENDER BRACKET LOWER RH	\$	S _L	11.80		
1	FENDER BRACKET FRT RH	\$	S _L	106.40		
1	FENDER INSULATOR RH	\$	S _L	66.30	}	X
1	WIPER RESERVOIR	\$	S _L	179.60		
1	WIPER RESERVOIR NECK	\$	S _L	29.30		
1	WIPER RESERVOIR MOTOR	\$	S _L	82.60		
1	AIR CLEANER BOX	\$	S _L	464.20		
1	AIR CLEANER HOSE	\$	S _L	175.85		
1	AIR CLEANER LOWER	\$	CM	271.26		
1	AUTO COMPUTER	\$	S _L	1,287.30		
1	INJECTION COMPUTER	\$	S _L	2,706.30		
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S _L	3,765.30		
1	STEERING PUMP ELECTRIC L70Y	\$	S _L	2,026.70		
1	STEERING PINION RACK L70Y	\$	S _L	3,765.30		
1	SUBFRAME OUTER FRT	\$	S _L	1,094.20		
1	SUBFRAME BRACKET OUTER LH	\$	X	49.00		
1	SUBFRAME BRACKET OUTER RH	\$	N	49.00		
1	A/C CONDENSER	\$	S _L	1,537.80		

Trans-cab Auto Services Pte Ltd**AAD2001-002**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 212P

1	LOWER ARM LH L70Y	\$	<i>Sm</i> 192.70	} X
1	KNUCKLE ARM LH L70Y	\$	<i>Sm</i> 481.50	
1	ABSORBER FRT LH L70Y	\$	<i>Sm</i> 274.10	
1	DRIVESHAFT LH	\$	<i>Sm</i> 1,355.70	
1	STABILIZER BAR FRT	\$	<i>Sm</i> 427.90	

TOTAL	\$	32,340.09
10%	\$	3,234.01
	\$	29,106.08

Special Nett

1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>nn</i> 52.00	X
1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00	✓
1SET	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00	} X
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50	
1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i> 12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i> 10.50	
1	RADIATOR GRILLE SCREW	\$	<i>nn</i> 16.00	
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i> 70.00	
1SET	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i> 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i> 30.00	
1	FRONT RIGHT TYRE	\$	<i>Sm</i> 300.00	
1	FRONT RIGHT TYRE RIM	\$	<i>Sm</i> 380.00	} X
1	FRONT LEFT TYRE	\$	<i>Sm</i> 300.00	
1	FRONT LEFT TYRE RIM	\$	<i>Sm</i> 380.00	
1	Front licence plate with holder	\$	<i>Sm</i> 80.00	
1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i> 30.50	
1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 30.50	
6	BONNET INSULATOR CLIP L70Y	\$	<i>nn</i> 7.30	
2	BONNET CABLE COVER SCREW L70Y	\$	<i>nn</i> 10.85	
2	BONNET CABLE CLIP L70Y	\$	<i>nn</i> 6.31	

TOTAL	\$	1,893.47
TOTAL PARTS	\$	30,999.55

Trans-cab Auto Services Pte Ltd**AAD2001-002**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 212P**Labour**

To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X
To rust-proofing of the affected areas.	\$	<i>nn</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		7,500.00	<i>3001</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To Transfer Of Front Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>h</i>	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>h</i>	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>h</i>	170.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>h</i>	380.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>h</i>	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>h</i>	170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>h</i>	380.00	X

Trans-cab Auto Services Pte Ltd**AAD2001-002**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 212P

To remove and renew power steering pump, oil cooler
pipe and final checking and testing.

\$ *nn* 440.00 *X*

To check ABS and brake efficiency, final checking and
testing.

\$ *nn* 380.00 *X*

Putty and spray painting of the affected portion.

\$ 7,500.00 *4401*

To Check Electrical Lighting Concerned.

\$ 170.00 *201***TOTAL \$ 18,960.00****Over All Total \$ 49,959.55****(LUMP SUM) Repair Days*****25* DAYS***2 day,*