

ASS. REC. BY:

REF: CS/CTI 20000286 / My 327 Special Instruction:

Surveyor: HOCK AM ASSIGNMENT (Office)From (Person): Adeline Chng of CTI Date/Time: 6 Jan. 2020 3:15pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 7444K Insured: XD 76932at Workshop m/s Euro Surcs Tel: 982 89277of 1 Kali Bukit Ave 2 #102-03 AutobayPolicy No: _____ Claim No: SVM20D200050

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 3 Jan. 2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 6.1.2020 4.15pm Person Contacted: Ah Hunt H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 7444K - X
	XD 76932 - X
15/1	Simon said need Hock Am to check price (No sign).
¥	Finalised Amt 2/sep con \$19200 over 13 day (Red \$59816-31, 75%

H-ANN

CTI

ASSIGNMENT

From: _____ Date: 7/1/2020

Estimated Cost: _____

TP / RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 7494K

at Workshop no/s: Euro Success

of: 1 Kaki Bukit Ave 6 #02-03

Insured: Autobay

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLP 7494K Regn: 16/01/2019

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi E200 CC 1750

Colour: Black AC: Insured / Std / NI / NA

Sp Reading: 222 492 km T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: W002130042A091050

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 225/55/225

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear
R/Bal. <u>67</u> mm	<u>Kapsen</u>	R/Bal. <u>67</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>3/1/20</u>		D.O.I. <u>7/1/20</u>

Survey held at: Euro Success

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* SLP 7494K
	Do Insure by Police
	RECEIVED 05 MAR 2020
	* workshop pending given GIA report
	MV - 142000
	PV - 75215
	NV - 66700

Date/Time, File Pass to? : Prel. Report

: Final Report

6/3/20 Typist

Report Format: Emp 500 / 0.1 : \$19200/f

Days Of Repair: 13

Resurvey No. of Trip: 3

Survey Fee: 270

Transportation	
2-PS	
Notes	
Others	
TOTAL	<u>270</u>

Add Fee: Site Insp (f) Interview (f) Tech. Insp (f) Wheel track (f)

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Friday, 6 March, 2020 12:06 PM
To: Goh Wei Jie
Cc: Yvonne Wong (LKK Auto); Bryan Ang (LKKAuto)
Subject: RE: RE: SLP 7494K FINALIZED

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear wei jie ,

Good day, regarding your request for L/SUMP repair cost need \$ 19700 , that have try submit to insurance after other party insurance management did.t not approve this amount .

at last other party insurance management offer to your repair cost L/SUMP amount COR \$ 19200 and DOR 13 DAY.

Kindly to take noted, will be base finalized amount COR \$19200 and DOR 13 DAYS to close this case.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to china taiping insurance claim dept .

Thanks.

Best Regards,
Hock Ann| Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hock Ann (LKK Auto)
Sent: Monday, 3 February, 2020 5:53 PM
To: Goh Wei Jie
Cc: Yvonne Wong (LKK Auto)
Subject: RE: SLP 7494K FINALIZED

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear wei jie ,

Nivitha (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Monday, 6 January 2020 3:15 PM
To: assignments@lkkauto.com
Cc: ruby@htapartners.com.sg; Claims Dept of CTI; Tan Kah Leong; Alfred Toh
Subject: FW: OUR REF:SNM20D200050/XD7693Z/TKL & YOUR REF: TCL.GCN.RO.50012.20.ESS- REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLP 7494K

Without Prejudice

Dear LKK,

Please refer to the below email and liaise with third party workshop accordingly.

Thank you.

Adeline Chng

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Adeline Chng
Sent: Monday, 6 January 2020 2:52 PM
To: ruby@htapartners.com.sg
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: RE: OUR REF:SNM20D200050/XD7693Z/TKL & YOUR REF: TCL.GCN.RO.50012.20.ESS- REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLP 7494K

Without Prejudice

Dear Ruby,

We refer to your email dated on 06.01.2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN

XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Adeline Chng

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Claims Dept of CTI

Sent: Monday, 6 January 2020 2:38 PM

To: Adeline Chng <adeline.chng@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>;
ruby@htapartners.com.sg

Subject: OUR REF:SNM20D200050/XD7693Z/TKL & YOUR REF: TCL.GCN.RO.50012.20.ESS- REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLP 7494K

Importance: High

Dear Adeline,

Please conduct PRS-SLP7494K soonest possible on behalf of Kah Leong.

officer in charge –Tan Kah Leong –DID: 6389 6193

Dear Ruby,

***** kindly quote our reference number when replying*****

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6116

Fax: (65) 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: Monday, January 06, 2020 9:19 AM

To: Claims Dept of CTI

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLP 7494K [OUR REF. TCL.GCN.RO.50012.20.ESS]

Importance: High

Your ref : XD 7693Z

WITHOUT PREJUDICE

Our ref : TCL.GCN.ro.50012.20.ess

6 January 2020

China Taiping Insurance Co (Singapore) Pte Ltd

By Email Only

Motor Claims Department

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

VERY URGENT

Dear Sirs

CLAIMANT: AMV PTE LTD

NOTICE OF ACCIDENT & PRE-REPAIR SURVEY : ACCIDENT INVOLVING SLP 7494K & XD 7693Z ALONG PIE TUAS BEFORE CTE (SLE/TPE) EXIT ON 3 JANUARY 2020 @ 1415HRS

We are instructed by AMV Pte Ltd to notify you of a road traffic accident on 3 January 2020 at about 1415hrs along PIE Tuas before CTE (SLE/TPE) involving our clients' vehicle registration number SLP 7494K and vehicle registration number XD 7693Z driven by your authorised driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, our client proposes to appoint Marcus Chua of LKK Auto Consultants Pte Ltd as the single joint expert to carry out the pre-repair survey for SLP 7494K.

Kindly contact the person-in-charge to make the necessary arrangements for the pre-repair survey of our clients' vehicle. Please be informed that our clients' vehicle is at :

Venue : **EURO SUCCESS SERVICES PTE LTD**
1 Kaki Bukit Avenue 6
#02-03 Autobay
Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our clients' right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary

M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if/so/as.

ACCIDENT STATEMENT

Date Of Report	06/01/2020 18:47
Date Of Accident	03/01/2020 14:15
Exact Location Of Accident	PIE TUAS BEFORE CTE (SLE/TPE) EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP7494K
Insured/Policyholder	
Name Of Registered Owner	AMV PTE. LTD.
Co Reg No	2XXXXX825Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98583956

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E220 CDI
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5091973415-02
Cover Note Number	

Driver

Name of Driver	LOUIS KOK HOONG HUA
NRIC No	SXXXX431J
Date Of Birth	18/04/1966
Occupation	OUTDOOR
Date Of Driving Pass	04/02/2014
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96833229
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 448 BRIGHT HILL DRIVE #03-143
Postcode	570448
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN SEE LUN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD7693Z
Vehicle Make/Model/Colour	MITSUBISHI / FV51JJD4RDEA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereto consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

1. My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
2. all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
3. my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
4. my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
5. the information so collected under (1) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)

Reporting Centre
23 Kaki Bukit Ave 4
Singapore 415933
Name:
Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg

Accident Sketch Plan

SKETCH PLAN



A: SLP 7494K

B: XD7693Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above stated date and time, I was traveling
 along PIE TMS Before (LE (SLE / TPE) Exit. I was
 traveling straight when suddenly vehicle B collided onto
 my vehicle rear portion.

DECLARATION

I/We declare that the above particulars are true in every respect.

Policyholder's Name:
 Date & Time:

Driver's Signature
 (If driver is not the policy holder)
 Date & Time:

IDAC KAKI BUKIT (VAG)

23 Kaki Bukit Ave 4

Singapore 415933

Name: Tel: 67416697 Fax: 67492305

NRIC: Email: vockb@singnet.com.sg

Enquire Road Tax Expiry Date

Review Details

Vehicle No.
SLP7494K

Vehicle Make/Model
MERCEDES BENZ / E220 CDI

Road Tax Expiry Date :

15 Dec 2019 (Road tax has expired. It is an offence to use the vehicle on the roads without valid road tax.)

The information contained herein is correct as at 07 Jan 2020 / 10:43.

Save as PDF

OK →

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	825Z
Vehicle Details	
Vehicle No.:	SLP7494K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E220 CDI
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	65492080044043
Chassis No.:	WDD2130042A091050
Maximum Power Output:	143.0 kW (191 bhp)
Open Market Value:	\$50,465.00
Original Registration Date:	16 Jun 2017
First Registration Date:	16 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$47,837.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2027
PARF Rebate Amount:	\$35,877.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$39,338.00
Total Rebate Amount:	\$75,215.00

The information contained herein is correct as at 13 Jan 2020

OK

HOTTEST NEW CAR PROMOTIONS



Toyota Sienta Hybrid
Ready stock available with immediate COE registration. Call us now!!

DON'T MISS

Mercedes-Benz E220 Price Range Depreciation Year Reg Vehicle Type

Home » Used Cars » Shuang Hup Credit » Mercedes-Benz E-Class E220d SE Premium

Mercedes-Benz E-Class E220d SE Premium

Overview Financial Insurance Accessories Similar Research Photos Map



双合 (贷款) 私人有限公司
SHUANG HUP CREDIT PTE LTD



Price	\$159,800	Fuel Type	Diesel (Euro 5 Engine and Above)
Depreciation	\$17,580 /yr <small>View models with similar depre</small>	Reg Date	11-Aug-2017 <small>(7yrs 6mths 28days COE left)</small>
Mileage	60,000 km (24.7k /yr)	Manufactured	2017
Road Tax	\$1,834 /yr	Transmission	Auto
Dereg Value	\$80,583 as of today (change)	OMV	\$53,430
COE	\$53,711	ARF	\$53,174
Engine Cap	1,950 cc	Power	143.0 kW (191 bhp)
Curb Weight	1,700 kg	No. of Owners	1
Type of Vehicle	Luxury Sedan		



Shortlist Compare Add nc
Report Error More Actions

Features

Powerful 2.0L 4 Cylinder Inline Engine Producing 191Bhp, 400Nm Torque. 9G-Tronic Transmission, 0 To 100 Km/H In 7.3s. Rear Wheel Drive. View specs of the Mercedes-Benz E-Class Saloon Diesel (2016)

Accessories

Sports Rims, Multi Function Steering Wheel, Reverse Camera, Multi Zone Aircon, Auto Start-Stop Engine, Bluetooth, Cruise Control.

Description

1 Year Warranty. Panoramic Roof. Tip Top Condition. Vehicle In Showroom Condition. Elegant Grey With Light Grey Leather Interior. Bank/In House Loan Available. Lowest Interest Rate. Trade In Are Welcome. Call Our Friendly Sales Consultant For Discussion. Price Inclusive Of GST.

Category

PARF Car, Premium Ad Car

Status

Available

Resource

Compare - Free

Seller Information

Shuang Hup Credit

30 vehicles for sale. 31 sold in past 3 mths



31 West Coast Highway Lot 17/18

West Coast Car Mart

Tel: 67381118

Search cars nearby

Dolly Steve

81234847
98532668

DOA - 3/1/20
MV - 142000
PV - 75215
NV - 66700

Bank 7yr 5mths
mpn 16000 yr
16000 + 2 = 1333
112000 + 6665 + 23918
= 142583

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SLP7494K

Model: MERCEDES BENZ E220D

QTY	List Items	Price \$
1	REAR BOOT LID ✓ cut	2710.50
1	REAR BOOT EMBLEM E220D ✓ ne	110.80
1	REAR BOOT LID EMBLEM ✓ ne	138.00
1	REAR BOOT CHROME MOULDING ✓ mis	281.63
2	REAR BOOT LICENCE LAMP @68.55 ?	137.10
1	REAR BOOT INNER LOCK ✓	461.55
1	REAR BOOT OUTER LOCK X (svc)	430.00
1	REAR BOOT INNER TRIM ? ✓	281.60
1	REAR BOOT RUBBER ? ✓	125.50
1	REAR BOOT LOCK CATCH ?	61.50
1	REAR BOOT W/ STRIP ?	261.43
2 2	REAR BOOT HINGES L-R @181.5 X (R)	363.00
2 1	REAR BOOT HINGES COVERS L-R @58.5 4H? R/H X (svc)	117.00
2	REAR BOOT STOPPER @12.6 X (svc)	25.20
1	REAR BUMPER ✓ cut	1899.61
6 3 only	REAR BUMPER PDC SENSOR @313.75 ✓ slant	1882.50
2 1	REAR BUMPER REFLECTOR L-R @110.2 4H? R/H X (svc)	220.40
1	REAR BUMPER DIFUSSER ?	850.00
1	REAR BUMPER DIFUSSER CHROME MOULDING ?	350.00
2	REAR BUMPER LOWER BRACKET @45.5 ?	91.00
1	REAR BUMPER REINFORCEMENT ?	899.00
2 1	REAR BUMPER RETAINERS L-R @210 4H ✓ ORA R/H X (svc)	420.00
1	REAR BUMPER INNER TOP BRACKET ?	278.00
1	REAR BUMPER DIFFUSSER INNER GARNISH X (svc)	330.00
2	REAR BUMPER LOWER EXHAUST GARNISH L-R @150 X (svc)	300.00
1	REAR END PANEL ?	1450.00
1	REAR END PANEL INNER BOARD ?	730.00
40 15	REAR END PANEL DEBIT @5 ✓ ne	200.00
1	REAR SPARE TYRE PANEL X (R)	1850.00
1	REAR SPARE TYRE BOARD ?	698.00
1	REAR SPARE TYRE SPUNG X (svc)	599.90
1	REAR FLOOR BOARD X (svc)	581.90
2 1	REAR FENDER L-R @2000.5 4H of ✓ R/H X (R)	4001.00
2	REAR FENDER AIR BAG SENSOR L-R @ 1450 X (svc)	2900.00
2	REAR FENDER INNER TRIMS L-R @460.6 ?	921.20
2	REAR FENDER INNER PANEL L-R @950 X (R)	1900.00
2	REAR FENDER INNER TOP TRIM L-R @550.6 X (R)	1101.20
2	REAR TAIL LAMP L-R @1025 4H ✓ ORA R/H ?	2050.00
2	REAR TAIL LAMP BRACKET L-R @280 X (not use)	560.00
2	REAR TAIL LAMP COVERS L-R @55.6 X (not use)	111.20
10 6	REAR TAIL LAMP COVER CLIPS @4.50 ✓ ne	45.00
1	REAR KICK SENSOR X (svc)	321.60

1	REAR EXHAUST BOX	X (SVC)	2950.00
1	REAR EXHAUST INSULATOR	X (SVC)	1950.00
2	REAR EXHAUST CHROME PLATE L-R @345.5	X (SVC)	691.00
2	REAR DOOR L-R @2350	(R) X	4700.00
2	REAR DOOR RUBBER L-R @ 125	✓ CRG	250.00
1	REAR L/H DOOR INNER BOARD	?	1350.00
2	REAR DOOR 1/4 GLASS RUBBER L-R @145.5	X (SVC)	291.00
2	REAR DOOR INNER LOCK L-R @499.7	X (SVC)	999.40
2	REAR DOOR OUTER LOCK MOTOR L-R @550.60	X (SVC)	1101.20
1	REAR WIND SCREEN GLASS	✓ SUR	2450.00
1	REAR PASSENGER SEAT	X (R)	3500.60
2	REAR L/H PASSENGER SEAT BELT @750	✓ JM	1500.00
1	REAR SPEAKER INNER BOARD	X (SVC)	950.00
1	REAR PASSENGER SEAT BRACKET	X (SVC)	1250.00
1	FRONT DRIVER SEAT BELT	✓ JM	950.00
1	FRONT PASSENGER SEAT BLET	✓ JM	950.00
2	REAR LOWER ARM L-R @ 699.9		1399.80
2	REAR UPPER ARM L-R @ 750		1500.00
2	REAR KNUCKLE ARM L-R @1380		2760.00
2	REAR KNUCKLE ARM ABS SENSOR L-R @ 1400.7		2801.40
2	REAR KNUCKLE WHEEL BEARING L-R @ 600.97		1201.94
2	REAR SHOCK ABSORBER L-R @ 1300.72		2601.44
2	REAR CHASSIS MEMBER L-R @ 2450.90		4901.80

TOTAL \$76,045.90
 LESS 10% \$7,604.59
 TOTAL \$68,441.31

Social Nett Items

1	WINDSCREEN SEALANT	✓ JM	220.00	40
10	REAR BUMPER CLIPS @ 5.50	✓ JM	55.00	30
1	REAR NO. PLATE WITH HOLDER	✓ CRG	50.00	35
1	REAR SPARE TYRE	X (SVC)	750.00	

TOTAL \$1,075.00

Labour Charges

TOWING CHARGES	250.00	80
TO REMOVE, REPASTE PRIVATE HIRE STICKER FRONT & REAR	50.00	
TO CHECK FRONT & REAR ELECTRICAL WIRING	250.00	30
TO REMOVE, REFIX REAR WINDSCREEN	150.00	120
TO REMOVE, REFIX REAR SEAT, INTERIOR TRIMS TO ASSIST REPAIR	200.00	120
TO REMOVE, REFIX REAR UNDERCARRIAGE	650.00	
TO REMOVE REAR SEAT, ROOF AND FLOORBOARD TO ASSIST REPAIR	450.00	200
TO REPROGRAMME CAR ECU	600.00	280
TO RESPRAY UNDERCOATING	750.00	60
TO HAUL UP & REINSTALL ENGINE TO ASSIST REPAIR	650.00	
TO RESPRAY PAINTING AND ETC	2500.00	1800
PANEL BEATING, CUT, WELD REMOVE AND REPLACING ABOVE PARTS	3000.00	1800

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SLP7494K

Model: MERCEDES BENZ E220D

QTY	List Items	Price \$	
1	REAR BOOT LID ✓ cut	2710.50	2100.50 ✓
1	REAR BOOT EMBLEM E220D ✓ an	110.80	65.80 ✓
1	REAR BOOT LID EMBLEM ✓ an	138.00	60 ✓
1	REAR BOOT CHROME MOULDING ✓ an	281.63	145.30 ✓
2	REAR BOOT LICENCE LAMP @68.55 ✓ CRU	137.10	✓
1	REAR BOOT INNER LOCK ✓ JM	461.55	283 ✓
1	REAR BOOT OUTER LOCK ✓ X (SVC)	430.00	
1	REAR BOOT INNER TRIM ✓ CRU	281.60	230.80 ✓
1	REAR BOOT RUBBER ✓ CRU	125.50	✓
1	REAR BOOT LOCK CATCH X (R)	61.50	
1	REAR BOOT W/ STRIP X RPT	261.43	
2	REAR BOOT HINGES L-R @181.5 X (R)	363.00	
2	REAR BOOT HINGES COVERS L-R @58.5 ✓ X (SVC)	117.00	
2	REAR BOOT STOPPER @12.6 X (SVC)	25.20	
1	REAR BUMPER ✓ cut	1899.61	1600.50 ✓
6	REAR BUMPER PDC SENSOR @313.75 ✓ 36ms	1882.50	800 ✓
2	REAR BUMPER REFLECTOR L-R @110.2 ✓ CRU	220.40	80 ✓
1	REAR BUMPER DIFUSSER ✓ CRU	850.00	300 ✓
1	REAR BUMPER DIFUSSER CHROME MOULDING ✓ SKR 4H	350.00	100 ✓
2	REAR BUMPER LOWER BRACKET @45.5 ✓ CRU	91.00	✓
1	REAR BUMPER REINFORCEMENT ✓ BT	899.00	760 ✓
2	REAR BUMPER RETAINERS L-R @210 ✓ CRU	420.00	86 ✓
1	REAR BUMPER INNER TOP BRACKET ✓ CRU	278.00	110 ✓
1	REAR BUMPER DIFFUSSER INNER GARNISH X (SVC)	330.00	
2	REAR BUMPER LOWER EXHAUST GARNISH L-R @150 X (SVC)	300.00	
1	REAR END PANEL ✓ BT	1450.00	1060.00/1350 ✓
1	REAR END PANEL INNER BOARD ✓ CRU	730.00	420 ✓
40	REAR END PANEL DEBIT @5 ✓ CRU	200.00	45 ✓
1	REAR SPARE TYRE PANEL X (R)	1850.00	
1	REAR SPARE TYRE BOARD ✓ CRU	698.00	620 ✓
1	REAR SPARE TYRE SPUNG X (SVC)	599.90	
1	REAR FLOOR BOARD X (SVC)	581.90	
2	REAR FENDER L-R @2000.5 ✓ BT ✓ R/H X (R)	4001.00	1709.90 ✓
2	REAR FENDER AIR BAG SENSOR L-R @ 1450 X (SVC)	2900.00	
2	REAR FENDER INNER TRIMS L-R @460.6 ✓ 4H CRU ✓ R/H X (SVC)	921.20	393.30 ✓
2	REAR FENDER INNER PANEL L-R @950 X (R)	1900.00	
2	REAR FENDER INNER TOP TRIM L-R @550.6 X (R)	1101.20	
2	REAR TAIL LAMP L-R @1025 ✓ CRU ✓ R/H ✓ CRU	2050.00	1551.40 ✓
2	REAR TAIL LAMP BRACKET L-R @280 X (SVC) NS	560.00	
2	REAR TAIL LAMP COVERS L-R @55.6 X (SVC) NS	111.20	
10	REAR TAIL LAMP COVER CLIPS @4.50 ✓ CRU	45.00	24 ✓
1	REAR KICK SENSOR X (SVC)	321.60	

1	REAR EXHAUST BOX	X (SVC)	2950.00	
1	REAR EXHAUST INSULATOR	X (SVC)	1950.00	
2	REAR EXHAUST CHROME PLATE L-R @345.5	X (SVC)	691.00	
2	REAR DOOR L-R @2350	(R) X	4700.00	
2	REAR DOOR RUBBER L-R @ 125	✓ CRG	250.00	✓
1	REAR L/H DOOR INNER BOARD	✓ CRG 4/4	1350.00	850 ✓
2	REAR DOOR 1/4 GLASS RUBBER L-R @145.5	X (SVC)	291.00	
2	REAR DOOR INNER LOCK L-R @499.7	X (SVC)	999.40	
2	REAR DOOR OUTER LOCK MOTOR L-R @550.60	X (SVC)	1101.20	
1	REAR WIND SCREEN GLASS	✓ CRG	2450.00	1600 ✓
1	REAR PASSENGER SEAT	X (R)	3500.60	
2/1	REAR L/H PASSENGER SEAT BELT @750	✓ CRG	1500.00	640 ✓
1	REAR SPEAKER INNER BOARD	X (SVC)	950.00	
1	REAR PASSENGER SEAT BRACKET	X (SVC)	1250.00	
1	FRONT DRIVER SEAT BELT	✓ CRG	950.00	750 ✓
1	FRONT PASSENGER SEAT BLET	✓ CRG	950.00	750 ✓
2	REAR LOWER ARM L-R @ 699.9		1399.80	} NDX
2	REAR UPPER ARM L-R @ 750		1500.00	
2	REAR KNUCKLE ARM L-R @1380		2760.00	
2	REAR KNUCKLE ARM ABS SENSOR L-R @ 1400.7		2801.40	
2	REAR KNUCKLE WHEEL BEARING L-R @ 600.97		1201.94	
2	REAR SHOCK ABSORBER L-R @ 1300.72		2601.44	
2	REAR CHASSIS MEMBER L-R @ 2450.90		4901.80	

TOTAL \$76,045.90
 LESS 10% \$7,604.59
 TOTAL \$68,441.31

Social Nett Items

1	WINDSCREEN SEALANT	✓ CRG	220.00	40 ✓
10	REAR BUMPER CLIPS @ 5.50	✓ CRG	55.00	30 ✓
1	REAR NO. PLATE WITH HOLDER	✓ CRG	50.00	35 ✓
1	REAR SPARE TYRE	X (SVC)	750.00	

TOTAL \$1,075.00

Labour Charges

TOWING CHARGES	✓	250.00	60 ✓
TO REMOVE, REPASTE PRIVATE HIRE STICKER FRONT & REAR	X	50.00	
TO CHECK FRONT & REAR ELECTRICAL WIRING	✓	250.00	30 ✓
TO REMOVE, REFIX REAR WINDSCREEN	✓	150.00	120 ✓
TO REMOVE, REFIX REAR SEAT, INTERIOR TRIMS TO ASSIST REPAIR	✓	200.00	150 ✓
TO REMOVE, REFIX REAR UNDERCARRIAGE	X	650.00	
TO REMOVE REAR SEAT, ROOF AND FLOORBOARD TO ASSIST REPAIR	✓	450.00	280 ✓
TO REPROGRAMME CAR ECU	✓	600.00	280 ✓
TO RESPRAY UNDERCOATING	✓	750.00	150 ✓
TO HAUL UP & REINSTALL ENGINE TO ASSIST REPAIR	X	650.00	
TO RESPRAY PAINTING AND ETC	✓	2500.00	1800 ✓
PANEL BEATING, CUT, WELD REMOVE AND REPLACING ABOVE PARTS	✓	3000.00	1800 ✓

\$9,500.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$79,016.31

*L/S repr
without purchase
Resurvey refer part
Huck ANN
Huck ANN@lkk Auto.com
853 11883
2-50 pm
7/1/20
13 day*

69962.77

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$9,500.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$79,016.31


 31/1/2020
 L/S report
 without prejudice
 Resurvey after part
 Honda AANW
 Honda AANW@lkk Auto.com
 853 11883
 2.50 per
 7/1/20
 13 day

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

parts	21338.70
parts less	10%
	19204.83
spc nett	105
labour	4670
	23979.83
L/S less	20%
	19183.86
Total	\$ 19200.00
L/S Net	→

EURO SUCCESS SERV PTE. LTD
 1 KAKI BUKIT AVENUE 6, #02-03(AUTOBAY) SINGAPORE 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

SUPPLEMENTARY

Vehicle No: SLP7494K

LKK Auto Care
 the Repairer of the
 • To resurvey before start
 • To display damaged
 • Parts prices are subject
 • Third party survey is
 • To illegal modification
 • Supplementary item(s) must be
 is subject to final approval from

Acknowledged by Repairer
 Signature:
 Date:

QTY	List Items	Price\$
1	REAR BOOT INNER LOCK SWITCH ✓ JM	450.00 250 ✓
1	REAR BOOT INNER LOCK SWITCH BRACKET ✓ CRA	225.50 90 ✓
1	REAR BOOT LOCK MOTOR ✓ JM	550.90 270 ✓
1	REAR BOOT LOCK ECU ✓ short	975.65 587.80 ✓
1	REAR BOOT ECU X (SVC)	1250.00
1	REAR BOOT BLUETOOTH ECU ✓ CRA 4H	1380.80 830.50 ✓
1	REAR BOOT BLUETOOTH ECU BRACKET X (SVC)	230.50
1	REAR BOOT TUNER BOX DIGITAL AUDIO ECU X (SVC)	2750.50
2	REAR BOOT SPRING L-R @330 X (SVC)	660.00
1	REAR BOOT FUSE BOX X (SVC)	875.55
1	REAR FLOOR BOARD COVER X (SVC)	295.65
1	REAR SPARE TYRE PANEL FLOOR BOARD X (SVC)	259.96
1	REAR BOOT LOCK BRACKET X (NS)	120.36
1	REAR SPARE TYRE PANEL TOP COVER X (SVC)	233.69
1	REAR BOOT TOP PANEL ✓ H	1050.50 430.80 ✓
1	REAR BUMPER PDC SENSOR ECU X (SVC)	660.95
2	REAR FENDER INNER TOP PANEL L-R @950 X (R)	1900.00
1	REAR FLOOR PANEL X (R)	1750.00
2	REAR FENDER INNER PANEL L-R @1400 ✓ H/H ✓ R/H X (R)	2800.00 850.50 ✓
	TOTAL	\$18,420.51
	LESS 10%	\$1,842.05
	TOTAL	\$16,578.46

*Revised taken
 4.11.15 pm
 H. Anwar / AHK
 Mr. Ang / ABR part
 9/1/20
 853/1483*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jan 2020		07 Jan 2020 10:51 Edit Adj Rpt	S\$19,200.00 Edit Estimates	S\$19,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	AMV PTE. LTD. , Co. Reg. No.: 201505825Z								
Vehicle Reg. No.:	SLP7494K	Date of Loss:	03/01/2020 14:00 - :59 [30 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200050C02		Policy/Cover Note No.:	DMCVSN19110719000					
Vehicle Reg. No. (Insured):	XD7693Z	Policy No. (Claimant):	5091973415-02						
		Excess:	S\$1,500.00						
Repairer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 16/01/2020]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP7494K (SNM20D200050C02)
[XD7693Z]
TP
AMV PTE. LTD.
Jan 3 2020 2:00PM
[-]
Euro Success Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print		
1	06/01/20 19:07	Accident Statement			Load HTM		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print		
1	06/01/20 19:07	Accident Photo [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>	
2	06/01/20 19:07	Accident Photo [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>	
3	06/01/20 19:07	Accident Photo [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>	
4	06/01/20 19:07	Accident Photo [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>	
5	06/01/20 19:07	Accident Photo [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>	
6	06/01/20 19:07	Accident Photo [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>	
7	06/01/20 19:07	Accident Photo [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>	
8	06/01/20 19:07	Accident Photo [Linked Accident Report Documents]			Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	08/01/20 09:15	Chassis Number			Load JPG	<input checked="" type="checkbox"/>	
2	08/01/20 09:16	Odometer Reading			Load JPG	<input checked="" type="checkbox"/>	
3	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
4	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
5	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
6	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
7	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
8	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
9	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
10	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
11	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
12	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
13	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
14	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
15	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
16	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
17	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
18	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
19	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
20	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
21	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	
22	08/01/20 09:16	General View			Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
23	08/01/20 09:16	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/01/20 09:16	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/01/20 09:16	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/01/20 09:16	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/01/20 09:16	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/01/20 09:16	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
36	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
53	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
54	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
55	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
56	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
57	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
58	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
59	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
60	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
61	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
62	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
63	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
64	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
65	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
66	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
67	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
68	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
69	08/01/20 09:17	General View	Load JPG	<input checked="" type="checkbox"/>
70	08/01/20 09:17	General View	Load JPG	<input checked="" type="checkbox"/>
71	08/01/20 09:17	General View	Load JPG	<input checked="" type="checkbox"/>
72	08/01/20 09:17	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
73	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
74	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
75	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
76	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
77	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
78	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
79	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
80	08/01/20 09:17	General View	 Load JPG	<input checked="" type="checkbox"/>
81	08/01/20 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
82	08/01/20 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
83	08/01/20 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
84	08/01/20 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
85	08/01/20 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
86	08/01/20 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
87	08/01/20 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
88	08/01/20 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
89	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	14/01/20 11:23	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	14/01/20 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	14/01/20 11:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
120	14/01/20 11:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
121	14/01/20 11:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
122	14/01/20 11:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
123	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
124	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
125	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
126	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
127	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
128	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
129	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
130	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
131	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
132	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
133	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
134	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
135	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
136	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
137	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
138	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
139	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
140	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
141	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
142	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
143	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
144	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
145	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
146	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
147	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
148	14/01/20 11:24	Reinspection Photo		<input checked="" type="checkbox"/>
149	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
150	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
151	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
152	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
153	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
154	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
155	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
156	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
157	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
158	14/01/20 11:25	Reinspection Photo		<input checked="" type="checkbox"/>
159	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
160	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
161	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
162	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
163	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
164	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
165	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
166	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
167	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
168	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
169	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
170	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
171	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
172	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
173	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
174	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
175	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
176	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
177	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
178	14/01/20 11:26	Reinspection Photo		<input checked="" type="checkbox"/>
179	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
180	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
181	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
182	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
183	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
184	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
185	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
186	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
187	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
188	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
189	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
190	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
191	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
192	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
193	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
194	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
195	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
196	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
197	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
198	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
199	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
200	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
201	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
202	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
203	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
204	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
205	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
206	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
207	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
208	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
209	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
210	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
211	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
212	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
213	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
214	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
215	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
216	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
217	14/01/20 11:27	Reinspection Photo		<input checked="" type="checkbox"/>
218	07/02/20 09:18	After Repair Photo		<input checked="" type="checkbox"/>
219	07/02/20 09:18	After Repair Photo		<input checked="" type="checkbox"/>
220	07/02/20 09:18	After Repair Photo		<input checked="" type="checkbox"/>
221	07/02/20 09:18	After Repair Photo		<input checked="" type="checkbox"/>
222	07/02/20 09:18	After Repair Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
223	07/02/20 09:18	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
224	07/02/20 09:18	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
225	07/02/20 09:18	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/01/20 10:56	Pre-Repair Survey	 Load PDF	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/01/20 19:04	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
2	06/01/20 19:04	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/01/20 19:07	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/01/20 19:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	06/01/20 19:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	06/01/20 19:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	06/01/20 19:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	06/01/20 19:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	06/01/20 19:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	06/01/20 19:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	06/01/20 19:07	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	06/01/20 19:04	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	06/01/20 19:04	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120000286/HYF3E2
Date: 18/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN19110719000	
Claimant Vehicle No: SLP7494K	Insured Vehicle No: XD7693Z	
Date of Loss: 03/01/2020	Nature of Claim: TP	Claim No: SNM20D200050C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP7494K	Engine No: 65492080044043
Make & Model: MERCEDES-BENZ E220, 2.1 CDI (A)	Chassis No: WDD2130042A091050
Reg. Date: 16/06/2017 (Man. Year: 2016)	Odometer: 222492 km
Colour: Black	
Engine Capacity: 1950 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55Z R17	Rear Tyre Size: 225/55Z R17
Front Left Side: KAPSEN 6 mm	Rear Left Side: KAPSEN 6 mm
Front Right Side: KAPSEN 6 mm	Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	86,463.77	19,309.83	67,153.94	77.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,500.00	4,670.00	4,830.00	50.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	95,963.77	23,979.83	71,983.94	75.01
Approved Total (Overridden) (S\$)		19,200.00		
Nett Amount (S\$)	95,963.77	19,200.00	76,763.77	79.99

INSPECTION

Date of Assignment: 07/01/2020	Date Inspected: 07/01/2020	Inspected At: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883
Estimated Period of Repair: 13.0 days		

Adjuster: LEE HOCK ANN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2020)
Parts: 143	MERCEDES-BENZ E220 2.1 CDI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP7494K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Cut	2,710.50 FL	*2,100.50 FL
2	1		*REAR BOOT EMBLEM E220D	Necessary	110.80 FL	*65.80 FL
3	1		*REAR BOOT LID EMBLEM	Necessary	138.00 FL	*60.00 FL
4	1		*REAR BOOT CHROME MOULDING	Missing	281.63 FL	*145.30 FL
5	2		*REAR BOOT LICENCE LAMP	Crumpled	137.10 FL	*137.10 FL
6	1		*REAR BOOT INNER LOCK	Jammed	461.55 FL	*283.00 FL
7	1		*REAR BOOT OUTER LOCK	Serviceable	430.00 FL	*- FL
8	1		*REAR BOOT INNER TRIM	Crumpled	281.60 FL	*230.80 FL
9	1		*REAR BOOT RUBBER	Cracked	125.50 FL	*125.50 FL
10	1		*REAR BOOT LOCK CATCH	Repair	61.50 FL	*- FL
11	1		*REAR BOOT W/STRIP	Repeated	261.43 FL	*- FL
12	2		*REAR BOOT HINGES L-R	Repair	363.00 FL	*- FL
13	2		*REAR BOOT HINGES COVERS L-R	Serviceable	117.00 FL	*- FL
14	2		*REAR BOOT STOPPER	Serviceable	25.20 FL	*- FL
15	1		*REAR BUMPER	Cut	1,899.61 FL	*1,600.50 FL
16	1		*REAR BUMPER PDC SENSOR (6PCS)	Shorted (4Pcs Only)	1,882.50 FL	*800.00 FL
17	2		*REAR BUMPER REFLECTOR L-R	Cracked	220.40 FL	*80.00 FL
18	1		*REAR BUMPER DIFFUSER	Cracked	850.00 FL	*300.00 FL
19	1		*REAR BUMPER DIFUSSER CHROME MOULDING L/H	Scratched	350.00 FL	*100.00 FL
20	2		*REAR BUMPER LOWER BRACKET	Crumpled	91.00 FL	*91.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	899.00 FL	*760.00 FL
22	1		*REAR BUMPER RETAINERS L-R	N/S Crumpled / O/S Serviceable	420.00 FL	*86.00 FL
23	1		*REAR BUMPER INNER TOP BRACKET	Cracked	278.00 FL	*110.00 FL
24	1		*REAR BUMPER DIFUSSER INNER GARNISH	Serviceable	330.00 FL	*- FL
25	2		*REAR BUMPER LOWER EXHAUST GARNISH L-R	Serviceable	300.00 FL	*- FL
26	1		*REAR END PANEL	Bent	1,860.00 FL	*1,350.00 FL
27	1		*REAR END PANEL INNER BOARD	Crumpled	730.00 FL	*420.00 FL
28	1		*REAR END PANEL DEBIT (40PCS)	Necessary (15Pcs Only)	200.00 FL	*45.00 FL
29	1		*REAR SPARE TYRE PANEL	Repair	1,850.00 FL	*- FL
30	1		*REAR SPARE TYRE BOARD	Crumpled	698.00 FL	*620.00 FL
31	1		*REAR SPARE TYRE SPUNG	Serviceable	599.90 FL	*- FL
32	1		*REAR FLOOR BOARD	Serviceable	581.90 FL	*- FL
33	1		*REAR FENDER L-R	N/S Bent / O/S Repair	4,001.00 FL	*1,709.90 FL
34	2		*REAR FENDER AIR BAG SENSOR L-R	Serviceable	2,900.00 FL	*- FL
35	1		*REAR FENDER INNER TRIMS L-R		921.20 FL	*393.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				N/S Crumpled / O/S Serviceable		
36	2		*REAR FENDER INNER PANEL L-R	Repair	1,900.00 FL	*- FL
37	2		*REAR FENDER INNER TOP TRIM L-R	Repair	1,101.20 FL	*- FL
38	2		*REAR TAIL LAMP L-R	Cracked	2,050.00 FL	*1,551.40 FL
39	2		*REAR TAIL LAMP BRACKET L-R	No such part	560.00 FL	*- FL
40	2		*REAR TAIL LAMP COVERS L-R	No such part	111.20 FL	*- FL
41	1		*REAR TAIL LAMP COVER CLIPS (10PCS)	Necessary (6Pcs Only)	45.00 FL	*24.00 FL
42	1		*REAR KICK SENSOR	Serviceable	321.60 FL	*- FL
43	1		*REAR EXHAUST BOX	Serviceable	2,950.00 FL	*- FL
44	1		*REAR EXHAUST INSULATOR	Serviceable	1,950.00 FL	*- FL
45	2		*REAR EXHAUST CHROME PLATE L-R	Serviceable	691.00 FL	*- FL
46	2		*REAR DOOR L-R	Repair	4,700.00 FL	*- FL
47	2		*REAR DOOR RUBBER L-R	Crumpled	250.00 FL	*250.00 FL
48	1		*REAR L/H DOOR INNER BOARD L/H	Cracked	1,350.00 FL	*850.00 FL
49	2		*REAR DOOR 1/4 GLASS RUBBER L-R	Serviceable	291.00 FL	*- FL
50	2		*REAR DOOR INNER LOCK L-R	Serviceable	999.40 FL	*- FL
51	2		*REAR DOOR OUTER LOCK MOTOR L-R	Serviceable	1,101.20 FL	*- FL
52	1		*REAR WIND SCREEN GLASS	Scratched	2,450.00 FL	*1,600.00 FL
53	1		*REAR PASSENGER SEAT	Repair	3,500.60 FL	*- FL
54	1		*REAR L/H PASSENGER SEAT BELT (2PCS)	Jammed (1Pc Only)	1,500.00 FL	*640.00 FL
55	1		*REAR SPEAKER INNER BOARD	Serviceable	950.00 FL	*- FL
56	1		*REAR PASSENGER SEAT BRACKET	Serviceable	1,250.00 FL	*- FL
57	1		*FRONT DRIVER SEAT BELT	Jammed	950.00 FL	*750.00 FL
58	1		*FRONT PASSENGER SEAT BELT	Jammed	950.00 FL	*750.00 FL
59	2		*REAR LOWER ARM L-R (NOT DAMAGED)	Not Consistent With The Impact	1,399.80 FL	*- FL
60	2		*REAR UPPER ARM L-R (NOT DAMAGED)	Not Consistent With The Impact	1,500.00 FL	*- FL
61	2		*REAR KNUCKLE ARM L-R (NOT DAMAGED)	Not Consistent With The Impact	2,760.00 FL	*- FL
62	2		*REAR KNUCKLE ARM ABS SENSOR L-R (NOT DAMAGED)	Not Consistent With The Impact	2,801.40 FL	*- FL
63	2		*REAR KNUCKLE WHEEL BEARING L-R (NOT DAMAGED)	Not Consistent With The Impact	1,201.94 FL	*- FL
64	2		*REAR SHOCK ABSORBER L-R (NOT DAMAGED)	Not Consistent With The Impact	2,601.44 FL	*- FL
65	2		*REAR CHASSIS MEMBER L-R (NOT DAMAGED)	Not Consistent With The Impact	4,901.80 FL	*- FL
66	1		*WINDSCREEN SEALANT	Necessary	220.00 FS	*40.00 FS
67	10		*REAR BUMPER CLIPS	Necessary	55.00 FS	*30.00 FS
68	1		*REAR NO. PLATE WITH HOLDER	Cracked	50.00 FS	*35.00 FS
69	1		*REAR SPARE TYRE	Serviceable	750.00 FS	*- FS
70	1		*REAR BOOT INNER LOCK SWITCH	Jammed	450.00 FL	*250.00 FL
71	1		*REAR BOOT INNER LOCK SWITCH BRACKET	Cracked	225.50 FL	*90.00 FL
72	1		*REAR BOOT LOCK MOTOR	Jammed	550.90 FL	*270.00 FL
73	1		*REAR BOOT LOCK ECU	Shorted	975.65 FL	*587.80 FL
74	1		*REAR BOOT ECU	Serviceable	1,250.00 FL	*- FL
75	1		*REAR BOOT BLUETOOTH ECU L/H	Cracked	1,380.80 FL	*830.50 FL
76	1		*REAR BOOT BLUETOOTH ECU BRACKET	Serviceable	230.50 FL	*- FL
77	1		*REAR BOOT TUNER BOX DIGITAL AUDIO ECU	Serviceable	2,750.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
78	2		*REAR BOOT SPRING L-R	Serviceable	660.00 FL	*- FL
79	1		*REAR BOOT FUSE BOX	Serviceable	875.55 FL	*- FL
80	1		*REAR FLOOR BOARD COVER	Serviceable	295.65 FL	*- FL
81	1		*REAR SPARE TYRE PANEL FLOOR BOARD	Serviceable	259.96 FL	*- FL
82	1		*REAR BOOT LOCK BRACKET	No such part	120.36 FL	*- FL
83	1		*REAR SPARE TYRE PANEL TOP COVER	Serviceable	233.69 FL	*- FL
84	1		*REAR BOOT TOP PANEL	Bent	1,050.50 FL	*430.80 FL
85	1		*REAR BUMPER PDC SENSOR ECU	Serviceable	660.95 FL	*- FL
86	2		*REAR FENDER INNER TOP PANEL L-R	Repair	1,900.00 FL	*- FL
87	1		*REAR FLOOR PANEL	Repair	1,750.00 FL	*- FL
88	1		*REAR FENDER INNER PANEL L-R	N/S Bent / O/S Repair	2,800.00 FL	*850.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	95,951.41	21,443.70
- List Item Discount on L Items 10.00/10.00% (S\$)	9,487.64	2,133.87
Total Parts (S\$)	86,463.77	19,309.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	250.00	60.00
2	TO REMOVE, REPASTE PRIVATE HIRE STICKER FRONT & REAR	New	50.00	0.00
3	TO REMOVE, REFIX REAR SEAT, INTERIOR TRIMS TO ASSIST REPAIR	New	200.00	150.00
4	TO REMOVE, REFIX REAR UNDERCARRIAGE	New	650.00	0.00
5	TO REMOVE REAR SEAT, ROOF AND FLOORBOARD TO ASSIST REPAIR	New	450.00	280.00
6	TO REPROGRAMME CAR ECU	New	600.00	280.00
7	TO RESPRAY UNDERCOATING	New	750.00	150.00
8	TO HAUL UP & REINSTALL ENGINE TO ASSIST REPAIR	New	650.00	0.00
9	TO RESPRAY PAINTING AND ETC	New	2,500.00	1,800.00
10	PANEL BEATING, CUT, WELD REMOVE AND REPLACING ABOVE PARTS	New	3,000.00	1,800.00
11	TO CHECK FRONT & REAR ELECTRICAL WIRING	New	250.00	30.00
12	TO REMOVE, REFIX REAR WINDSCREEN	New	150.00	120.00
Gross Labour Cost (S\$)			9,500.00	4,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >