

国强

**ESTIMATE**

VEHICLE NO : SLJ 8914R  
 MARK & MODEL : MAZDA 3  
 Chassis No JM6BN22A8H0129108

YEAR : 2020

NO	DESCRIPTION	QTY	AMOUNT (\$)
<b>PARTS</b>			
1	Boot Lid X NN	1	\$ 1,258.50
2	Boot Lid lock X NN	1	\$ 260.00
3	Boot Lid bottom lock striker X NN	1	\$ 131.00
4	Boot lid "MAZDA" logo X NN	1	\$ 48.00
5	Boot "MAZDA 3" emblem X NN	1	\$ 39.00
6	Boot lid "SKYACTIV" emblem X NN	1	\$ 36.00
7	Boot lid weatherstrip X NN	1	\$ 185.60
8	Boot lid lamp L+R @\$277.40 X NN	2	\$ 554.80
9	Tail lamp L+R @\$538.20 X NN	2	\$ 1,076.40
10	Rear bumper - upper ✓ DE	1	\$ 1,098.70
11	Rear bumper - lower X NN	1	\$ 346.20
12	Rear bumper reflector L+R @\$64.30 X NN	2	\$ 128.60
13	Rear bumper tow cover X NN	1	\$ 22.60
14	Rear bumper center protector lower X NN	1	\$ 128.70
15	Rear bumper side retainer L+R @\$36.10 X NN	2	\$ 72.20
16	Rear bumper bracket L+R@\$45.60 X NN	2	\$ 91.20
17	Rear bumper reinforcement ✓ BT	1	\$ 558.00
18	End panel X NN	1	\$ 567.00
19	End panel top garnish X NN	1	\$ 216.50
20	Spare wheel panel X NN	1	\$ 653.00
21	Spare wheel panel top board X NN	1	\$ 285.70
<b>Total :</b>			\$ 7,757.70
<b>Less 20 %</b>			\$ 1,551.54
<b>Total :</b>			<b>\$ 6,206.16</b>
<b>Special Nett</b>			
1	Rear bumper reverse sensor (Factory Original) X NN	1 set	\$ 648.00
2	Rear bumper reverse sensor holder X NN	1 set	\$ 72.00
3	Rear bumper clips ✓ NEC	1 set	\$ 60.00
4	End panel top garnish clips X NN	1 set	\$ 60.00
5	End panel sealant X NN	1	\$ 120.00
6	Spare wheel panel sealant X NN	1	\$ 180.00
7	Rear number plate and frame X NN		\$ 55.00
<b>Total :</b>			<b>\$ 1,195.00</b>

998

538

1536

1228.8

30

Labour				
1	To staighen and panel beat rear accident area.Bootlid and garnish,bumper and all other affected portions.	1	\$ 1,000.00	200
2	To putty,spray paint and polish rear accident area.Bootlid and garnish,end panel and all other affected portions.	1	\$ 1,000.00	200
3	Check wiring after repair for proper function.	1	\$ 80.00	× NN
4	To remove and refit reverse sensors.	1	\$ 80.00	40
5	To rust proof affected areas.	1	\$ 160.00	× NN
<b>Total</b>			<b>\$ 2,320.00</b>	<b>440</b>
<b>Grand Total</b>			<b>\$ 9,721.16</b>	

1698.8

20%: 1350

2 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
Signature:  
Date: