

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Date: 06.01.2020

ACCIDENT DATE : 03.01.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Mercedes Benz C200" Reg. No. SDY9955Y Claiming Against Your Insured Veh. No. GBD7457A		1635.17
1pc	Rear Bumper <i>Re.</i>		1,820.00 1545
1pc	Rear Bumper Clips <i>MC</i>	9.00	90.00 30
1pc	Rear Bumper Sponge <i>X NN</i>		108.00 X
1pc	Rear Bumper Core LH <i>X NN</i>		65.00 X
1pc	Rear Bumper Top Retainer <i>7</i> <i>BR</i>		65.00 ✓
1pc	Rear Bumper Sensor <i>DM</i>		195.00 ✓
2pcs	Rear Bumper Sensor Holders <i>MC</i>	25.00	50.00 ✓
1pc	Rear Bumper Lower Diffuser Cover <i>SR</i>		255.00 ✓
1pc	Taillamp LH <i>ORA</i>		792.00 730 755
1pc	Taillamp Gasket <i>X NN</i>	2985.17	36.00 X
	Less 10%	2686.65	3,370.00
		2590.2	337.00
	To Conduct Electrical Check, Replace Reverse Sensor & Regrogram System		3,033.00
	Labour Charge - Panel Beating, Repairing Taillamp Panel, Bumper Reinforcement, Rear Fender and Parts Replacement		60.160.00
	To Spray Painting Affected Areas	760	300 500.00
	<i>3 Days.</i>	Total :	400 580.00
	<i>part by part.</i>		<u>1,240.00</u>
	<i>refue paint photos.</i>		3350.2
	<i>Gmo Qiang - 82880282</i>		3446.65
	<i>06 / 1 / 2020</i>		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: