


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HYUNDAI STAREX
 Engine/Chassis No.: KMFWBX7KMFU689845
 Date of accident:
 Damaged area: N/S rear

Date: 02/04/2020
 Claim Type: TP
 VRN: GBD6155C



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Taillamp n/s X NN	1	\$ 696.00	\$ 696.00
2	Taillamp panel n/s X NN	1	\$ 162.00	\$ 162.00
3	Taillamp lower garnish n/s X REPAIR	1	\$ 417.00	\$ 417.00
4	End panel X NN	1	\$ 612.00	\$ 612.00
5	End panel inner member X NN	1	\$ 324.00	\$ 324.00
6	Rear fender panel n/s X REPAIR	1	\$ 875.00	\$ 875.00
7	Rear bumper ✓ CUT	1	\$ 676.00	\$ 676.00
8	Rear bumper splash guard n/s X NN	1	\$ 139.00	\$ 139.00
9	Rear bumper lower bracket X NN	4	\$ 36.00	\$ 144.00
10	Rear bumper side retainer X NN	2	\$ 189.00	\$ 378.00
Subtotal				\$ 4,423.00
List discount				20.00%
Total				\$ 3,538.40

435

348

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Reverse sensor X NN	1	\$ 280.00	\$ 280.00
2	End panel sealant X NN	1	\$ 100.00	\$ 100.00
3	Parking aid harness X NN	1	\$ 350.00	\$ 350.00
4	Rear bumper clips ✓ NEC	10	\$ 5.50	\$ 55.00
5	Sundries X NN	1	\$ 50.00	\$ 50.00
Total				\$ 835.00

20

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray end panel, n/s rear fender panel and other affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,150.00
Estimate Grand Total			\$ 6,523.40

300
30
250
X NN
580
948
-20%: 750
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: