



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. AC2004019  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSE INV Date 19/05/2020  
SINGAPORE 189556 Reference CS/INC20000299/Gsd3n2  
ATTN: DAVID Code INC



#### PROFESSIONAL SERVICE FEE

Vehicle No. GBD 6155C  
Insured Veh. SJV 2117A  
Claim No. MT/1076716-002  
Policy No.  
Accident Date 20/12/2019  
Inspection Date 07/01/2020

Description	Total
Damage Assessment	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000299/Gsd3n2  
73 BRAS BASAH ROAD Date: 19-05-2020  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: DAVID Code: INC



### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJV 2117A	<b>Veh. Inspected</b>	GBD 6155C
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1076716-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	THERESA VIMALA	<b>Assign Date</b>	06/01/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI H1 STAREX 2.5	<b>c.c</b>	2497
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	KMFWBX7KMFU689845	<b>Colour</b>	WHITE
<b>Odometer</b>	105913 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/70 R16	FIREMAX	5 mm
<b>L/H Front Tyre</b>	215/70 R16	FIREMAX	5 mm
<b>R/H Rear Tyre</b>	215/70 R16	FIREMAX	5 mm
<b>L/H Rear Tyre</b>	215/70 R16	FIREMAX	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/12/2019	<b>Inspect Date / Time</b>	07/01/2020 ( 09:30 AM )
<b>Survey held at</b>	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 6155C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILLAMP N/S	NOT NECESSARY	696.00	-
1	TAILLAMP PANEL N/S	NOT NECESSARY	162.00	-
1	TAILLAMP LOWER GARNISH N/S	TO REPAIR SEE LABOUR	417.00	-
1	END PANEL	NOT NECESSARY	612.00	-
1	END PANEL INNER MEMBER	NOT NECESSARY	324.00	-
1	REAR FENDER PANEL N/S	TO REPAIR SEE LABOUR	875.00	-
1	REAR BUMPER	CUT	676.00	435.00
1	REAR BUMPER SPLASH GUARD N/S	NOT NECESSARY	139.00	-
4	REAR BUMPER LOWER BRACKET @\$36.00	NOT NECESSARY	144.00	-
2	REAR BUMPER SIDE RETAINER @\$189.00	NOT NECESSARY	378.00	-
	LESS 20% DISCOUNT		-884.60	-87.00
			3,538.40	348.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	PARKING AID HARNESS (SN)	NOT NECESSARY	350.00	-
10	REAR BUMPER CLIPS @\$5.50 (N)	NECESSARY	55.00	20.00
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			835.00	20.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP LOWER GARNISH N/S AND REAR FENDER PANEL N/S.		1,000.00	300.00
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS.		50.00	30.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY END PANEL,N/S REAR FENDER PANEL AND OTHER AFFECTED AREA/PANEL.		1,000.00	250.00

Report Ref No. CS/INC20000299/Gsd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST PROOF ALL AFFECTED PORTION AFTER REPAIR.	NOT NECESSARY	100.00	-
			2,150.00	580.00
<b>GRAND TOTAL</b>			<b>6,523.40</b>	<b>948.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>750.00</b>

Report Ref No. CS/INC20000299/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBD 6155C

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBD 6155C

RE-INSPECTION

