

INS. CASE OWNER:

JIMMY FOO

CC4/AIG20000308/Ada3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

ADRIAN

DOI: 09/01/2020

Date / Time: 06/01/2020

Registered in Merimen: 06/01/2020

Pre-assign / CCU / FTE



Insured Vehicle No. : SMJ 1057Z

Name of Insured : TAN YEOW SIN

Insured Tel No. : HP: +65-98210210

Excess Sec II : \$5 D.O.A : 03/01/2020

Is driver the owner? (☒ YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. : 1298019459SG

Policy No. : 1900018806

Make / Model : KIA STONIC-998CC DCT (A)

Place of Accident : OUTSIDE BARTLEY MRT STATION

OT GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability : % Final ? Yes / No

SKS 8668R



INSRS:
WSP:
Tel:
Liability:
RMKS:

Dynamic Autowork.



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	SKS 8668R - X	SMJ 1057Z - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☒
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☒
			LTA / GIA :	☒
			Medical Bill:	☒
			PIR:	☒
			Mandate/Reject Instruction:	☒
			LOD	☒
			Payment Breakdown Form:	☒
			Post-Repair Photos:	☒
			Others:	☒

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$5 (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 20/2/2020 Confirm with: Michelle Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia:

Repair Cost: (w/45) \$5 3424.00

Loss of Rental (LOR): \$5 450.00 (3 days) x \$150

Loss of Use (LOU): \$5 - (\$ a days)

Loss of Income (LOI): \$5 - (\$ a days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search \$5 36.45

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost \$5 -

Total: \$5 3910.45 Global Sum \$5: 3900.00

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1: \$5 3900.00 Name 1: Dynamic Autowork Pte Ltd

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COPY SENT 28/1/2020

1) Claim status: Normal/Reject/Private Settle
2) Report Format: ☒ P
3) Survey fee: \$320

ASS. REC. BY:

REF: ALG

ASSIGNMENT

From:

Date:

9 Jan 2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKS 8668R

at Workshop n/s

Vision Auto work / Dynamic?

of 8 RAK Bukit Ave 4 #108-09 Premier

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bot. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lim Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

map

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKS8668R

Yr Regn:

2010, Oct.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Estima

c.c. 2362

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

167114

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ALRS00108553

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Leao

Front

Rear

R/Bal.

db

mm

R/Bal.

db

mm

L/Bal.

db

mm

L/Bal.

db

mm

D.O.A.

D.O.I.

09/01/20

Survey held at

Vision

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPAIG

45 - \$3200 (Red \$8570.15/732)

MV: 30K

PV: 21.7K

Nett: 8.3K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Pop. Forms:

Long. Sign / F.P.:

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: dynamicautowork@gmail.com

DATE : 08.01.2

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKS8668R**
MODEL : **TOYOTA ESTIMA**
DATE OF ACCIDENT : 03.01.20
TIME OF ACCIDENT : 18:30HRS

Jia Le

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>dent</i>	1	\$ 1,350.00	\$ 1,350.00
2	REAR BUMPER SPONGE <i>2H could</i>	2	\$ 165.00	\$ 330.00
3	REAR BUMPER TOW HOOK COVER <i>new</i>	2	\$ 30.00	\$ 60.00
4	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 65.00	\$ 130.00
5	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 78.10	\$ 156.20
6	REAR BUMPER SIDE RETAINER (REAR) <i>new</i>	2	\$ 80.00	\$ 160.00
7	TAILGATE TOP LOCK <i>new</i>	1	\$ 395.00	\$ 395.00
8	TAILGATE LOWER LOCK <i>new</i>	1	\$ 35.00	\$ 35.00
9	TAILGATE DETECTOR <i>could</i>	1	\$ 214.00	\$ 214.00
10	TAILGATE BUZZLE <i>new</i>	1	\$ 135.00	\$ 135.00
11	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 360.00	\$ 360.00
12	REAR FENDER INNER TRIM <i>new</i>	2	\$ 680.00	\$ 1,360.00
13	REAR FENDER COWLING <i>new</i>	2	\$ 95.00	\$ 190.00
14	REAR END PANEL <i>Dented</i>	1	\$ 670.00	\$ 670.00
15	REAR END PANEL TOP GARNISH <i>3 could</i>	1	\$ 280.00	\$ 280.00
16	REAR END PANEL LOWER GARNISH	1	\$ 495.00	\$ 495.00
17	REAR FLOOR PANEL MAT <i>2 new</i>	1	\$ 970.00	\$ 970.00
18	REAR FLOOR PANEL TOP BOARD <i>could</i>	1	\$ 1,150.00	\$ 1,150.00

782

165

✓

+

+

+

+

+

+

✓

✓

+

685

3451

2588.15

TOTAL PRICE \$ 8,440.20
LESS 25% \$ 2,110.05
SUB TOTAL PRICE \$ 6,330.15

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
3	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
5	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
6	REAR END PANEL LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00

30

+

+

60

10

10

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKS8668R**
 MODEL : **TOYOTA ESTIMA**
 DATE OF ACCIDENT : 03.01.20
 TIME OF ACCIDENT : 18:30HRS

7	REAR FLOOR PANEL MAT CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>x</i>
8	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

310 TOTAL \$ 680.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
5	REMOVE AND REFIX REAR AIRCON BLOWER MOTOR AND TOP UP GAS	\$ 350.00	<i>x</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>60</i>
7	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>x</i>
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>x</i>
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

TOTAL \$4,760.00 *1180*

TOTAL PARTS COST : \$ 7,010.15
 TOTAL LABOUR COST : \$ 4,760.00
 TOTAL REPAIR COST : \$ 11,770.15

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR

ABBY (HP : 9856 4815)

I, the Repairer, hereby notify the Insurer of the following:
 • To be fully surveyed before/after spray painting
 • To be fully surveyed during resurvey
 • Parts prices are subject to confirmation
 • The repair survey is on a "Without Prejudice" basis
 • Any modification(s) is allowed
 • Any repair(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Lij *total: 4078.25*
2/5 09/01/20 *1/5: 32K*
050mp

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	785H
Vehicle Details	
Vehicle No.:	SKS8668R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	2AZF362101
Chassis No.:	ACR500108593
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$36,637.00
Original Registration Date:	22 Oct 2010
First Registration Date:	22 Oct 2010
Transfer Count:	3
Actual ARF Paid:	\$36,637.00
PARF Eligibility	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Oct 2020
PARF Rebate Amount:	\$18,318.00
COE Details	
COE Expiry Date:	21 Oct 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$43,565.00
COE Rebate Amount:	\$3,355.00
Total Rebate Amount:	\$21,673.00

The information contained herein is correct as at 09 Jan 2020

OK



 **Lake View**
Credit Pte Ltd [view our cars](http://www.lakeviewcars.com)

- Low prices guaranteed
- Specialist in Japanese cars
- Easy loan approval
- All terms are negotiable

[Browse by Category](#)
[Save Search](#)
[Print](#)
[« Back \(1 2 \) Next »](#)
[Sort by Date Posted](#)
[20 results/page](#)

Advanced Search

Search Selection	Estima	Any	Any	2010	Any	Any	Any	Available
------------------	--------	-----	-----	------	-----	-----	-----	-----------



AA Trust Automotive



Model: 113-Geo-2019 Type: 2010 Toyota Estima, 2010 Toyota Estima, Toyota Estima, Toyota Estima, Toyota, Estima, Estima, used Toyota



Vehicle In Original Condition, Ideal For Short Term Drive And Renew COE Later, Selling Cheap, Call Now Don't Miss. Loan Arrangeable

© 2010 Toyota Motor Sales, U.S.A., Inc. Toyota, Toyota logo, and all other marks contained herein are trademarks of Toyota Motor Sales, U.S.A., Inc. or its affiliates. All rights reserved. *MSRP. Excludes tax, title, license, and optional equipment. Dealer sets actual price.



\$1,331 x 64 Month, With Insurance, New Paintwork, New Leather, New Floormat. Bank Loan/In House Loan Available, Trade In Welcome.
Call Our Senior Consultant For More Details.

Publicado: 23-Oct-2019 | Page: 2012 | Tercera Edición, 2008 Segunda edición, Tercera Edición, cuarta edición, Quinta, sexta, séptima, octava

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Very Well Maintained, No Accidents And All Wear And Tear Been Replaced. No Leaks, Undercarriage All Done Up And Drives Very Quietly. View To Believe Previous Owner Already Spend About \$30k In To The Car. Full Car Sound Proof, And All Lighting And Speaker.

Foto: 21.08.2019



Low Mileage, Very Well Maintained With No Repairs Needed, Car In Excellent Condition.

Best For COE Review, 7 Seater

Applied: 07-Jan-2022 **Topic:** 2019 Toyota Fitima, 2018 Honda odion, Toyota Fitima, Sayda odion, Sayda, Fitima, odion, Haid Toyota

PRE-REPAIR INSPECTION REQUEST – SKS8668R vs SMJ1057J (OI) on D.O.A.: 03/01/2020

From: Hor, Yinnul
To: "assignments@lkkauto.com", Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Di
Sent: 1/6/2020 10:18:14 AM
Attachments: 00012020152245.pdf

Hi,

Please refer to the enclosed request from **Dynamic Autowork**.

Claim no : 1298019459SG003
Case Owner : Foo Chit Yan

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002258
Yinnul.Hor@aig.com | www.aig.sg

From: dynamicautowork@gmail.com <dynamicautowork@gmail.com>
Sent: Monday, January 6, 2020 9:47 AM
To: Hor, Yinnul <Yinnul.Hor@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMJ1057J AND SKS8668R ON 03/01/2020

Dear All,

Thanks for reply

Please arrange LKK AUTO CONSULTANTS PTE LTD to survey the above vehicle.

Michelle

From: Hor, Yinnul
Sent: Mon, 6 Jan 2020 01:41:59 +0000
To: Dynamic Autowork
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMJ1057J AND SKS8668R ON 03/01/2020

Without Prejudice

Your Reference : SKS8668R
Our Reference : 1298019459SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

308/ d03

10:37am @ 6/1/2020

P: Michelle
v: Not In

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
PNOL Adjuster I
Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

From: Dynamic Autowork <dynamicautowork@gmail.com>

Sent: Saturday, January 4, 2020 4:24 PM

To: Hor, Yinrul <yinrul.Hor@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>

Subject: [EXTERNAL] SX58668R (Pre-inspection) / Your vehicle : SMU10571

This message is from an external sender; be cautious with links and attachments.

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** PLEASE ADVISE LIABILITY****

--

Thank You.

Yours Sincerely,

Michelle
HP : 9856 4815

8 Kaki Bukit Avenue 4
#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

View Received Message

This mail is associated with :

*SKS8668R (1298019459SG)
[SMJ1057Z]
TP
ANG JIE KAI
Jan 3 2020 6:00PM
[TAN YEOW SIN]
Dynamic Autowork Pte. Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS5), sent on 17/02/2020 09:52 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3910.45) - SKS8668R - Claim Handler: Loh, Chee-Heng

Approved:3910.45.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2020 Edit Reg		06 Jan 2020 00:00 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN YEOW SIN , ID: S7600705E									
Main Claimant: ANG JIE KAI									
Vehicle Reg. No.: SKS8668R		Date of Loss: 03/01/2020 18:00 - :59 [110 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1298019459SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SMJ1057Z		Policy No. (Claimant): 5109901756							
		Excess:							
Repairer: Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 15/01/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (17/02/2020): Alert - Adj Mandate Approved (S\$3910.45) - SKS8668R - Claim Handler: Loh, Chee-H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKS8668R (1298019459SG)
[SMJ1057Z]
TP
ANG JIE KAI
Jan 3 2020 6:00PM
[TAN YEOW SIN]
Dynamic Autowork Pte. Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page 1	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1		Edit	
Assessment Reports										1 per page 1	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	17/02/20 09:01	Adjuster Immediate Advice						1		Load HTM	
Photos/Images										3 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	29/01/20 10:34	General View						1		Load JPG	
2	29/01/20 10:34	General View						1		Load JPG	
3	29/01/20 10:34	General View						1		Load JPG	
4	29/01/20 10:34	General View						1		Load JPG	
5	29/01/20 10:34	General View						1		Load JPG	
6	29/01/20 10:34	General View						1		Load JPG	
7	29/01/20 10:34	General View						1		Load JPG	
8	29/01/20 10:34	General View						1		Load JPG	
9	29/01/20 10:34	General View						1		Load JPG	
10	29/01/20 10:34	General View						1		Load JPG	
11	29/01/20 10:34	General View						1		Load JPG	
12	29/01/20 10:34	Reinspection Photo						1		Load JPG	
13	29/01/20 10:34	Reinspection Photo						1		Load JPG	
14	29/01/20 10:34	Reinspection Photo						1		Load JPG	
15	29/01/20 10:34	Reinspection Photo						1		Load JPG	
16	29/01/20 10:34	Reinspection Photo						1		Load JPG	
17	29/01/20 10:34	Reinspection Photo						1		Load JPG	
18	29/01/20 10:34	Reinspection Photo						1		Load JPG	
19	29/01/20 10:34	Reinspection Photo						1		Load JPG	
20	29/01/20 10:34	Reinspection Photo						1		Load JPG	
21	29/01/20 10:34	Reinspection Photo						1		Load JPG	
22	29/01/20 10:34	Reinspection Photo						1		Load JPG	
23	29/01/20 10:34	Reinspection Photo						1		Load JPG	
24	29/01/20 10:34	Reinspection Photo						1		Load JPG	
25	29/01/20 10:34	Reinspection Photo						1		Load JPG	
26	29/01/20 10:34	Reinspection Photo						1		Load JPG	
27	29/01/20 10:34	Reinspection Photo						1		Load JPG	
28	29/01/20 10:34	Reinspection Photo						1		Load JPG	
29	29/01/20 10:34	Reinspection Photo						1		Load JPG	
30	29/01/20 10:34	Reinspection Photo						1		Load JPG	
31	29/01/20 10:34	Reinspection Photo						1		Load JPG	
32	29/01/20 10:34	Reinspection Photo						1		Load JPG	
33	29/01/20 10:34	Reinspection Photo						1		Load JPG	
34	29/01/20 10:34	Reinspection Photo						1		Load JPG	
35	29/01/20 10:34	Reinspection Photo						1		Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/01/20 17:29	ACKNOWLEDGEMENT EMAIL TO AIG DD 06.01.2020	Load PDF	
2	06/01/20 17:29	EMAIL FROM AIG DD 06.01.2020	Load PDF	
3	06/01/20 17:29	NOTIFICATION FROM WORKSHOP + TP GIA REPORT	Load PDF	
4	05/02/20 17:10	TP ESTIMATE - MARKED (FINAL)	Load PDF	
5	14/02/20 17:51	LOD	Load PDF	
6	14/02/20 17:51	RENTAL RECEIPT	Load PDF	
7	14/02/20 17:51	LTA/GIA Search Fee	Load PDF	
8	03/03/20 14:17	WORKSHOP INVOICE	Load PDF	
9	03/03/20 14:17	AUTHORISATION TO ACT FORM	Load PDF	
10	03/03/20 14:17	Release Voucher	Load PDF	
11	03/03/20 14:17	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/01/20 14:26	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SMJ1057Z (Insd veh)	Model:	TOYOTA ESTIMA 2.4 (A)
	SKS8668R (TP veh)		
Date of Accident:	03/01/2020		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	12,594.06
Final Repair Cost	:	\$	3,900.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	3 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,900.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Dynamic Autowork Pte. Ltd.	:	\$ 3,900.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

03 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20000308/ADA3Q2

Date: 03/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SKS8668R

Insured Vehicle No : SMJ1057Z

Date of Loss: 03/01/2020

Nature of Claim: TP

Claim No: 1298019459SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS8668R

Make & Model: TOYOTA ESTIMA, 2.4 (A)

Engine No: 2AZF362101

Reg. Date: 22/10/2010 (Man. Year: 2010)

Chassis No: ACR500108593

Colour: Silver

Odometer: 167114 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: LEAO 6 mm

Rear Left Side:

LEAO 6 mm

Front Right Side: LEAO 6 mm

Rear Right Side:

LEAO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,010.15	2,898.25	4,111.90	58.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,760.00	1,180.00	3,580.00	75.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,770.15	4,078.25	7,691.90	65.35
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	11,770.15	3,200.00	8,570.15	72.81
+ GST 7.00/7.00% (S\$)	823.91	224.00	599.91	72.81
Nett Amount (S\$)	12,594.06	3,424.00	9,170.06	72.81
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,910.45		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment: 06/01/2020

Date Inspected: 09/01/2020 Inspected At:

Dynamic Autowork Pte. Ltd (HQ)

8 Kaki Bukit Ave 4, #08-09 Premier @

Kaki Bukit

Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,350.00 FL	*782.00 FL
2	1		*REAR BUMPER SPONGE	O/S Cracked	330.00 FL	*165.00 FL
3	2		*REAR BUMPER TOW HOOK COVER	Not Necessary	60.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	130.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER (FRONT)	Not Necessary	156.20 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINER (REAR)	Necessary	160.00 FL	*160.00 FL
7	1		*TAILGATE TOP LOCK	Not Necessary	395.00 FL	*- FL
8	1		*TAILGATE LOWER LOCK	Not Necessary	35.00 FL	*- FL
9	1		*TAILGATE DETECTOR	Cracked	214.00 FL	*214.00 FL
10	1		*TAILGATE BUZZLE	Not Necessary	135.00 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Not Necessary	360.00 FL	*- FL
12	2		*REAR FENDER INNER TRIM	Not Necessary	1,360.00 FL	*- FL
13	2		*REAR FENDER COWLING	Not Necessary	190.00 FL	*- FL
14	1		*REAR END PANEL	Dented	670.00 FL	*670.00 FL
15	1		*REAR END PANEL TOP GARNISH	Cracked	280.00 FL	*280.00 FL
16	1		*REAR END PANEL LOWER GARNISH	Cracked	495.00 FL	*495.00 FL
17	1		*REAR FLOOR PANEL MAT	Not Necessary	970.00 FL	*- FL
18	1		*REAR FLOOR PANEL TOP BOARD	Cracked	1,150.00 FL	*685.00 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
20	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
21	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
22	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
23	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
24	1		*SET REAR END PANEL LOWER GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
25	1		*SET REAR FLOOR PANEL MAT CLIP	Not Necessary	50.00 FS	*- FS
26	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,120.20	3,761.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,110.05	862.75
Total Parts (\$\$)	7,010.15	2,898.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	400.00
3	TUFF COAT	New	250.00	60.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
5	REMOVE AND REFIX REAR AIRCON BLOWER MOTOR AND TOP UP GAS	New	350.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	60.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			4,760.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >