

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

Repair Limit 2k 23k?

TO	: AIG	DATE	: 3-Jan-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: Vic	VEHICLE NO	: SGY3982G
ADDRESS	:	MODEL	: CHEVROLET AVEO
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE :			
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT :			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID Dented	1	\$ 1,159.00	\$ 1,159.00
2	BOOT LID EMBLEM 'AVEO'	1	\$ 49.00	\$ 49.00
3	BOOT LID EMBLEM 'CHEVROLET'	1	\$ 64.00	\$ 64.00
4	BOOT LID INNER LOCK New	1	\$ 242.00	\$ 242.00
5	BOOT LID LOWER LOCK New	2	\$ 41.00	\$ 82.00
6	BOOT LID WEATHER STRIP New	1	\$ 98.00	\$ 98.00
7	REAR FENDER INNER TRIM New	2	\$ 24.00	\$ 48.00
8	REAR BUMPER Dented	1	\$ 1,415.00	\$ 1,415.00
9	REAR BUMPER BRACKET New	2	\$ 51.00	\$ 102.00
10	REAR BUMPER SPONGE New	1	\$ 356.00	\$ 356.00
11	REAR BUMPER REINFORCEMENT BRACKET New	2	\$ 193.00	\$ 386.00
12	REAR BUMPER SIDE REATINER New	2	\$ 62.00	\$ 124.00
13	TAILLAMP New	2	\$ 328.00	\$ 656.00
14	REAR FENDER INNER TRIM New	2	\$ 694.00	\$ 1,388.00

15	REAR END PANEL <i>Repair</i>	1	\$ 641.00	\$ 641.00	+
16	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 249.00	\$ 249.00	-
17	REAR SPARE TYRE BOLT <i>new</i>	1	\$ 49.00	\$ 49.00	+
18	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 569.00	\$ 569.00	+

3034
2730.60

TOTAL PRICE \$7,677.00
LESS 10% \$ 767.70
SUB TOTAL PRICE \$6,909.30

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$50.00	\$50.00	+
2	REAR BUMPER CLIPS <i>new</i>	8	\$6.50	\$52.00	30
3	REAR FENDER INNER TRIM CLIPS <i>new</i>	20	\$6.50	\$130.00	+
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	3	\$8.50	\$25.50	+
5	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$150.00	\$150.00	+
6	REAR FLOOR PANEL INSULATOR SEAL <i>new</i>	1	\$280.00	\$280.00	+
7	REVERSE SENSOR <i>Repair</i>	1	\$220.00	\$220.00	20

8) Rear bumper LIP \$1800 - 700
Deland

930

TOTAL \$907.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$1,400.00	600	
2	TO SPRAY PAINT AFFECTED AREA	\$1,200.00	800	
3	TUFF COAT	\$250.00	60	
4	WIRING AND BULB CHECK	\$80.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$250.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50	
7	REAR CHASSIS ALIGNMENT	\$250.00	x	
8	TRANSFER BOOT LID MECHANISM	\$80.00	x	
9	CONDUCT WATER LEAKAGE TEST	\$120.00	x	
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$150.00	x	

1600

TOTAL

\$3,860.00

ESTIMATE REPORT

TOTAL PARTS COST : \$7,816.80
TOTAL LABOUR COST : \$3,860.00
TOTAL REPAIR COST : \$11,676.80

APPROVED DETAILS

EXCESS :
NO. OF DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lj
L/S 09/01/20.
05 hrs.

Nett Value : \$1.5K
agreed.

total 5260.60

L/S 1.5K ✓
(Nett Value).

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: