

DATE 30.12.2019

**PC5514X YUTONG ZK6938H**

| No       | Qty | PARTICULAR                                  | AMOUNT S\$    |
|----------|-----|---|---------------|
| 1        | 1   | FRONT BUMPER <i>one 1680</i>                | 2,850.00      |
| 2        | 1   | FRONT BUMPER RE-INFORCEMENT <i>n-1</i>      | 852.00        |
| 3        | 1   | FRONT BUMPER BRACKET RH <i>n-1</i>          | 250.00        |
| 4        | 1   | FRONT HEADLAMP RH <i>one 1620</i>           | 3,200.00      |
| 5        | 1   | FRONT HEADLAMP GARNISH RH <i>one 215.00</i> | 280.00        |
| 6        | 1   | SIDE PANEL RH <i>2</i>                      | 1,988.00      |
| 7        | 1   | WASHER TANK DOOR                            | 1,255.00      |
| 8        | 2   | WASHER TANK DOOR LOCK <i>Daye</i>           | 160.00 320.00 |
| 9        | 2   | WASHER TANK DOOR HINGE <i>n-1</i>           | 180.00 360.00 |
|          |     |   | \$ 11,355.00  |
| LESS 10% |     |   | \$ 1,135.50   |
|          |     |   | \$ 10,219.50  |

| No | Qty | PARTICULAR             | SPECAIL NETT | AMOUNT S\$ |
|----|-----|------------------------|--------------|------------|
| 1  | 1   | SIDE WINDOW SEALANT    |              | 17 90.00   |
| 2  | 1   | SIDE WINDOW INNER SEAL |              | 17 80.00   |
|    |     |                        |              | \$ 170.00  |

**LABOUR & MISCELLANEOUS:**

|   |  |             |             |
|---|--|-------------|-------------|
| 1 | To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments | <i>600</i>  | 2,800.00    |
| 2 | To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials  | <i>800</i>  | 1,800.00    |
| 3 | To remove, refit right side panel window glass with all necessary components   | <i>17 X</i> | 200.00      |
| 4 | To remove, refit right side panel inner garnishes with all necessary components  | <i>17 X</i> | 200.00      |
| 5 | To conduct front headlamp alignment  | <i>20</i>   | 50.00       |
|   |  |             | \$ 5,050.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 15,439.50