

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

WVWZZZ1KZ8M014198

NUR SYAHIDAH BINTE SHAMSUDDEEN
BLK 562 PASIR RIS ST 51
#12-257
S 510562

TP China
Ichonchna.

Date :14.02.2020
Vehicle No :SKA 7360 D
Make/Model :VOLKSWAGEN JETTA
Accident date :31.12.2019

No	DESCRIPTION	Qty	Amount (\$S)
<u>List Items</u>			
1	Rear bootlid <i>Regis</i>	1	\$ 1540 <i>X</i>
2	Rear bootlid hinges @ \$231.00 <i>3 Here</i>	2	\$ 462 <i>X</i>
3	Rear bootlid shock absorber @ \$110.00	2	\$ 220 <i>X</i>
4	Rear bootlid upper lock <i>3 Not ne</i>	1	\$ 137.5 <i>X</i>
5	Rear bootlid lower lock	1	\$ 55 <i>X</i>
6	Rear bootlid weather strip <i>ne ne</i>	1	\$ 319 <i>X</i>
7	Rear bootlid centre emblem <i>3</i>	1	\$ 99 <i>✓</i>
8	Rear bootlid Jetta emblem <i>3</i>	1	\$ 88 <i>✓</i>
9	Rear bootlid TSI emblem	1	\$ 77 <i>✓</i>
10	Rear bootlid reflector @ \$198.00 <i>Not ne</i>	2	\$ 396 <i>X</i>
11	Rear bootlid top spoiler <i>Not ne</i>	1	\$ 528 <i>X</i>
12	Rear end panel <i>Dented</i>	1	\$ <u>1210</u> <i>870</i>
13	Rear end panel top garnish <i>cracked</i>	1	\$ 154 <i>✓</i>
14	Rear bumper <i>Distorted</i>	1	\$ 1100 <i>✓</i>
15	Rear bumper side holder @ \$63.80 <i>LH ne</i>	2	\$ 127.6 <i>6380</i>
16	Rear bumper lower lip <i>Deformed</i>	1	\$ 660 <i>✓</i>
17	Rear bumper reflector @ \$60.50 <i>LH cracked</i>	2	\$ 121 <i>6050</i>
18	Rear bumper reinforcement <i>Dented</i>	1	\$ 517 <i>✓</i>
19	Rear bumper centre guide <i>ab ne</i>	1	\$ 121 <i>X</i>
20	Rear bumper bracket @ \$63.80 <i>Ne ne</i>	2	\$ 127.6 <i>X</i>
21	Rear lamp @ \$297.00 <i>LH cracked</i>	2	\$ 594 <i>297</i>
22	Rear lamp housing @ \$165.00 <i>Regis</i>	2	\$ 330 <i>X</i>
23	Rear lamp lower bracket <i>cracked</i>	1	\$ 170 <i>25</i>
24	Rear exhaust pipe <i> Bent</i>	1	\$ 55 110 <i>✓</i>
25	Rear exhaust pipe mounting <i>Not ne</i>	1	\$ 99 <i>X</i>
			\$ 9907.7
Less 10% Disc			\$ 990.77
Total			\$ 8916.93

488130

4393.17

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NUR SYAHIDAH BINTE SHAMSUDDEEN
BLK 562 PASIR RIS ST 51
#12-257
S 510562

Date :14.02.2020
Vehicle No :SKA 7360 D
Make/Model :VOLKSWAGEN JETTA
Accident date :31.12.2019

No	DESCRIPTION	Qty	Amount (\$\$)
----	-------------	-----	---------------

Special Nett Items

1	Rear reverse sensor @ \$380.00 <i>Damaged</i>	2	\$ 760 ²⁰⁰
		Total	\$ 760

Labour Cost

1	To supply rear end panel inner sealant	\$ 200 ⁶⁰
2	Remove & reinstall exhaust pipe	\$ 380 ⁸³
3	Remove & reinstall reverse sensor	\$ 150 ⁵⁰
4	Remove & reinstall petrol tank	\$ 150 x
5	Remove ,replace & repair consistent to the accident	\$ 1800 ⁶⁰⁰
6	Respray painting	\$ 1400 ⁶⁰⁰
7	Tuff kote	\$ 150 ⁶⁰
	Total	\$ 4230

Grand Total \$ 13906.93

total: 6043.17
1/2: 4.7K (Nett Value)
06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: