


REPAIR ESTIMATE*

INDIA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Van</i>			\$ 553.00	X
	Rear Bumper Clip 10 pcs <i>SVL</i>			\$ 22.00	X
	Tail Lamp (RH) <i>HL</i>			\$ 697.80	X
	Rear Fender With Housing (RH) <i>Pender</i>		<i>2020-00</i>	\$ 4,736.80	✓
	Rear Windscreen Moulding <i>Hec</i>			\$ 28.30	✓
	Rear Door (RH) <i>Pender</i>			\$ 2,201.10	✓
	Rocker Panel Outer Garnish (RH) <i>Repair</i>			\$ 341.40	X
	Rear Tyre Rim (RH) <i>HL</i>			\$ 325.30	X
	Rear Wheel Hup-Cap (RH) <i>HL</i>			\$ 107.10	✓
	Rear Wheelbearing ING & Hub <i>2 Dom</i>			\$ 362.00	✓
	Rear Trailing Arm (RH) <i>2 distributor</i>			\$ 192.00	✓
	Rear Assist (RH) <i>2 distributor</i>			\$ 145.70	✓
	Rear Shock Absorber (RH) <i>2 distributor</i>			\$ 276.30	✓
	Rear Shock Absorber Mounting (RH) <i>HL</i>			\$ 81.30	X
	Rear Crossmember <i>HL</i>			\$ 1,021.50	X
	Stabilizer Bar <i>HL</i>			\$ 199.60	X
	Stabilizer Link <i>HL</i>			\$ 85.90	X
	Rear Upper Arm (RH) <i>2 distributor</i>			\$ 335.75	✓
	Rear Lower Arm (RH) <i>2 distributor</i>			\$ 353.80	✓
	Rear Knuckle Arm (RH) <i>2 distributor</i>			\$ 545.60	✓
	SUB TOTAL			\$ 12,612.25	
	LESS 20%			\$ 2,522.45	
	DISCOUNTED TOTAL			\$ 10,089.80	
	Rear Bumper Advertisement Logo <i>Hec</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>HL</i>			\$ 50.00	Nett X
	Rear Fender Advertisement Logo (LH/RH) <i>Hec</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>Hec</i>			\$ 46.00	Nett ✓
	Rear Door Advertisement Logo (RH) <i>Hec</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>Hec</i>			\$ 80.00	Nett ✓
	Rear Tyre (RH) <i>HL</i>			\$ 216.00	Nett X
				\$ 742.00	

SHA 9980L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			\$ 1,800.00
	Panel Beating			\$ 1,250.00
	Spray Painting Charge			\$ 50.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 150.00
	Remove/Refix Cushion & Upholstery Rear			\$ 120.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door			\$ 200.00
	Remove/Refix Undercarriage (RR)			\$ 120.00
	Rear Wheel Alignment			\$ 200.00
	Re-set Rear ABS System			\$ 200.00
	Re-set Rear Power Window System			\$ 480.00
	Diagnostic & Resetting To Erase Fault Code			
	TOTAL LABOUR			\$ 4,910.00
	ESTIMATE TOTAL			\$ 15,741.80
	03/01/2020 @ 1700hrs Noted Anthony 2/Sum 5 days.  LKK Auto 			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

600/-

600/-

44

30/-

44

80/-

80/-

44

60/-

150/-

60/-

150/-

150/-