



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMP7068X

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **39710**
Reg No/Reg Date **SMP7068X / 28/02/2014**
Date In/Mileage **08/01/2020 / 73914**
Chassis No **WDD2120362A942649**
Engine No **27492030132417**
Make/Model **MB/E 250 2.0 CGI SEDAN (W212**
Colour/Trim **029 988 Diamond Sil/ 042 258 Basalt Grey**

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|------------------|
| WC000668 | Credit | 10/01/2020/ 14:31 | K0 | 301 / Kerlyn Ong |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|-----|------------|-------|--------|
|---------------------------------|-----|------------|-------|--------|

Z REQUEST

Customer Request
M-BPNSUN

POLICY NO/ACC DATE : GA510830/1 // 12/12/2019
DRIVE IN/EXCESS : 13/12/2019 // SMN7432M - CHINA
DATE IN/DATE SURVEY: 08/01/2020 1215 // LKK - RASUL
DIRECT SETTLEMENT : 27/12/2019 1333 // CHINA - BOON SEN

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

X REAR BUMPER

1.00 1634.56 00.00 1634.56

X LH/ REAR BUMPER CHROME MOULDING

1.00 134.36 00.00 134.36

X RH/ REAR BUMPER CHROME MOULDING

1.00 166.46 00.00 166.46

X LH/ BASIC MOUNTING FOR BUMPER

1.00 50.89 00.00 50.89

X RH/ BASIC MOUNTING FOR BUMPER

1.00 50.89 00.00 50.89

Finalization

Confirmed & accepted by

Nett **4,097.16**
7% GST on **4097.16** **286.80**

Authorized signatory and company stamp

Total Payable **4,383.96**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMP7068X

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **39710**
Reg No/Reg Date **SMP7068X / 28/02/2014**
Date In/Mileage **08/01/2020/ 73914**
Chassis No **WDD2120362A942649**
Engine No **27492030132417**
Make/Model **MB/E 250 2.0 CGI SEDAN (W212)**
Colour/Trim **029 988 Diamond Sil/ 042 258 Basalt Grey**

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|------------------|
| WC000668 | Credit | 10/01/2020/ 14:30 | K0 | 301 / Kerlyn Ong |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|------|------------|-------|--------|
| X LH/ BASIC MOUNTING FOR BUMPER | 1.00 | 50.89 | 00.00 | 50.89 |
| X RH/ BASIC MOUNTING FOR BUMPER | 1.00 | 50.89 | 00.00 | 50.89 |

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

| | | |
|---------------|--------|--------|
| | Nett | 101.78 |
| 7% GST on | 101.78 | 7.12 |
| Total Payable | | 108.90 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany