

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 24733

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0008/2020/KK
Date	:	6-Jan-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lim Hock Lai
Address	:	41 Choa Chu Kang Loop #06-12 Singapore 689677
Telephone	:	HP +65 97712122
Type of Claim	:	Own Damage Claim
Policy No.	:	1800033031
Vehicle No	:	SLX 7606 M
Model Code	:	Audi A6 1.8 TFSI S TRONIC
Model / Year	:	Apr-18
Engine No	:	CYG 020601
Chassis No	:	WAUZZZ4GXHN128184
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	27-Dec-19
Place of Accident	:	Great World City Car Park Basement 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 7606 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	<i>X</i>
2	To remove and reinstall aircond condenser and radiator. To renew charged air coller. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00	<i>X</i>
3	To dismantle and renew front bumper. To remove and reinstall front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 4,000.00	<i>500</i>
4	To rep spray front bumper.	\$ 1,200.00	<i>750</i>
5	To carry out diagnostic check.	S/N \$ 192.00	<i>✓</i>
TOTAL LABOUR CHARGES		: \$ 7,272.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7606 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>cut</i>	\$ 2,787.00	<i>229.60</i>
2	FRONT BUMPER FIXING PARTS <i>X su</i>	\$ 491.00	
3	FRONT BUMPER CENTRE GRILLE - LOWER <i>cr</i>	\$ 116.00	<i>92.40</i>
4	FRONT BUMPER AIR GUIDE GRILLE LOCKING CLIP <i>X nn</i> 14	\$ 51.00	
5	FRONT BUMPER CLOSING ELEMENT <i>X su</i>	\$ 199.00	
6	FRONT BUMPER LOWER SPOILER <i>de</i>	\$ 227.00	<i>181.20</i>
7	FRONT BUMPER UPPER SPOILER <i>X cr cr cr</i>	\$ 860.00	<i>687.60</i> ✓
8	RADIATOR GRILLE <i>cr</i>	\$ 1,766.00	<i>1412.80</i>
9	RADIATOR GRILLE COVER <i>X su</i>	\$ 33.00	
10	RADIATOR SENSOR SUPPORT - LH/RH <i>? X su</i>	\$ 122.00	<i>X</i>
11	FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>X su</i>	\$ 904.00	
12	FRONT BUMPER AIR GUIDE GRILLE COVER - LH/RH <i>X su</i>	\$ 92.00	
13	FRONT WHEEL SPOILER - LH/RH <i>X su</i>	\$ 482.00	
14	FRONT HEADLAMP WASHER COVER - LH/RH <i>X su</i>	\$ 104.00	
15	FOAM FILLER PIECE <i>X su</i>	\$ 215.00	
16	FRONT BUMPER REINFORCEMENT <i>X bt bt</i>	\$ 754.00	<i>602.80</i> ✓
17	FRONT BUMPER TOP COVER <i>X su</i>	\$ 112.00	
18	SIGN 'CAUTION' <i>X nn</i>	\$ 13.00	
19	FRONT SENSOR <i>X su</i>	2 \$ 419.00	
20	FRONT SENSOR SEAL RING <i>X nn</i>	4 \$ 5.00	
SUB TOTAL SPARE PARTS		: \$ 9,752.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 7606 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT BUMPER AIR GUIDE - LH/RH X <i>en</i>	\$	50.00
22	RADIATOR UPPER COVER X <i>en</i>	\$	27.00
23	RADIATOR LOWER SEALING STRIP X <i>en</i>	\$	21.00
24	AIR COOLER X <i>en</i>	\$	513.00
25	FRONT NO PLATE <i>SA</i> ✓	S/N \$	40.00 ✓
26	SUNDRIES ? <i>nu</i> ✓	\$	300.00 <i>40.32</i> ✓
TOTAL SPARE PARTS		:	\$ 10,703.00
TOTAL LABOUR CHARGES		:	\$ 7,272.00
GRAND TOTAL		:	\$ 17,975.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Rasul - Hp 90610668

Surveyed Date

: 06/01/2020 @ 1030

Authorised Date

:

Excess Cost

:

3 days

Liability

:

Remarks

:

EXCESS: TBA

Revert
Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____
Alan Wu

Claims Consultant