

ASS. REC. BY:

REF: CS/CT1 20060361/khf3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tan Hui Ping of CT1 Date/Time: 7. Jan. 2020

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 2630m Insured:

at Workshop m/s S R H Motor Tel: 6453 4730

of 160 Sin Ming Drive # 07-02

Policy No: DMBSN 3076621800 Claim No: SNM 200200056 / PC2630m / Irene

Sum Insured: Excess: \$1500.00

Make of Veh: D.O.A. 2.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 7.1.20 10.32a.m Person Contacted: Cynthia Vehicle: IN/OUT

| Date/Time   | Action/Instruction (✓) Estimate                      |
|-------------|--|
|             | PC 2630m - (C3/AXD 14014665/K1WY/392 D.02-20/07/2014 |
| 7/1 @ 15.26 | mandate Request                                      |
| 8/1 @ 10.13 | mandate Approval by Irene Tan                        |
| 8/1 @ 11.19 | inform Cynthia authorise part by part excess \$1500. |

ASS. REC. BY:

REF: CT2 / CS / CT1 20000361 / Ktf3

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

06 days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

1-B / %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_

Colour: \_\_\_\_\_

Sp. Reading: \_\_\_\_\_

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size: \_\_\_\_\_

F: Yoko

R: Journey

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

R/Bal. \_\_\_\_\_

L/Bal. \_\_\_\_\_

D.O.A. \_\_\_\_\_

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

part by part \$8036.30, 6days (Red:1740.80; 17%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: \_\_\_\_\_

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S - RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

8036.30 p/p

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                    | Est Submitted                             | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|---|---|--|---------|---------------|------------|--|
| Main | 06 Jan 2020<br><a href="#">Sendback Est</a> | 06 Jan 2020<br>15:25<br><b>\$9,337.10</b> | 07 Jan 2020<br>10:27<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

### CLAIM SUBFOLDER DETAILS

|                   |   |                        |   |
|-------------------|---|------------------------|---|
| Insured:          | <b>RIEZQI TRANSPORTATION</b> , Co. Reg. No.: 53315610J  |                        |   |
| Vehicle Reg. No.: | <b>PC2630M</b>  | Date of Loss:          | 02/01/2020 06:00 - :59<br>[66 Months and 3 Days From LTA Reg Date (Man Yr)] |
| Claim Type:       | <b>OD / SNM20D200056/PC2630M/IRENE</b>  | Policy/Cover Note No.: | DMB1SN3076621800 (Comprehensive)  |
|                   |   | Excess:                | S\$1,500.00   |
| Repairer:         | <b>S &amp; H Motor Pte Ltd (Sin Ming)</b> 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730          |                        |   |
| Handling Insurer: | <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192] |                        |   |
| Adjuster:         | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 16/01/2020]  |                        |   |
| Driver/Custodian: | LIM CHIN KEONG (44 / Male) , NRIC: S7537906D, Tel: +6588963298 Email: NOEMAIL   |                        |   |
| Adj Asg. Remarks: | PLEASE SURVEY AND REVERT  |                        |   |

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Business                             |
| Owner ID:                           | 610J                                 |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | PC2630M                              |
| Vehicle to be Exported:             | No                                   |
| Intended Deregistration Date:       | 07 Jan 2020                          |
| Vehicle Make:                       | TOYOTA                               |
| Vehicle Model:                      | HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB |
| Primary Colour:                     | Silver                               |
| Manufacturing Year:                 | 2014                                 |
| Engine No.:                         | 1KD2396426                           |
| Chassis No.:                        | KDH2230019876                        |
| Maximum Power Output:               | -                                    |
| Open Market Value:                  | \$36,716.00                          |
| Original Registration Date:         | 30 Jun 2014                          |
| First Registration Date:            | 30 Jun 2014                          |
| Transfer Count:                     | 1                                    |
| Actual ARF Paid:                    | \$1,836.00                           |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | No                                   |
| PARF Eligibility Expiry Date:       | -                                    |
| PARF Rebate Amount:                 | \$0.00                               |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 29 Jun 2024                          |
| COE Category:                       | C - Goods Vehicle & Bus              |
| COE Period(Years):                  | 10                                   |
| PQP Paid:                           | \$28,070.00                          |
| COE Rebate Amount:                  | \$12,958.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$12,958.00</b>                   |

The information contained herein is correct as at 07 Jan 2020

OK

\$4216 (cost)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |  |
|----------------------------|--|
| Date Of Report             | 03/01/2020 12:03                                   |
| Date Of Accident           | 02/01/2020 06:45                                   |
| Exact Location Of Accident | ALONG RD 1 OLD TAMPINES RD TO TANAH MERAH BESAR RD |
| Country/State of Loss      | SINGAPORE  |

### DETAILS OF OWN VEHICLE

|                             |                       |
|-----------------------------|-----------------------|
| Vehicle Registration Number | PC2630M               |
| <b>Insured/Policyholder</b> |                       |
| Name Of Registered Owner    | RIEZQI TRANSPORTATION |
| Co Reg No                   | 5XXXXX10J             |
| Email Address               | NOEMAIL               |
| Mobile Phone No             | (LOCAL) +65-88963298  |
| Alternative Phone No        | OFFICE-88963298       |

### Vehicle Particulars

|  |                    |
|--|--------------------|
| Manufacturer   | TOYOTA             |
| Model  | HIACE              |
| Exact Purpose for which vehicle was being used at time of accident           |                    |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES                |
| If No, Please state action to be taken                                       |                    |
| Vehicle Category   | COMMERCIAL VEHICLE |

### Insurance Company

|                           |   |
|---------------------------|---|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                                 |
| Fleet Policy              | NO  |
| Policy Number             | DMB1SN3076621800                              |
| Cover Note Number         |   |

### Driver

|                      |                        |
|----------------------|------------------------|
| Name of Driver       | LIM CHIN KEONG         |
| NRIC No              | SXXXX906D              |
| Date Of Birth        | 22/12/1975             |
| Occupation           | OUTDOOR                |
| Date Of Driving Pass | 02/03/2004             |
| Driving Experience   | 15 YEARS AND 10 MONTHS |
| Gender               | MALE                   |
| Mobile Number        | (LOCAL) +65-88963298   |
| Fax Number           |                        |
| Contact Number       |                        |
| EEmail Address       | NOEMAIL                |

**Attachment(s)**

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

**DETAILS OF OTHER VEHICLE PROPERTY 1**

|                                     |          |
|-------------------------------------|----------|
| Vehicle Registration Number         | SBS9838S |
| Vehicle Make/Model/Colour           |          |
| Details Of Properties               |          |
| Vehicle Category                    | BUS      |
| Name of Driver                      |          |
| NRIC/Passport Number                |          |
| Contact Number                      |          |
| Address                             |          |
| Postcode                            |          |
| Insurance Company Name              |          |
| Nature Of Damage                    |          |
| No. Of Passenger (Including Driver) |          |


**DETAILS OF INJURED PERSON 1**

|   |         |
|---|---------|
| Name  |         |
| Approximate Age                                     |         |
| Injuries Sustain                                    |         |
| Injured person in which vehicle?                    | PC2630M |
| Were seat belts worn?                               |         |
| Was this injured conveyed to hospital by ambulance? | YES     |
| Address   |         |
| Postcode  |         |

**DETAILS OF INJURED PERSON 2**

|   |         |
|---|---------|
| Name  |         |
| Approximate Age                                     |         |
| Injuries Sustain                                    |         |
| Injured person in which vehicle?                    | PC2630M |
| Were seat belts worn?                               |         |
| Was this injured conveyed to hospital by ambulance? | YES     |
| Address   |         |
| Postcode  |         |

SKETCH PLAN



A - PC 2630m  
B - SB 98385

A → B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer attached police report.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20200102/2031

2 of 3

Report No. T/20200102/2031

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

**CONTINUATION OF REPORT**

**Brief Details.**

On 02/01/2020 at 6.48 am along Old Tampines Road, I was driving my company van (PC2630M) and there was one bus (SBS9838S) in-front of me. The bus braked but I could not brake in time causing the front of the van to hit onto the rear of the bus. Ambulance came and conveyed two of my passengers to Changi Hospital for medical treatment. Both of them were discharged and given 1 day and 2 days MC respectively. Traffic police came to the location and took the SD card from my in-car camera and told me to lodge a traffic police report.



**S&H Motor Pte Ltd**  
**160 Sin Ming Drive #07-02**  
**Sin Ming Autocity**  
**Singapore 575722**

Insurer Reference:

Repairer Reference: 026051

Date calculated: 06/01/2020 2:48 PM

**Summary Information**

**Claim**

Location: Singapore (SG)

Work Provider:

Printed by: SH Motor

Currency:

Claim Reference:

Date of Incident

Estimated Repair Time:

Hire Car Start:

Actual Repair Days:

Hire Car End:

**Vehicle Details**

**Vehicle**

Manufacturer: TOYOTA  
 Model: HIACE  
 Sub Model: COMMUTER BUS  
 Model Sheet Number: 70 E4 05  
 Registration: PC2630M

VIN number:

Odometer:

**Model Specs**

FRT + REAR AIR CON 3.0 LTR 100/106 KW TWO

**Labour**

| Code      | Description   | Time Base 10 W |       |
|-----------|---|----------------|-------|
| B091      | R + R LEFT FRONT WING   |                | 20    |
| B091      | R + R RIGHT FRONT WING  |                | 20    |
| B020)     | RENEW FRONT BUMPER REINFORCEMENT  |                | 2.60  |
| B020      | RENEW FRONT BUMPER<br>(BUMPER REMOVED)<br>INCLUDES: R + R FRONT FOG LAMPS |                | 9.40  |
| NO NUMBER | R + R CENTRE LOWER RADIATOR GRILLE  |                | 8.40  |
| B030      | R + R RADIATOR GRILLE   |                | 8.40  |
| B040      | R + R HEADLAMPS<br>(BUMPER REMOVED)<br>INCLUDES: ADJUST HEADLAMPS         |                | 16.80 |
| 530051    | RENEW BONNET<br>INCLUDES: ASS ATTACHED PARTS AND IF NECE<br>RENEW         |                | 12.60 |
| B080      | R + R BONNET HINGE/S  |                | 4.20  |
| B125      | RENEW FRONT LOCK CARRIER  |                | 21.00 |
| NO NUMBER | RENEW L/F SIDEMEMBER REINFORCEMENT  |                | 33.60 |
| NO NUMBER | RENEW R/F SIDEMEMBER REINFORCEMENT  |                | 33.60 |
| 752051    | R + R L/DOOR MIRROR   | 3.0            | 12.60 |
| M010      | DRAIN AIR CONDITIONING  | 4.0            | 16.80 |

| Code                             | Description   | WU           | Price SGD     |
|----------------------------------|---|--------------|---------------|
| M010                             | RENEW RADIATOR AND CONDENSER<br>(FRONT BUMPER REMOVED)<br>INCLUDES: INTERCOOLER, ELECTRIC FAN<br>CPL AND REQUIRD ATTACHED PARTS<br>REMOVE AND REFIT.<br>COOLING SYSTEM REFILL AND<br>BLEED. | 22.0         | 92.40         |
| 463011)                          | R + R BRAKE POWER REGULATOR   | 4.0          | 16.80         |
| 171021)                          | R + R AIR FILTER CPL  | 1.0          | 4.20          |
| M150)                            | RENEW CHARGE AIR COOLER (REMOVED)   | 1.0          | 4.20          |
| 004466)                          | VENT L/F BRAKE SYSTEM   | 2.0          | 8.40          |
| 004466)                          | VENT R/F BRAKE SYSTEM   | 2.0          | 8.40          |
| 004466)                          | VENT L/R BRAKE SYSTEM   | 2.0          | 8.40          |
| 004466)                          | VENT R/R BRAKE SYSTEM   | 2.0          | 8.40          |
| 1201                             | L/F SIDE MEMBER CPL REPAIR  | 20.0*        | 7 84.00       |
| 1202                             | R/F SIDE MEMBER CPL REPAIR  | 20.0*        | 7 84.00       |
| <b>Labour Cost</b>               |   | <b>Hrs</b>   | <b>WU</b>     |
| <b>Panel / Mechanical Labour</b> |   | <b>12.80</b> | <b>128.0</b>  |
| <b>Total of Labour</b>           |   |              | <b>537.60</b> |

## Paint

| Paint Work | SYSTEM AZT                        | Time Basis 10 WU/h |
|------------|-----------------------------------|--------------------|
| Code       | Description - TWO COAT METALLIC   | WU Price SGD       |
|            | BONNET NEW PART PAINTING          | 18.0               |
|            | CTR FRT PANEL STRUT SURFACE PAINT | 4.0                |
|            | FRT LOCK CARRIER SURFACE PAINT    | 4.0                |
|            | L/F SIDE MEMBER CPL SURFACE PAINT | 4.0                |
|            | R/F SIDE MEMBER CPL SURFACE PAINT | 4.0                |
|            | LEFT FRONT DOOR SURFACE PAINT     | 8.0                |
|            | RIGHT FRONT DOOR SURFACE PAINT    | 8.0                |

## Paint Material Per Part

| Code | Description                       | Price SGD |
|------|-----------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING          | 52.12     |
| 0988 | CTR FRT PANEL STRUT SURFACE PAINT | 2.74      |
| 1017 | FRT LOCK CARRIER SURFACE PAINT    | 3.74      |
| 1201 | L/F SIDE MEMBER CPL SURFACE PAINT | 2.49      |
| 1202 | R/F SIDE MEMBER CPL SURFACE PAINT | 2.49      |
| 1481 | LEFT FRONT DOOR SURFACE PAINT     | 23.66     |
| 1482 | RIGHT FRONT DOOR SURFACE PAINT    | 23.66     |

## Labour Cost - Paint

| Factor                      | 42.00 SGD/h    | Hrs         | WU          | Price SGD     |
|-----------------------------|----------------|-------------|-------------|---------------|
| Time Paint                  |                |             | 50.0        |               |
| Preparation Main Work Metal |                | 2.50        | 25.0        | 105.00        |
| <b>Total</b>                | <b>10 WU/h</b> | <b>7.50</b> | <b>75.0</b> | <b>315.00</b> |

# Material Cost - Paint

|                                     |               |
|-------------------------------------|---------------|
| New Part Painting                   | 52.12         |
| Surface-/Blend Paint                | 58.78         |
| Material-constant Metal Preparation | 28.60         |
| <b>Total</b>                        | <b>139.50</b> |

|                  |
|------------------|
| <b>Price SGD</b> |
| 52.12            |
| 58.78            |
| 28.60            |
| 139.50           |

## Spare Parts

|      |                         |             |          | prices as at 2015-06-01/01 | Price SGD |
|------|-------------------------|-------------|----------|----------------------------|-----------|
| Code | Description             | Part Number | Supplier |                            |           |
| 0253 | L/F BMPR BLANK CAP      | 53113 26060 |          | MIT                        | 110.00 ✓  |
| 0281 | FRONT BUMPER            | 52119 26650 |          | BT/LM                      | 240.00 ✓  |
| 0293 | L/F BUMPER COVER        | 52127 26120 |          | MIT                        | 25.00 ✓   |
| 0331 | FRT BUMPER SUPPORT      | 52131 26020 |          | BT                         | 120.00 ✓  |
| 0410 | LWR RADIATOR GRILLE     | 53111 26510 |          | MIT                        | 260.00 ✓  |
| 0411 | UPP RADIATOR GRILLE     | 53111 26500 |          | MIT                        | 160.00 ✓  |
| 0413 | GRILLE BACKING          | 53112 26090 |          | MIT                        | 230.00 ✓  |
| 0431 | GRILLE BADGE            | 90975 02086 |          | MIT                        | 85.00 ✓   |
| 0471 | BONNET                  | 53301 26080 |          | BT                         | 280.00 ✓  |
| 0475 | LEFT BONNET HINGE       | 53420 26040 |          | BT                         | 40.00 ✓   |
| 0476 | RIGHT BONNET HINGE      | 53410 26040 |          | BT                         | 40.00 ✓   |
| 0493 | BONNET LOCK             | 53510 26060 |          | JM                         | 60.00 ✓   |
| 0561 | LEFT HEADLAMP ASSY      | 81170 26731 |          | MIT BT                     | 385.00 ✓  |
| 0562 | RIGHT HEADLAMP ASSY     | 81130 26731 |          | MIT                        | 385.00 ✓  |
| 0988 | CTR FRT PANEL STRUT     | 53209 26100 |          | BT                         | 180.00 ✓  |
| 1017 | FRT LOCK CARRIER        | 53205 26012 |          | BT                         | 165.00 ✓  |
| 1185 | L/RADIATOR BRACKET      | 53212 26080 |          |                            | 95.00 ?   |
| 1186 | R/RADIATOR BRACKET      | 53211 26080 |          |                            | 95.00 ?   |
| 1327 | L/F S-MEMBER REINF      | 57017 26010 |          |                            | 95.00 ?   |
| 1328 | R/F S-MEMBER REINF      | 57016 26010 |          |                            | 95.00 ?   |
| 1436 | WASHER CONTAINER        | 85315 26110 |          |                            | 55.00 ?   |
| 1737 | L/DOOR MIRROR           | 87940 26681 |          | SM                         | 160.00 X  |
| 4465 | CONDENSER               | 88450 26120 |          | BT/PM                      | 490.00 ✓  |
| 4483 | CONDENSER TUBE          | 88715 26390 |          |                            | 280.00 ?  |
| 4487 | EVAPORATOR/COND<br>PIPE | 88710 2F631 |          |                            | 240.00 ?  |
| 7505 | BRAKE POWER CONTROL     | 44610 26711 |          |                            | 480.00 ?  |
| 7515 | BRAKE MASTER CYL        | 47207 26010 |          |                            | 230.00 ?  |
| 7753 | L/RADIATOR AIR GUIDE    | 16594 75011 |          | CM                         | 65.00 ✓   |
| 7754 | R/RADIATOR AIR GUIDE    | 16593 75012 |          | CM                         | 65.00 ✓   |
| 7761 | RADIATOR                | 16400 30163 |          |                            | 680.00 ?  |
| 7767 | FAN HOUSING             | 16712 75122 |          |                            | 130.00 ?  |
| 7768 | FAN SHROUD              | 16711 30081 |          |                            | 130.00 ?  |
| 7789 | L/FAN MOTOR             | 16363 30041 |          |                            | 380.00 ?  |
| 7790 | R/FAN MOTOR             | 16363 30041 |          |                            | 380.00 ?  |
| 7793 | L/BLOWER FAN            | 16361 30050 |          |                            | 90.00 ?   |
| 7794 | R/BLOWER FAN            | 16361 30060 |          |                            | 90.00 ?   |
| 8391 | AIR FILTER ASSY         | 17700 30281 |          |                            | 330.00 ?  |
| 8401 | SUSPENS INTAKE HOSE     | 17750 30040 |          |                            | 0.00 ?    |
| 8405 | EXPANSION TANK          | 16470 75123 |          |                            | 95.00 ?   |
| 8739 | HEAT EXCHANGER          | 17940 30050 |          |                            | 550.00 ?  |
| 1000 | INTERCOOLER COVER       | INTERCOOLER |          |                            | 95.00 ?   |
| 1001 | INTERCOOLER RUBBER      | INTERCOOLER |          |                            | 0.00 ?    |

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

**Savings**  
**Subtotal**

**0.00**  
**8,160.00**

**Total****8,160.00****Extras**

| Code                | Description                     | Price SGD     |
|---------------------|---------------------------------|---------------|
| 1002                | Electrical work Electrical work | 20l 40.00*    |
| 1003                | Engine coolant Engine coolant   | 20l 30.00*    |
| 1004                | Air con coolant Air con         | 30l 50.00*    |
| 1005                | Front number plate Number Plate | Pl 35.00*     |
| 1006                | BRAKE OIL BRAKE                 | nu 30.00*     |
| <b>Total Extras</b> |                                 | <b>185.00</b> |

**Final Calculation**

|                                       | SGD      | SGD             |
|---------------------------------------|----------|-----------------|
| <b>Parts</b>                          | 8,160.00 |                 |
| <b>Total Parts</b>                    |          | <b>8,160.00</b> |
| <b>Labour Time Base 10 WU/h</b>       |          |                 |
| Total 128.0 WU X 42.00 SGD/h          | 537.60   |                 |
| <b>Total of Labour</b>                |          | <b>537.60</b>   |
| <b>Total Of Extras</b>                |          | <b>185.00</b>   |
| <b>Paint Work Time Base 10 WU/h</b>   |          |                 |
| Labour Cost 75.0 WU X 42.00 SGD/h     | 315.00   |                 |
| Material Cost                         | 139.50   |                 |
| <b>Total Paint Including Material</b> |          | <b>454.50</b>   |
| <b>Repair Cost Excludes GST</b>       |          | <b>9,337.10</b> |
| GST (+7.0%)                           |          | <b>653.60</b>   |
| <b>Repair Cost Included GST</b>       |          | <b>9,990.70</b> |

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

**Assessment Note**

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Business                             |
| Owner ID:                           | 610J                                 |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | PC2630M                              |
| Vehicle to be Exported:             | Yes                                  |
| Intended Deregistration Date:       | 03 Jan 2020                          |
| Vehicle Make:                       | TOYOTA                               |
| Vehicle Model:                      | HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB |
| Primary Colour:                     | Silver                               |
| Manufacturing Year:                 | 2014                                 |
| Engine No.:                         | 1KD2396426                           |
| Chassis No.:                        | KDH2230019876                        |
| Maximum Power Output:               | -                                    |
| Open Market Value:                  | \$36,716.00                          |
| Original Registration Date:         | 30 Jun 2014                          |
| First Registration Date:            | 30 Jun 2014                          |
| Transfer Count:                     | 1                                    |
| Actual ARF Paid:                    | \$1,836.00                           |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | No                                   |
| PARF Eligibility Expiry Date:       | -                                    |
| PARF Rebate Amount:                 | \$0.00                               |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 29 Jun 2024                          |
| COE Category:                       | C - Goods Vehicle & Bus              |
| COE Period(Years):                  | 10                                   |
| PQP Paid:                           | \$28,070.00                          |
| COE Rebate Amount:                  | \$12,990.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$12,990.00</b>                   |

The information contained herein is correct as at 03 Jan 2020

OK

**S&H Motor Pte Ltd**  
**160 Sin Ming Drive #07-02**  
**Sin Ming Autocity**  
**Singapore 575722**

**Insurer Reference:**  
**Repairer Reference: 026051**  
**Date calculated: 06/01/2020 2:48 PM**

**Full Report**  
**Registration: PC2630M**  
**Printed: 06/01/2020 2:49 PM**

### Summary Information

|                               |                |                          |   |
|-------------------------------|----------------|--------------------------|---|
| <b>Claim Location:</b>        | Singapore (SG) | <b>Work Provider:</b>    | China Taiping Insurance (Singapore) Pte Ltd |
| <b>Printed by:</b>            | SH Motor       | <b>Currency:</b>         | SGD   |
| <b>Claim Reference:</b>       |                | <b>Date of Incident:</b> | 02/01/20                                    |
| <b>Estimated Repair Time:</b> |                | <b>Hire Car Start:</b>   |   |
| <b>Actual Repair Days:</b>    |                | <b>Hire Car End:</b>     |   |

### Vehicle Details

|                            |                    |                          |                            |
|----------------------------|--------------------|--------------------------|----------------------------|
| <b>Vehicle</b>             |                    |                          |                            |
| <b>Manufacturer:</b>       | TOYOTA             |                          |                            |
| <b>Model:</b>              | HIACE              |                          |                            |
| <b>Sub Model:</b>          | COMMUTER BUS       |                          |                            |
| <b>Model Sheet Number:</b> | 70 E4 05           |                          |                            |
| <b>Registration:</b>       | PC2630M            |                          |                            |
| <b>VIN number:</b>         |                    |                          |                            |
| <b>Odometer:</b>           |                    |                          |                            |
| <b>Model Specs</b>         |                    |                          |                            |
| <b>FRT + REAR AIR CON</b>  | 3.0 LTR 100/106 KW | <b>TWO COAT METALLIC</b> | <b>PREPARE OFF VEHICLE</b> |

*Not Notched*  
*Repair 84 points*  
*Ex 81500h*  
*6 days No car parts*  
*Fax: 62564313*

### Labour

| Code      | Description                              | Time Base 10 WU/h | Price = 42.00 SGD/h |           |
|-----------|--|-------------------|---------------------|-----------|
|           |  |                   | WU                  | Price SGD |
| B091      | R + R LEFT FRONT WING                    |                   | 1.0                 | 4.20      |
| B091      | R + R RIGHT FRONT WING                   |                   | 1.0                 | 4.20      |
| B020)     | RENEW FRONT BUMPER REINFORCEMENT         |                   | 3.0                 | 12.60     |
| B020      | RENEW FRONT BUMPER (BUMPER REMOVED)      |                   | 7.0                 | 29.40     |
|           | INCLUDES: R + R FRONT FOG LAMPS          |                   |                     |           |
| NO NUMBER | R + R CENTRE LOWER RADIATOR GRILLE       |                   | 2.0                 | 8.40      |
| B030      | R + R RADIATOR GRILLE                    |                   | 2.0                 | 8.40      |
| B040      | R + R HEADLAMPS (BUMPER REMOVED)         |                   | 4.0                 | 16.80     |
|           | INCLUDES: ADJUST HEADLAMPS               |                   |                     |           |
| 530051    | RENEW BONNET                             |                   | 3.0                 | 12.60     |
|           | INCLUDES: ASS ATTACHED PARTS AND IF NECE |                   |                     |           |
|           | RENEW                                    |                   |                     |           |
| B080      | R + R BONNET HINGE/S                     |                   | 1.0                 | 4.20      |
| B125      | RENEW FRONT LOCK CARRIER                 |                   | 5.0                 | 21.00     |
| NO NUMBER | RENEW L/F SIDEMEMBER REINFORCEMENT       |                   | 8.0                 | 33.60     |
| NO NUMBER | RENEW R/F SIDEMEMBER REINFORCEMENT       |                   | 8.0                 | 33.60     |
| 752051    | R + R L/OOOF MIRROR                      |                   | 3.0                 | 12.60     |
| M010      | DRAIN AIR CONDITIONING                   |                   | 4.0                 | 16.80     |



| Code                             | Description   | WU         | Price SGD |
|----------------------------------|---|------------|-----------|
| M010                             | RENEW RADIATOR AND CONDENSER<br>(FRONT BUMPER REMOVED)<br>INCLUDES INTERCOOLER, ELECTRIC FAN<br>CPL AND REQUIRED ATTACHED PARTS<br>REMOVE AND REFIT.<br>COOLING SYSTEM REFILL AND<br>BLEED. | 22.0       | 92.40     |
| 463011)                          | R + R BRAKE POWER REGULATOR   | 4.0        | 16.80     |
| 171021)                          | R + R AIR FILTER CPL  | 1.0        | 4.20      |
| M150)                            | RENEW CHARGE AIR COOLER (REMOVED)   | 1.0        | 4.20      |
| 004466)                          | VENT L/F BRAKE SYSTEM   | 2.0        | 8.40      |
| 004466)                          | VENT R/F BRAKE SYSTEM   | 2.0        | 8.40      |
| 004466)                          | VENT L/R BRAKE SYSTEM   | 2.0        | 8.40      |
| 004466)                          | VENT R/R BRAKE SYSTEM   | 2.0        | 8.40      |
| 1201                             | L/F SIDE MEMBER CPL REPAIR  | 20.0*      | 84.00     |
| 1202                             | R/F SIDE MEMBER CPL REPAIR  | 20.0*      | 84.00     |
| <b>Labour Cost</b>               |   | <b>Hrs</b> | <b>WU</b> |
| <b>Panel / Mechanical Labour</b> |   | 12.80      | 128.0     |
| <b>Total of Labour</b>           |   |            | 537.60    |
|                                  |   |            | 537.60    |

**Paint**

| Code | Description - TWO COAT METALLIC   | WU   | Price SGD |
|------|-----------------------------------|------|-----------|
|      | BONNET NEW PART PAINTING          | 18.0 |           |
|      | CTR FRT PANEL STRUT SURFACE PAINT | 4.0  |           |
|      | FRT LOCK CARRIER SURFACE PAINT    | 4.0  |           |
|      | L/F SIDE MEMBER CPL SURFACE PAINT | 4.0  |           |
|      | R/F SIDE MEMBER CPL SURFACE PAINT | 4.0  |           |
|      | LEFT FRONT DOOR SURFACE PAINT     | 8.0  |           |
|      | RIGHT FRONT DOOR SURFACE PAINT    | 8.0  |           |

**Paint Material Per Part**

| Code | Description                       | Price SGD |
|------|-----------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING          | 52.12     |
| 0988 | CTR FRT PANEL STRUT SURFACE PAINT | 2.74      |
| 1017 | FRT LOCK CARRIER SURFACE PAINT    | 3.74      |
| 1201 | L/F SIDE MEMBER CPL SURFACE PAINT | 2.49      |
| 1202 | R/F SIDE MEMBER CPL SURFACE PAINT | 2.49      |
| 1481 | LEFT FRONT DOOR SURFACE PAINT     | 23.66     |
| 1482 | RIGHT FRONT DOOR SURFACE PAINT    | 23.66     |

**Labour Cost - Paint**

|                             | Hrs  | WU   | Price SGD |
|-----------------------------|------|------|-----------|
| Factor                      |      | 50.0 |           |
| Time Paint                  | 2.50 | 25.0 | 105.00    |
| Preparation Main Work Metal | 7.50 | 75.0 | 315.00    |
| <b>Total</b>                |      |      |           |

42.00 SGD/h

10 WU/h



**Material Cost - Paint**

|                                      |               |
|--------------------------------------|---------------|
| New Part Painting                    | 52.12         |
| Surface-/Blend Paint                 | 58.78         |
| Material-constant: Metal Preparation | 28.60         |
| <b>Total</b>                         | <b>139.50</b> |

Price SGD

52.12

58.78

28.60

139.50

**Spare Parts**

prices as at 2015-06-01/01

| Code | Description             | Part Number | Supplier | Price SGD |
|------|-------------------------|-------------|----------|-----------|
| 3253 | L/F BUMPR BLANK CAP     | 53113 26060 |          | 110.00    |
| 3281 | FRONT BUMPER            | 52119 26650 |          | 240.00    |
| 3293 | L/F BUMPER COVER        | 52127 26120 |          | 25.00     |
| 3331 | FRT BUMPER SUPPORT      | 52131 26020 |          | 120.00    |
| 3410 | LWR RADIATOR GRILLE     | 53111 26510 |          | 260.00    |
| 3411 | UPP RADIATOR GRILLE     | 53111 26500 |          | 160.00    |
| 3413 | GRILLE BACKING          | 53112 26090 |          | 230.00    |
| 3431 | GRILLE BADGE            | 90975 02086 |          | 85.00     |
| 3471 | BONNET                  | 53301 26080 |          | 280.00    |
| 3475 | LEFT BONNET HINGE       | 53420 26040 |          | 40.00     |
| 3476 | RIGHT BONNET HINGE      | 53410 26040 |          | 40.00     |
| 3493 | BONNET LOCK             | 53510 26060 |          | 60.00     |
| 3561 | LEFT HEADLAMP ASSY      | 81170 26731 |          | 385.00    |
| 3562 | RIGHT HEADLAMP ASSY     | 81130 26731 |          | 385.00    |
| 3988 | CTR FRT PANEL STRUT     | 53209 26100 |          | 180.00    |
| 4017 | FRT LOCK CARRIER        | 53205 26012 |          | 165.00    |
| 4185 | L/RADIATOR BRACKET      | 53212 26080 |          | 95.00     |
| 4186 | R/RADIATOR BRACKET      | 53211 26080 |          | 95.00     |
| 4327 | L/F S-MEMBER REINF      | 57017 26010 |          | 95.00     |
| 4328 | R/F S-MEMBER REINF      | 57016 26010 |          | 95.00     |
| 4436 | WASHER CONTAINER        | 85315 26110 |          | 55.00     |
| 4737 | L/DOOR MIRROR           | 87940 26681 |          | 160.00    |
| 4465 | CONDENSER               | 88450 26120 |          | 490.00    |
| 4483 | CONDENSER TUBE          | 88715 26390 |          | 280.00    |
| 4487 | EVAPORATOR/COND<br>PIPE | 88710 2F631 |          | 240.00    |
| 7505 | BRAKE POWER CONTROL     | 44610 26711 |          | 480.00    |
| 7515 | BRAKE MASTER CYL        | 47207 26010 |          | 230.00    |
| 7753 | L/RADIATOR AIR GUIDE    | 16594 75011 |          | 65.00     |
| 7754 | R/RADIATOR AIR GUIDE    | 16593 75012 |          | 65.00     |
| 7761 | RADIATOR                | 16400 30163 |          | 680.00    |
| 7767 | FAN HOUSING             | 16712 75122 |          | 130.00    |
| 7768 | FAN SHROUD              | 16711 30081 |          | 130.00    |
| 7789 | L/FAN MOTOR             | 16363 30041 |          | 380.00    |
| 7790 | R/FAN MOTOR             | 16363 30041 |          | 380.00    |
| 7793 | L/BLOWER FAN            | 16361 30050 |          | 90.00     |
| 7794 | R/BLOWER FAN            | 16361 30060 |          | 90.00     |
| 3391 | AIR FILTER ASSY         | 17700 30281 |          | 330.00    |
| 3401 | SUSPENS INTAKE HOSE     | 17750 30040 |          | 0.00      |
| 3405 | EXPANSION TANK          | 16470 75123 |          | 95.00     |
| 3739 | HEAT EXCHANGER          | 17940 30050 |          | 550.00    |
| 1000 | INTERCOOLER COVER       | INTERCOOLER |          | 95.00     |
| 1001 | INTERCOOLER RUBBER      | INTERCOOLER |          | 0.00      |

0: OEM Parts  
1: Non-OEM Parts  
2: Used parts

**Savings**  
**Subtotal**

0.00  
8,160.00

**Total** **8,160.0**

| <b>Extras</b>       |                                 | <b>Price SG</b> |
|---------------------|---------------------------------|-----------------|
| <b>Code</b>         | <b>Description</b>              |                 |
| 1002                | Electrical work Electrical work | 2ol 40.00       |
| 1003                | Engine coolant Engine coolant   | 2ol 30.00       |
| 1004                | Air con. coolant Air con.       | 3ol 50.00       |
| 1005                | Front number plate Number Plate | Per 35.00       |
| 1006                | BRAKE OIL BRAKE                 | Per 30.00       |
| <b>Total Extras</b> |                                 | <b>185.0</b>    |

**Final Calculation**

|                                       | <b>SGD</b> | <b>SG</b>      |
|---------------------------------------|------------|----------------|
| <b>Parts</b>                          | 8,160.00   |                |
| <b>Total Parts</b>                    |            | <b>8,160.0</b> |
| <b>Labour Time Base 10 WU/h</b>       |            |                |
| Total 128.0 WU X 42.00 SGD/h          | 537.60     |                |
| <b>Total of Labour</b>                |            | <b>537.6</b>   |
| <b>Total Of Extras</b>                |            | <b>185.0</b>   |
| <b>Paint Work Time Base 10 WU/h</b>   |            |                |
| Labour Cost 75.0 WU X 42.00 SGD/h     | 315.00     |                |
| Material Cost                         | 139.50     |                |
| <b>Total Paint Including Material</b> |            | <b>454.5</b>   |
| <b>Repair Cost Excludes GST</b>       |            | <b>9,337.1</b> |
| GST (+7.0%)                           |            | <b>653.6</b>   |
| <b>Repair Cost Included GST</b>       |            | <b>9,990.7</b> |

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

**Assessment Note**

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

**Insurer Reference:**  
**Repairer Reference: 026051**  
**Date calculated: 07/01/2020 3:04 PM**

**Full Report**  
**Registration: PC2630M**  
**Printed: 07/01/2020 3:12 PM**

### Summary Information

|                        |                |                   |   |
|------------------------|----------------|-------------------|---|
| <b>Claim</b>           |                |                   |   |
| Location:              | Singapore (SG) | Work Provider:    | China Taiping Insurance (Singapore) Pte Ltd |
| Printed by:            | KK LAU         | Currency:         | SGD   |
| Claim Reference:       |                | Date of Incident: | 02/01/20                                    |
| Estimated Repair Time: |                | Hire Car Start:   |   |
| Actual Repair Days:    |                | Hire Car End:     |   |

### Vehicle Details


|                     |                    |                   |                     |
|---------------------|--------------------|-------------------|---------------------|
| <b>Vehicle</b>      |                    |                   |                     |
| Manufacturer:       | TOYOTA             |                   |                     |
| Model:              | HIACE              |                   |                     |
| Sub Model:          | COMMUTER BUS       |                   |                     |
| Model Sheet Number: | 70 E4 05           |                   |                     |
| Registration:       | PC2630M            |                   |                     |
| VIN number:         |                    |                   |                     |
| Odometer:           |                    |                   |                     |
| <b>Model Specs</b>  |                    |                   |                     |
| FRT + REAR AIR CON  | 3.0 LTR 100/106 KW | TWO COAT METALLIC | PREPARE OFF VEHICLE |

### Vehicle Condition

**Vehicle Status**  
Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

**All** ☐  
**Underbody** ☐



# Labour

| Code                             | Description  | Time Base 10 WU/h | Price = 42.00 SGD/h |               |
|----------------------------------|--|-------------------|---------------------|---------------|
|                                  |  |                   | WU                  | Price SGD     |
| B091                             | R + R LEFT FRONT WING                                |                   | 1.0                 | 4.20          |
| B091                             | R + R RIGHT FRONT WING                               |                   | 1.0                 | 4.20          |
| B020)                            | RENEW FRONT BUMPER REINFORCEMENT                     |                   | 3.0                 | 12.60         |
| B020                             | RENEW FRONT BUMPER<br>(BUMPER REMOVED)               |                   | 7.0                 | 29.40         |
|                                  | INCLUDES: R + R FRONT FOG LAMPS                      |                   |                     |               |
| NO NUMBER                        | R + R CENTRE LOWER RADIATOR GRILLE                   |                   | 2.0                 | 8.40          |
| B030                             | R + R RADIATOR GRILLE                                |                   | 2.0                 | 8.40          |
| B040                             | R + R HEADLAMPS<br>(BUMPER REMOVED)                  |                   | 4.0                 | 16.80         |
|                                  | INCLUDES: ADJUST HEADLAMPS                           |                   |                     |               |
| 530051                           | RENEW BONNET   |                   | 3.0                 | 12.60         |
|                                  | INCLUDES: ASS ATTACHED PARTS AND IF NECE             |                   |                     |               |
|                                  | RENEW  |                   |                     |               |
| B080                             | R + R BONNET HINGE/S                                 |                   | 1.0                 | 4.20          |
| B125                             | RENEW FRONT LOCK CARRIER                             |                   | 5.0                 | 21.00         |
| M010                             | R + R AIR CONDITIONING CONDENSER<br>(BUMPER REMOVED) |                   | 20.0                | 84.00         |
|                                  | INCLUDES: FILL AIR CONDITIONING                      |                   |                     |               |
| NO NUMBER                        | R + R AIR INLET HOSE                                 |                   | 2.0                 | 8.40          |
| 1185                             | L/RADIATOR BRACKET CHECK                             |                   |                     |               |
| 1186                             | R/RADIATOR BRACKET CHECK                             |                   |                     |               |
| 1201                             | L/F SIDE MEMBER CPL CHECK                            |                   |                     |               |
| 1202                             | R/F SIDE MEMBER CPL CHECK                            |                   |                     |               |
| 1327                             | L/F S-MEMBER REINF CHECK                             |                   |                     |               |
| 1328                             | R/F S-MEMBER REINF CHECK                             |                   |                     |               |
| 1436                             | WASHER CONTAINER CHECK                               |                   |                     |               |
| 4483                             | CONDENSER TUBE CHECK                                 |                   |                     |               |
| 4487                             | EVAPORATOR/COND PIPE CHECK                           |                   |                     |               |
| 7505                             | BRAKE POWER CONTROL CHECK                            |                   |                     |               |
| 7515                             | BRAKE MASTER CYL CHECK                               |                   |                     |               |
| 7761                             | RADIATOR CHECK                                       |                   |                     |               |
| 7767                             | FAN HOUSING CHECK                                    |                   |                     |               |
| 7768                             | FAN SHROUD CHECK                                     |                   |                     |               |
| 7789                             | L/FAN MOTOR CHECK                                    |                   |                     |               |
| 7790                             | R/FAN MOTOR CHECK                                    |                   |                     |               |
| 7793                             | L/BLOWER FAN CHECK                                   |                   |                     |               |
| 7794                             | R/BLOWER FAN CHECK                                   |                   |                     |               |
| 8391                             | AIR FILTER ASSY CHECK                                |                   |                     |               |
| 8401                             | SUSPENS INTAKE HOSE CHECK                            |                   |                     |               |
| 8405                             | EXPANSION TANK CHECK                                 |                   |                     |               |
| 8739                             | HEAT EXCHANGER CHECK                                 |                   |                     |               |
| 1000                             | INTERCOOLER COVER CHECK                              |                   |                     | 95.00*        |
| 1001                             | INTERCOOLER RUBBER CHECK                             |                   |                     |               |
| <b>Labour Cost</b>               |  | <b>Hrs</b>        | <b>WU</b>           |               |
| <b>Panel / Mechanical Labour</b> |  | <b>5.10</b>       | <b>51.0</b>         | <b>214.20</b> |
| <b>Fixed Rate</b>                |  |                   |                     | <b>95.00</b>  |
| <b>Total of Labour</b>           |  |                   |                     | <b>309.20</b> |

**Paint**

| Paint Work |                                   | SYSTEM AZT | Time Basis 10 WU/h |           |
|------------|-----------------------------------|------------|--------------------|-----------|
| Code       | Description - TWO COAT METALLIC   |            | WU                 | Price SGD |
|            | BONNET NEW PART PAINTING          |            | 18.0               |           |
|            | CTR FRT PANEL STRUT SURFACE PAINT |            | 4.0                |           |
|            | FRT LOCK CARRIER SURFACE PAINT    |            | 4.0                |           |
|            | LEFT FRONT DOOR SURFACE PAINT     |            | 8.0                |           |
|            | RIGHT FRONT DOOR SURFACE PAINT    |            | 8.0                |           |

**Paint Material Per Part**

| Code | Description                       | Price SGD |
|------|-----------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING          | 52.12     |
| 0988 | CTR FRT PANEL STRUT SURFACE PAINT | 2.74      |
| 1017 | FRT LOCK CARRIER SURFACE PAINT    | 3.74      |
| 1481 | LEFT FRONT DOOR SURFACE PAINT     | 23.66     |
| 1482 | RIGHT FRONT DOOR SURFACE PAINT    | 23.66     |

**Labour Cost - Paint**

|                             | 42.00 SGD/h    | Hrs  | WU   | Price SGD |
|-----------------------------|----------------|------|------|-----------|
| Factor                      |                |      | 42.0 |           |
| Time Paint                  |                | 2.50 | 25.0 | 105.00    |
| Preparation Main Work Metal |                | 6.70 | 67.0 | 281.40    |
| <b>Total</b>                | <b>10 WU/h</b> |      |      |           |

**Material Cost - Paint**

|                                     | Price SGD     |
|-------------------------------------|---------------|
| New Part Painting                   | 52.12         |
| Surface-/Blend Paint                | 53.80         |
| Material-constant Metal Preparation | 28.60         |
| <b>Total</b>                        | <b>134.52</b> |

**Spare Parts**

|      |                     |             |          | prices as at 2015-06-01/01 |
|------|---------------------|-------------|----------|----------------------------|
| Code | Description         | Part Number | Supplier | Price SGD                  |
| 0253 | L/F BMPR BLANK CAP  | 53113 26060 |          | 110.00                     |
| 0281 | FRONT BUMPER        | 52119 26650 |          | 240.00                     |
| 0293 | L/F BUMPER COVER    | 52127 26120 |          | 25.00                      |
| 0331 | FRT BUMPER SUPPORT  | 52131 26020 |          | 120.00                     |
| 0410 | LWR RADIATOR GRILLE | 53111 26510 |          | 260.00                     |
| 0411 | UPP RADIATOR GRILLE | 53111 26500 |          | 160.00                     |
| 0413 | GRILLE BACKING      | 53112 26090 |          | 230.00                     |
| 0431 | GRILLE BADGE        | 90975 02086 |          | 85.00                      |
| 0471 | BONNET              | 53301 26080 |          | 280.00                     |
| 0475 | LEFT BONNET HINGE   | 53420 26040 |          | 40.00                      |
| 0476 | RIGHT BONNET HINGE  | 53410 26040 |          | 40.00                      |
| 0493 | BONNET LOCK         | 53510 26060 |          | 60.00                      |
| 0561 | LEFT HEADLAMP ASSY  | 81170 26731 |          | 385.00                     |
| 0562 | RIGHT HEADLAMP ASSY | 81130 26731 |          | 385.00                     |
| 0988 | CTR FRT PANEL STRUT | 53209 26100 |          | 180.00                     |
| 1017 | FRT LOCK CARRIER    | 53205 26012 |          | 165.00                     |

| Code             | Description          | Part Number | Supplier | Price SGD |
|------------------|----------------------|-------------|----------|-----------|
| 4465             | CONDENSER            | 88450 26120 |          | 490.00    |
| 7753             | L/RADIATOR AIR GUIDE | 16594 75011 |          | 65.00     |
| 7754             | R/RADIATOR AIR GUIDE | 16593 75012 |          | 65.00     |
| f: OEM Parts     |                      |             |          | 0.00      |
| n: Non-OEM Parts |                      |             |          | 3,385.00  |
| u: Used parts    |                      |             |          | 3,385.00  |
| <b>Savings</b>   |                      |             |          |           |
| <b>Subtotal</b>  |                      |             |          |           |
| <b>Total</b>     |                      |             |          |           |

### Extras

| Code                | Description                     | Price SGD     |
|---------------------|---------------------------------|---------------|
| 1002                | Electrical work Electrical work | 20.00*        |
| 1003                | Engine coolant Engine coolant   | 20.00*        |
| 1004                | Air con coolant Air con         | 30.00*        |
| 1005                | Front number plate Number Plate | 35.00*        |
| 1006                | BRAKE OIL BRAKE                 | 30.00*        |
| <b>Total Extras</b> |                                 | <b>135.00</b> |

### Final Calculation

|                                       | SGD      | SGD             |
|---------------------------------------|----------|-----------------|
| <b>Parts</b>                          | 3,385.00 |                 |
| <b>Total Parts</b>                    |          | <b>3,385.00</b> |
| <b>Labour Time Base 10 WU/h</b>       |          |                 |
| Total 51.0 WU X 42.00 SGD/h           | 214.20   |                 |
| Fixed Rate                            | 95.00    |                 |
| <b>Total of Labour</b>                |          | <b>309.20</b>   |
| <b>Total Of Extras</b>                |          | <b>135.00</b>   |
| <b>Paint Work Time Base 10 WU/h</b>   |          |                 |
| Labour Cost 67.0 WU X 42.00 SGD/h     | 281.40   |                 |
| Material Cost                         | 134.52   |                 |
| <b>Total Paint Including Material</b> |          | <b>415.92</b>   |
| <b>Repair Cost Excludes GST</b>       |          | <b>4,245.12</b> |
| GST (+7.0%)                           |          | 297.16          |
| <b>Repair Cost Included GST</b>       |          | <b>4,542.28</b> |

### Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.



## View Received Message

This mail is associated with :

**PC2630M (SNM20D200056/PC2630M/IRENE)**

OD

Jan 2 2020 6:00AM

[RIEZQI TRANSPORTATION]

S & H Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 08/01/2020 10:13 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$4245.12) - PC2630M - Claim Handler: Irene Tay Hui Ping

Approved:4245.12.

### DOCUMENTS SUMMARY

There are no documents.