

ASS. REC. BY:

REF: CS/CT1 20060361/khf3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tan Hui Ping of CT1 Date/Time: 7. Jan. 2020

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 2630M Insured:

at Workshop m/s S R H Motor Tel: 6453 4730

of 160 Sin Ming Drive # 07-02

Policy No: DMBSN 3076621800 Claim No: SNM 200200056 / PC2630M / Irene

Sum Insured: Excess: \$1500.00

Make of Veh: D.O.A. 2.1.2020

(Client's Record)

CA / REV REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 7.1.20 10.32a.m Person Contacted: Cynthia Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	PC 2630M - (C3/AXD 14014665/K1WY/392 R.02-20/07/2014
7/1 @ 15.26	mandate Request
8/1 @ 10.13	mandate Approval by Irene Tan
8/1 @ 11.19	inform Cynthia authorise part by part excess \$1500.

ASS. REC. BY:

REF: CT2 / CS / CT1 20000361 / Ktf3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.1B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/A / S/Rim / STD A/Rim or

Tyre Size:

F: Yoko

R: Journey

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS. \$

Fees:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jan 2020 Sendback Est	06 Jan 2020 15:25 \$9,337.10	07 Jan 2020 10:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	RIEZQI TRANSPORTATION, Co. Reg. No.: 53315610J			
Vehicle Reg. No.:	PC2630M	Date of Loss:	02/01/2020 06:00 - :59 [66 Months and 3 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / SNM20D200056/PC2630M/IRENE	Policy/Cover Note No.:	DMB1SN3076621800 (Comprehensive)	
		Excess:	S\$1,500.00	
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/01/2020]			
Driver/Custodian:	LIM CHIN KEONG (44 / Male) , NRIC: S7537906D, Tel: +6588963298 Email: NOEMAIL			
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT			

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	610J
Vehicle Details	
Vehicle No.:	PC2630M
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2396426
Chassis No.:	KDH2230019876
Maximum Power Output:	-
Open Market Value:	\$36,716.00
Original Registration Date:	30 Jun 2014
First Registration Date:	30 Jun 2014
Transfer Count:	1
Actual ARF Paid:	\$1,836.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$28,070.00
COE Rebate Amount:	\$12,958.00
Total Rebate Amount:	\$12,958.00

The information contained herein is correct as at 07 Jan 2020

OK

\$4216 (cost)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/01/2020 12:03
Date Of Accident	02/01/2020 06:45
Exact Location Of Accident	ALONG RD 1 OLD TAMPINES RD TO TANAH MERAH BESAR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2630M
Insured/Policyholder	
Name Of Registered Owner	RIEZQI TRANSPORTATION
Co Reg No	5XXXXX10J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88963298
Alternative Phone No	OFFICE-88963298

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMB1SN3076621800
Cover Note Number	

Driver

Name of Driver	LIM CHIN KEONG
NRIC No	SXXXX906D
Date Of Birth	22/12/1975
Occupation	OUTDOOR
Date Of Driving Pass	02/03/2004
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88963298
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBS9838S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


DETAILS OF INJURED PERSON 1

Name	
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	PC2630M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	PC2630M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN



A - PC 2630m
B - SB 98385

A → B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer attached police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20200102/2031

2 of 3

Report No. T/20200102/2031

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

CONTINUATION OF REPORT

Brief Details.

On 02/01/2020 at 6.48 am along Old Tampines Road, I was driving my company van (PC2630M) and there was one bus (SBS9838S) in-front of me. The bus braked but I could not brake in time causing the front of the van to hit onto the rear of the bus. Ambulance came and conveyed two of my passengers to Changi Hospital for medical treatment. Both of them were discharged and given 1 day and 2 days MC respectively. Traffic police came to the location and took the SD card from my in-car camera and told me to lodge a traffic police report.

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:

Repairer Reference: 026051

Date calculated: 06/01/2020 2:48 PM

Summary Information

Claim

Location: Singapore (SG)

Work Provider:

Printed by: SH Motor

Currency:

Claim Reference:

Date of Incident

Estimated Repair Time:

Hire Car Start:

Actual Repair Days:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer: TOYOTA
 Model: HIACE
 Sub Model: COMMUTER BUS
 Model Sheet Number: 70 E4 05
 Registration: PC2630M

VIN number:

Odometer:

Model Specs

FRT + REAR AIR CON 3.0 LTR 100/106 KW TWO

Labour

Code	Description	Time Base 10 W	
B091	R + R LEFT FRONT WING		20
B091	R + R RIGHT FRONT WING		20
B020)	RENEW FRONT BUMPER REINFORCEMENT		2.60
B020	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R FRONT FOG LAMPS		9.40
NO NUMBER	R + R CENTRE LOWER RADIATOR GRILLE		8.40
B030	R + R RADIATOR GRILLE		8.40
B040	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		16.80
530051	RENEW BONNET INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW		12.60
B080	R + R BONNET HINGE/S		4.20
B125	RENEW FRONT LOCK CARRIER		21.00
NO NUMBER	RENEW L/F SIDEMEMBER REINFORCEMENT		33.60
NO NUMBER	RENEW R/F SIDEMEMBER REINFORCEMENT		33.60
752051	R + R L/DOOR MIRROR	3.0	12.60
M010	DRAIN AIR CONDITIONING	4.0	16.80

Code	Description	WU	Price SGD
M010	RENEW RADIATOR AND CONDENSER (FRONT BUMPER REMOVED) INCLUDES: INTERCOOLER, ELECTRIC FAN CPL AND REQUIRD ATTACHED PARTS REMOVE AND REFIT. COOLING SYSTEM REFILL AND BLEED.	22.0	92.40
463011)	R + R BRAKE POWER REGULATOR	4.0	16.80
171021)	R + R AIR FILTER CPL	1.0	4.20
M150)	RENEW CHARGE AIR COOLER (REMOVED)	1.0	4.20
004466)	VENT L/F BRAKE SYSTEM	2.0	8.40
004466)	VENT R/F BRAKE SYSTEM	2.0	8.40
004466)	VENT L/R BRAKE SYSTEM	2.0	8.40
004466)	VENT R/R BRAKE SYSTEM	2.0	8.40
1201	L/F SIDE MEMBER CPL REPAIR	20.0*	7 84.00
1202	R/F SIDE MEMBER CPL REPAIR	20.0*	7 84.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		12.80	128.0
Total of Labour			537.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	18.0
	CTR FRT PANEL STRUT SURFACE PAINT	4.0
	FRT LOCK CARRIER SURFACE PAINT	4.0
	L/F SIDE MEMBER CPL SURFACE PAINT	4.0
	R/F SIDE MEMBER CPL SURFACE PAINT	4.0
	LEFT FRONT DOOR SURFACE PAINT	8.0
	RIGHT FRONT DOOR SURFACE PAINT	8.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	52.12
0988	CTR FRT PANEL STRUT SURFACE PAINT	2.74
1017	FRT LOCK CARRIER SURFACE PAINT	3.74
1201	L/F SIDE MEMBER CPL SURFACE PAINT	2.49
1202	R/F SIDE MEMBER CPL SURFACE PAINT	2.49
1481	LEFT FRONT DOOR SURFACE PAINT	23.66
1482	RIGHT FRONT DOOR SURFACE PAINT	23.66

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			50.0	
Preparation Main Work Metal		2.50	25.0	105.00
Total	10 WU/h	7.50	75.0	315.00

Material Cost - Paint

New Part Painting	52.12
Surface-/Blend Paint	58.78
Material-constant Metal Preparation	28.60
Total	139.50

Price SGD
52.12
58.78
28.60
139.50

Spare Parts

				prices as at 2015-06-01/01	Price SGD
Code	Description	Part Number	Supplier		
0253	L/F BMPR BLANK CAP	53113 26060		MIT	110.00 ✓
0281	FRONT BUMPER	52119 26650		BT/LM	240.00 ✓
0293	L/F BUMPER COVER	52127 26120		MIT	25.00 ✓
0331	FRT BUMPER SUPPORT	52131 26020		BT	120.00 ✓
0410	LWR RADIATOR GRILLE	53111 26510		MIT	260.00 ✓
0411	UPP RADIATOR GRILLE	53111 26500		MIT	160.00 ✓
0413	GRILLE BACKING	53112 26090		MIT	230.00 ✓
0431	GRILLE BADGE	90975 02086		MIT	85.00 ✓
0471	BONNET	53301 26080		BT	280.00 ✓
0475	LEFT BONNET HINGE	53420 26040		BT	40.00 ✓
0476	RIGHT BONNET HINGE	53410 26040		BT	40.00 ✓
0493	BONNET LOCK	53510 26060		JM	60.00 ✓
0561	LEFT HEADLAMP ASSY	81170 26731		MIT BT	385.00 ✓
0562	RIGHT HEADLAMP ASSY	81130 26731		MIT	385.00 ✓
0988	CTR FRT PANEL STRUT	53209 26100		BT	180.00 ✓
1017	FRT LOCK CARRIER	53205 26012		BT	165.00 ✓
1185	L/RADIATOR BRACKET	53212 26080			95.00 ?
1186	R/RADIATOR BRACKET	53211 26080			95.00 ?
1327	L/F S-MEMBER REINF	57017 26010			95.00 ?
1328	R/F S-MEMBER REINF	57016 26010			95.00 ?
1436	WASHER CONTAINER	85315 26110			55.00 ?
1737	L/DOOR MIRROR	87940 26681		SM	160.00 X
4465	CONDENSER	88450 26120		BT/PM	490.00 ✓
4483	CONDENSER TUBE	88715 26390			280.00 ?
4487	EVAPORATOR/COND PIPE	88710 2F631			240.00 ?
7505	BRAKE POWER CONTROL	44610 26711			480.00 ?
7515	BRAKE MASTER CYL	47207 26010			230.00 ?
7753	L/RADIATOR AIR GUIDE	16594 75011		CM	65.00 ✓
7754	R/RADIATOR AIR GUIDE	16593 75012		CM	65.00 ✓
7761	RADIATOR	16400 30163			680.00 ?
7767	FAN HOUSING	16712 75122			130.00 ?
7768	FAN SHROUD	16711 30081			130.00 ?
7789	L/FAN MOTOR	16363 30041			380.00 ?
7790	R/FAN MOTOR	16363 30041			380.00 ?
7793	L/BLOWER FAN	16361 30050			90.00 ?
7794	R/BLOWER FAN	16361 30060			90.00 ?
8391	AIR FILTER ASSY	17700 30281			330.00 ?
8401	SUSPENS INTAKE HOSE	17750 30040			0.00 ?
8405	EXPANSION TANK	16470 75123			95.00 ?
8739	HEAT EXCHANGER	17940 30050			550.00 ?
1000	INTERCOOLER COVER	INTERCOOLER			95.00 ?
1001	INTERCOOLER RUBBER	INTERCOOLER			0.00 ?

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal

0.00
8,160.00

Total**8,160.00****Extras**

Code	Description	Price SGD
1002	Electrical work Electrical work	20l 40.00*
1003	Engine coolant Engine coolant	20l 30.00*
1004	Air con coolant Air con	30l 50.00*
1005	Front number plate Number Plate	Pl 35.00*
1006	BRAKE OIL BRAKE	nu 30.00*
Total Extras		185.00

Final Calculation

	SGD	SGD
Parts	8,160.00	
Total Parts		8,160.00
Labour Time Base 10 WU/h		
Total 128.0 WU X 42.00 SGD/h	537.60	
Total of Labour		537.60
Total Of Extras		185.00
Paint Work Time Base 10 WU/h		
Labour Cost 75.0 WU X 42.00 SGD/h	315.00	
Material Cost	139.50	
Total Paint Including Material		454.50
Repair Cost Excludes GST		9,337.10
GST (+7.0%)		653.60
Repair Cost Included GST		9,990.70

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	610J
Vehicle Details	
Vehicle No.:	PC2630M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2396426
Chassis No.:	KDH2230019876
Maximum Power Output:	-
Open Market Value:	\$36,716.00
Original Registration Date:	30 Jun 2014
First Registration Date:	30 Jun 2014
Transfer Count:	1
Actual ARF Paid:	\$1,836.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$28,070.00
COE Rebate Amount:	\$12,990.00
Total Rebate Amount:	\$12,990.00

The information contained herein is correct as at 03 Jan 2020

OK

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 026051
Date calculated: 06/01/2020 2:48 PM

Full Report
Registration: PC2630M
Printed: 06/01/2020 2:49 PM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	02/01/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	HIACE		
Sub Model:	COMMUTER BUS		
Model Sheet Number:	70 E4 05		
Registration:	PC2630M		
VIN number:			
Odometer:			
Model Specs			
FRT + REAR AIR CON	3.0 LTR 100/106 KW	TWO COAT METALLIC	PREPARE OFF VEHICLE

Not Notched
Repair 84 points
Ex 81500h
6 days No new parts
Fax: 62564313

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B091	R + R LEFT FRONT WING		1.0	4.20
B091	R + R RIGHT FRONT WING		1.0	4.20
B020)	RENEW FRONT BUMPER REINFORCEMENT		3.0	12.60
B020	RENEW FRONT BUMPER (BUMPER REMOVED)		7.0	29.40
	INCLUDES: R + R FRONT FOG LAMPS			
NO NUMBER	R + R CENTRE LOWER RADIATOR GRILLE		2.0	8.40
B030	R + R RADIATOR GRILLE		2.0	8.40
B040	R + R HEADLAMPS (BUMPER REMOVED)		4.0	16.80
	INCLUDES: ADJUST HEADLAMPS			
530051	RENEW BONNET		3.0	12.60
	INCLUDES: ASS ATTACHED PARTS AND IF NEEDED			
	RENEW			
B080	R + R BONNET HINGE/S		1.0	4.20
B125	RENEW FRONT LOCK CARRIER		5.0	21.00
NO NUMBER	RENEW L/F SIDEMEMBER REINFORCEMENT		8.0	33.60
NO NUMBER	RENEW R/F SIDEMEMBER REINFORCEMENT		8.0	33.60
752051	R + R L/OOOF MIRROR		3.0	12.60
M010	DRAIN AIR CONDITIONING		4.0	16.80

Code	Description	WU	Price SGD
M010	RENEW RADIATOR AND CONDENSER (FRONT BUMPER REMOVED) INCLUDES INTERCOOLER, ELECTRIC FAN CPL AND REQUIRED ATTACHED PARTS REMOVE AND REFIT. COOLING SYSTEM REFILL AND BLEED.	22.0	92.40
463011)	R + R BRAKE POWER REGULATOR	4.0	16.80
171021)	R + R AIR FILTER CPL	1.0	4.20
M150)	RENEW CHARGE AIR COOLER (REMOVED)	1.0	4.20
004466)	VENT L/F BRAKE SYSTEM	2.0	8.40
004466)	VENT R/F BRAKE SYSTEM	2.0	8.40
004466)	VENT L/R BRAKE SYSTEM	2.0	8.40
004466)	VENT R/R BRAKE SYSTEM	2.0	8.40
1201	L/F SIDE MEMBER CPL REPAIR	20.0*	84.00
1202	R/F SIDE MEMBER CPL REPAIR	20.0*	84.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		12.80	128.0
Total of Labour			537.60
			537.60

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	18.0	
	CTR FRT PANEL STRUT SURFACE PAINT	4.0	
	FRT LOCK CARRIER SURFACE PAINT	4.0	
	L/F SIDE MEMBER CPL SURFACE PAINT	4.0	
	R/F SIDE MEMBER CPL SURFACE PAINT	4.0	
	LEFT FRONT DOOR SURFACE PAINT	8.0	
	RIGHT FRONT DOOR SURFACE PAINT	8.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	52.12
0988	CTR FRT PANEL STRUT SURFACE PAINT	2.74
1017	FRT LOCK CARRIER SURFACE PAINT	3.74
1201	L/F SIDE MEMBER CPL SURFACE PAINT	2.49
1202	R/F SIDE MEMBER CPL SURFACE PAINT	2.49
1481	LEFT FRONT DOOR SURFACE PAINT	23.66
1482	RIGHT FRONT DOOR SURFACE PAINT	23.66

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor		50.0	
Time Paint	2.50	25.0	105.00
Preparation Main Work Metal	7.50	75.0	315.00
Total			

42.00 SGD/h

10 WU/h

Material Cost - Paint

New Part Painting

Surface-/Blend Paint

Material-constant: Metal Preparation

Total**Price SGD**

52.12

58.78

28.60

139.50**Spare Parts**

prices as at 2015-06-01/01

Code	Description	Part Number	Supplier	Price SGD
3253	L/F BUMPR BLANK CAP	53113 26060		110.00
3281	FRONT BUMPER	52119 26650		240.00
3293	L/F BUMPER COVER	52127 26120		25.00
3331	FRT BUMPER SUPPORT	52131 26020		120.00
3410	LWR RADIATOR GRILLE	53111 26510		260.00
3411	UPP RADIATOR GRILLE	53111 26500		160.00
3413	GRILLE BACKING	53112 26090		230.00
3431	GRILLE BADGE	90975 02086		85.00
3471	BONNET	53301 26080		280.00
3475	LEFT BONNET HINGE	53420 26040		40.00
3476	RIGHT BONNET HINGE	53410 26040		40.00
3493	BONNET LOCK	53510 26060		60.00
3561	LEFT HEADLAMP ASSY	81170 26731		385.00
3562	RIGHT HEADLAMP ASSY	81130 26731		385.00
3988	CTR FRT PANEL STRUT	53209 26100		180.00
4017	FRT LOCK CARRIER	53205 26012		165.00
4185	L/RADIATOR BRACKET	53212 26080		95.00
4186	R/RADIATOR BRACKET	53211 26080		95.00
4327	L/F S-MEMBER REINF	57017 26010		95.00
4328	R/F S-MEMBER REINF	57016 26010		95.00
4436	WASHER CONTAINER	85315 26110		55.00
4737	L/DOOR MIRROR	87940 26681		160.00
4465	CONDENSER	88450 26120		490.00
4483	CONDENSER TUBE	88715 26390		280.00
4487	EVAPORATOR/COND PIPE	88710 2F631		240.00
7505	BRAKE POWER CONTROL	44610 26711		480.00
7515	BRAKE MASTER CYL	47207 26010		230.00
7753	L/RADIATOR AIR GUIDE	16594 75011		65.00
7754	R/RADIATOR AIR GUIDE	16593 75012		65.00
7761	RADIATOR	16400 30163		680.00
7767	FAN HOUSING	16712 75122		130.00
7768	FAN SHROUD	16711 30081		130.00
7789	L/FAN MOTOR	16363 30041		380.00
7790	R/FAN MOTOR	16363 30041		380.00
7793	L/BLOWER FAN	16361 30050		90.00
7794	R/BLOWER FAN	16361 30060		90.00
3391	AIR FILTER ASSY	17700 30281		330.00
3401	SUSPENS INTAKE HOSE	17750 30040		0.00
3405	EXPANSION TANK	16470 75123		95.00
3739	HEAT EXCHANGER	17940 30050		550.00
1000	INTERCOOLER COVER	INTERCOOLER		95.00
1001	INTERCOOLER RUBBER	INTERCOOLER		0.00

0: OEM Parts
 1: Non-OEM Parts
 2: Used parts

Savings
Subtotal

0.00
8,160.00

Total **8,160.0**

Extras		Price SG
Code	Description	
1002	Electrical work Electrical work	2ol 40.00
1003	Engine coolant Engine coolant	2ol 30.00
1004	Air con. coolant Air con.	3ol 50.00
1005	Front number plate Number Plate	Per 35.00
1006	BRAKE OIL BRAKE	Per 30.00
Total Extras		185.0

Final Calculation

	SGD	SG
Parts	8,160.00	
Total Parts		8,160.0
Labour Time Base 10 WU/h		
Total 128.0 WU X 42.00 SGD/h	537.60	
Total of Labour		537.6
Total Of Extras		185.0
Paint Work Time Base 10 WU/h		
Labour Cost 75.0 WU X 42.00 SGD/h	315.00	
Material Cost	139.50	
Total Paint Including Material		454.5
Repair Cost Excludes GST		9,337.1
GST (+7.0%)		653.6
Repair Cost Included GST		9,990.7

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: 026051
Date calculated: 07/01/2020 3:04 PM

Full Report
Registration: PC2630M
Printed: 07/01/2020 3:12 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	02/01/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle			
Manufacturer:	TOYOTA		
Model:	HIACE		
Sub Model:	COMMUTER BUS		
Model Sheet Number:	70 E4 05		
Registration:	PC2630M		
VIN number:			
Odometer:			
Model Specs			
FRT + REAR AIR CON	3.0 LTR 100/106 KW	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
B091	R + R LEFT FRONT WING		1.0	4.20
B091	R + R RIGHT FRONT WING		1.0	4.20
B020)	RENEW FRONT BUMPER REINFORCEMENT		3.0	12.60
B020	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R FRONT FOG LAMPS		7.0	29.40
NO NUMBER	R + R CENTRE LOWER RADIATOR GRILLE		2.0	8.40
B030	R + R RADIATOR GRILLE		2.0	8.40
B040	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS		4.0	16.80
530051	RENEW BONNET INCLUDES: ASS ATTACHED PARTS AND IF NECE RENEW		3.0	12.60
B080	R + R BONNET HINGE/S		1.0	4.20
B125	RENEW FRONT LOCK CARRIER		5.0	21.00
M010	R + R AIR CONDITIONING CONDENSER (BUMPER REMOVED) INCLUDES: FILL AIR CONDITIONING		20.0	84.00
NO NUMBER	R + R AIR INLET HOSE		2.0	8.40
1185	L/RADIATOR BRACKET CHECK			
1186	R/RADIATOR BRACKET CHECK			
1201	L/F SIDE MEMBER CPL CHECK			
1202	R/F SIDE MEMBER CPL CHECK			
1327	L/F S-MEMBER REINF CHECK			
1328	R/F S-MEMBER REINF CHECK			
1436	WASHER CONTAINER CHECK			
4483	CONDENSER TUBE CHECK			
4487	EVAPORATOR/COND PIPE CHECK			
7505	BRAKE POWER CONTROL CHECK			
7515	BRAKE MASTER CYL CHECK			
7761	RADIATOR CHECK			
7767	FAN HOUSING CHECK			
7768	FAN SHROUD CHECK			
7789	L/FAN MOTOR CHECK			
7790	R/FAN MOTOR CHECK			
7793	L/BLOWER FAN CHECK			
7794	R/BLOWER FAN CHECK			
8391	AIR FILTER ASSY CHECK			
8401	SUSPENS INTAKE HOSE CHECK			
8405	EXPANSION TANK CHECK			
8739	HEAT EXCHANGER CHECK			
1000	INTERCOOLER COVER CHECK			95.00*
1001	INTERCOOLER RUBBER CHECK			
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		5.10	51.0	214.20
Fixed Rate				95.00
Total of Labour				309.20

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	BONNET NEW PART PAINTING		18.0	
	CTR FRT PANEL STRUT SURFACE PAINT		4.0	
	FRT LOCK CARRIER SURFACE PAINT		4.0	
	LEFT FRONT DOOR SURFACE PAINT		8.0	
	RIGHT FRONT DOOR SURFACE PAINT		8.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	52.12
0988	CTR FRT PANEL STRUT SURFACE PAINT	2.74
1017	FRT LOCK CARRIER SURFACE PAINT	3.74
1481	LEFT FRONT DOOR SURFACE PAINT	23.66
1482	RIGHT FRONT DOOR SURFACE PAINT	23.66

Labour Cost - Paint

	42.00 SGD/h	Hrs	WU	Price SGD
Factor			42.0	
Time Paint		2.50	25.0	105.00
Preparation Main Work Metal		6.70	67.0	281.40
Total	10 WU/h			

Material Cost - Paint

	Price SGD
New Part Painting	52.12
Surface-/Blend Paint	53.80
Material-constant Metal Preparation	28.60
Total	134.52

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0253	L/F BMPR BLANK CAP	53113 26060		110.00
0281	FRONT BUMPER	52119 26650		240.00
0293	L/F BUMPER COVER	52127 26120		25.00
0331	FRT BUMPER SUPPORT	52131 26020		120.00
0410	LWR RADIATOR GRILLE	53111 26510		260.00
0411	UPP RADIATOR GRILLE	53111 26500		160.00
0413	GRILLE BACKING	53112 26090		230.00
0431	GRILLE BADGE	90975 02086		85.00
0471	BONNET	53301 26080		280.00
0475	LEFT BONNET HINGE	53420 26040		40.00
0476	RIGHT BONNET HINGE	53410 26040		40.00
0493	BONNET LOCK	53510 26060		60.00
0561	LEFT HEADLAMP ASSY	81170 26731		385.00
0562	RIGHT HEADLAMP ASSY	81130 26731		385.00
0988	CTR FRT PANEL STRUT	53209 26100		180.00
1017	FRT LOCK CARRIER	53205 26012		165.00

Code	Description	Part Number	Supplier	Price SGD
4465	CONDENSER	88450 26120		490.00
7753	L/RADIATOR AIR GUIDE	16594 75011		65.00
7754	R/RADIATOR AIR GUIDE	16593 75012		65.00
f: OEM Parts				0.00
n: Non-OEM Parts				3,385.00
u: Used parts				3,385.00
Savings				
Subtotal				
Total				

Extras

Code	Description	Price SGD
1002	Electrical work Electrical work	20.00*
1003	Engine coolant Engine coolant	20.00*
1004	Air con coolant Air con	30.00*
1005	Front number plate Number Plate	35.00*
1006	BRAKE OIL BRAKE	30.00*
Total Extras		135.00

Final Calculation

	SGD	SGD
Parts	3,385.00	
Total Parts		3,385.00
Labour Time Base 10 WU/h		
Total 51.0 WU X 42.00 SGD/h	214.20	
Fixed Rate	95.00	
Total of Labour		309.20
Total Of Extras		135.00
Paint Work Time Base 10 WU/h		
Labour Cost 67.0 WU X 42.00 SGD/h	281.40	
Material Cost	134.52	
Total Paint Including Material		415.92
Repair Cost Excludes GST		4,245.12
GST (+7.0%)		297.16
Repair Cost Included GST		4,542.28

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

View Received Message

This mail is associated with :

PC2630M (SNM20D200056/PC2630M/IRENE)

OD

Jan 2 2020 6:00AM

[RIEZQI TRANSPORTATION]

S & H Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 08/01/2020 10:13 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4245.12) - PC2630M - Claim Handler: Irene Tay Hui Ping

Approved:4245.12.

DOCUMENTS SUMMARY

There are no documents.