

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005467

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

DATE : 06/01/2020
ACCIDENT DATE : 30/12/2019
VEHICLE NO : YP8181C
CHASSIS/ENG.NO : FEB21EA25014
VEHICLE MODEL : MIT CANTER FEB21
CLAIM NO :
POLICY NO :
REMARK : 8181INDIA TP AGST YQ1844P

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
5	1	PC	REAR TAILGATE 23PAX STICKER <i>✓</i>	20.00		20.00	20.00
6	1	PC	REAR NUMBER PLATE <i>✓</i> <i>FRT</i>	20.00		20.00	20.00
SUB-TOTAL							880.00
** WORK LABOUR **							
			TO CHECK WIRING			30.00	30.00
			TO APPLY ANTI RUST COATING			150.00	150.00
			REDRAW COMPANY LOGO @ FRT&REAR			300.00	300.00
			TO TOP UP AIRCON GAS			100.00	100.00
			TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS			1200.00	1200.00
			TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS			1000.00	1000.00
			TO REMOVE & REFIX FRT WINDSCREEN			150.00	150.00
			TO REMOVE & REFIX FRT DASHBOARD			200.00	200.00
SUB-TOTAL							3,130.00

Asul
Hp 90010068
7 days
4/5
09/01/2020
@ 1530
Ready after repair

total \$9213.75
less 20% = \$7371.00
plus \$7371.00
ok? pls revert. shann
29/1/2020.

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 13,436.75
ADD 7% GST. S\$ 940.57
GRAND TOTAL : S\$ 14,377.32

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.