

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 25140

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0011/2020/NS
Date : 6-Jan-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Narinder Kaboor
Address : Blk 808 Thomson Road
#20-22
Singapore 298190
Telephone : (HP)+65 98233821
Type of Claim : Own Damage Claims
Policy No. : 2100499441
Vehicle No : **SCW 7585 B**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : 26/1/2017
Engine No : CYR 021773
Chassis No : WAUZZZ4M1HD014201
Mileage : 23254
Date In : 4-Jan-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Jan-20
Place of Accident : BKE Going Towards PIE Exit 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SCW 7585 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 /	
2	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 480.00 X	
3	To dismantle and renew rear bumper. To repair lhs rear fender. To cut out and reweld end panel inner and end panel outer. Re-organise crash management components. Reinstall all parts removed.	S 4,950.00 <i>600</i> <i>600 x 2 = 1200</i>	<i>600</i> <i>1750</i>
4	To respray rear bumper, rear lower bumper, rear lid, both rear wheel arch trims, end panelling, lhs rear fender and spare wheel housing. To carry out joint sealer works and stone chip treatment.	S 7,100.00 <i>600</i> <i>600 x 3</i> <i>+ 400 + 600 = 2600</i>	<i>2400</i> <i>2200</i> <i>2800</i>
5	To remove and renew rear exhaust silencer and align to position.	S/N \$ 480.00 /	
6	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$ 13,562.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCW 7585 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER / DD	\$ 1,121.00	896.80
2	REAR BUMPER COVER / DD	\$ 1,677.00	1341.60
3	REAR BUMPER FIXING PARTS X NAI X NAI	\$ 188.00	X
4	REAR BUMPER SPOILER / DR	\$ 1,151.00	920.80
5	REAR BUMPER SPOILER TRIM ? X NAI	\$ 97.00	X
6	BOOT LID CONTROL UNIT X NAI	\$ 350.00	
7	REAR BUMPER CARRIER ? X NAI	\$ 1,238.00	X
8	REAR BUMPER HOLDING STRAP ? X NAI	\$ 166.00	X
9	REAR BUMPER GUIDE SECTION - CENTRE ? X NAI	\$ 129.00	X
10	REAR BUMPER GUIDE SECTION ? / DR	\$ 58.00	✓ 45.76
11	REAR BUMPER SEAL - LH ? X NAI	\$ 13.00	X
12	REAR PARKING AID SENSOR - INNER / OUTER X S NAI	462.00	X NAI
13	REAR PARKING AID SEAL RING X NAI 4	\$ 12.00	X NAI
14	REAR BUMPER WIRING SET ? X NAI	\$ 594.00	
15	AUDI EMBLEM X NAI	\$ 113.00	
16	Q7 INSCRIPTION X NAI	\$ 87.00	
17	TFSI INSCRIPTION X NAI	\$ 87.00	
18	QUATTRO INSCRIPTION X NAI	\$ 87.00	
19	LED TAIL LIGHT X NAI	\$ 1,750.00	
20	TAIL LIGHT - LH / DR	\$ 326.00	260.20
SUB TOTAL SPARE PARTS		: \$ 9,706.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCW 7585 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	REAR CROSS PANEL ? X MM	\$ 577.00	X
22	REAR CROSS PANEL REINFORCEMENT ? X MM	\$ 1,225.00	X
23	CENTRE SILENCER / DD	\$ 2,459.00	1967.20
24	DUAL CLIP / MC	\$ 52.00	41.60
25	EXHAUST TAIL PIPE TRIM - LH / CUT	\$ 300.00	240.00
26	REAR WHEEL COVER - LH / RH / MC 2	\$ 688.00	550.40
27	WHEEL HOUSING LINER / CR4	\$ 298.00	238.40
28	STONE CHIP ? X MM	S/N \$ 180.00	X
29	ACRYLIC SEALANT ? X MM	S/N \$ 180.00	X
30	CAVITY WAX ? X MM	S/N \$ 140.00	X
31	SUNDRIES ? / MC	\$ 300.00	16.64

TOTAL SPARE PARTS	\$ 16,105.00
TOTAL LABOUR CHARGES	\$ 13,562.00
GRAND TOTAL	\$ 29,667.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

[Signature]
8/1/2020

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Steve (LKK)

:

:

:

:

:

7/1/20, 12:30 am
OD - Not Auth (Part)

6 # days

Excess - ?

P/P

My Bel SM

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0011/2020/NS

Date

9-Jan-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SCW 7585 B

Model No

Audi Q7 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Parts			
1	Retainer for aerial / <i>OT</i>	\$ 37.00	37.00
2	Vent trim / <i>OR</i>	\$ 69.00	138.00

TOTAL

\$ 106.00

Stell 10/1/20

For Premium Automobiles Pte Ltd

add 1 repair day

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: