

ASS. REC. BY:

REF: CS/INC 70000384/Dyf302

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Theresa Vimala

of INC

Date/Time: 7 Jan 2020 9:57 a.m

~~Estimated Cost~~

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JSD 7114

Insured: SLN 2387 E

at Workshop m/s SG 98 motor

Tel: 91711655

of BLK 4001 Amc Inclusion / blk 1 #01-21

Policy No:

Claim No: MT/1078442-002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement: _____

Date/Time: 10:35am @ 7/1/2020

Person Contacted: Leena

Vehicle IN / OUT[illegible]

ASS. REC. BY:

REF:

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

JSD 7114

Yr Regn:

May 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha Jupiter 135

c.c

134

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

61870

T/Radio: Insured / Std / NI / NA

Eng/No:

P MYU 60420H 0080689

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90 R17

R:

80/90 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Michelin

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

61

mm

D.O.A.

02/01/2020

D.O.I.

07/09/2020

Survey held at

SG 98 Man

AME 0624PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front 4 o/s Portion 4 w/s Rn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NTUC BLN 2387E

Sum insured RM 5K

RECEIVED 03 MAR 2020

03/03/2020 Jumper L/S 1700/- with 3 days of repair (Red \$2348-20, 58%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

3/3/20 Typist

Report Format:

Comp Surd / R.E.C

\$1700/-

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

250

Transportation:

S + RS. \$

Photos

Others

TOTAL

250

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 7 January 2020 9:57 AM
To: Admin-D (LKKAuto); assignments; SUR
Cc: Thio Tse Kiat; Theresa Vimala D/O Balagangadharan
Subject: RE: TP CASES FARMED OUT TO LKK ON 7/1/2020

Dear LKK,

Please assist to survey the following vehicles :

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Type	Survey Time	OI VEH	DOA	Additional Remarks
1		MT/1073709-003	7/1/2020	PA7900L	LEXBUILD AUTO & TRADING PTE. LTD.	74 SUNGEI KADUT STREET 1 SUNGEI KADUT INDUSTRIAL ESTATE SINGAPORE 729374	Hui Wen / 6362 3393	Physical Survey				
2		PC/0664445	7/1/2020	PC7094C	LEXBUILD AUTO & TRADING PTE. LTD.	74 SUNGEI KADUT STREET 1 SUNGEI KADUT INDUSTRIAL ESTATE SINGAPORE 729374	Hui Wen / 6362 3393	Physical Survey				
3		MT/1078663-001	7/1/2020	SLT9514C	CARZ AUTO SERVICES PTE LTD	61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 SINGAPORE 757047	jeslyn chua / 83227418	Physical Survey				6493 1924
4		MT/1078525-002	7/1/2020	SLA7692I	ELITE AUTOMOTIVE	280 WOODLANDS	Christy / 86606722	Physical Survey				63397378

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 288914
Tel No: 1800-4829999



T/20200104/2033

1 of 3

Report No T/20200104/2033

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/01/2020 10:44		Vide Report No.:		Station Diary No.: 23	
Informant's Particulars					
Name of Informant: SEGAR A/L CHINNI/AH			Address:		
ID Type / ID No.: FIN NO / F0955268P			Contact No.: Home/Office:		Mobile: 82054989
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 52	Date of Birth: 04/04/1967	Type of Informant: Rider		
Race: Indian			Language:		Institution / School Name:
Occupation: SECURITY GUARD			Driving Licence Information: Class: 2		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 02/01/2020 07:10	Type of Location:
Location: VICTORIA PARK ROAD OUTSIDE 4 VICTORIA PARK ROAD				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JSD7114	Motorcycle	YAMAHA	YAMAHA 135LC	Red	Slightly Damaged	0
SLN2387E	Car	BMW	X1 SDRIVE18I AT LED NAV	Black	Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20200104/2033

2 of 3

Police Station Of Origin
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No 1800-4629999

Report No T/20200104/2033

CONTINUATION OF REPORT

Rider			
Name	SEGAR A/L CHINNIAH	ID No.	F0955268P
Related Vehicle	JSD7114 (Motorcycle)	Contact No.	82054989
Hospital/Clinic	ONECARE CLINIC CLEMENTI	Class of Driving Licence & Expiry Date	Class 2 Date of Expiry: NIL
Date Treatment	02/01/2020	Date Discharge	02/01/2020
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Driver			
Name	Tricia Yeo Yi-Twan	ID No.	S7641467Z
Related Vehicle	NIL	Contact No.	86502558
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 02/01/2020 at around 0710hrs, on my way to work, I was hit by one Singapore black B.M.W. vehicle SLN2387E, the driver's particular is as below:

TRICIA YEO YI-TWAN
NRIC: S7641467Z
HP 86502558
Vehicle no: SLN2387E

The accident happened when the above said vehicle SLN2387E was doing a out reversing from her unit to 4 Victoria park road while I was riding towards Empress Market. The vehicle, SLN2387E hit the rear side of my motorcycle causing my motorcycle exhaust pipe to be dented, fork tube damaged, and minor damages at other parts of my motorcycle. There is no camera mounted to my motorcycle. There is no visible injury caused, however, I went to the clinic for 2 days MC on 02/01/2020 and 03/01/2020 due to back pain after the incident. Both of us exchanged particular and she agreed to pay for my motorcycle damages, I am lodging this report for insurance claiming purposes.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bukit Timah N P C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999



T/20200104/2033

3 of 3

Report No. T/20200104/2033

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E/

Sgt 3 CHUA YITING

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case.

TP / AEIT /

SSI 2 JUREMAH BINTE AHMAD

Contact No: 65476219

Signature Of Informant:

Date/Time:

04/01/2020 10:44

Classification Of Case:

Authentication Stamp

12103



SINGAPORE
POLICE FORCE

SH 170

SIGNATURE



SIVIL PEMILIKAN KENDERAAN
JABATAN PENGANGKUTAN JALAN

JJR6ZE74

No. Pendaftaran : JS07114

No. ID

670404085227

Nama Pemilik Berdaftar

SEGAR A.I CHINNIAH

Alamat

NO 5 JLN JASA 16 LBN UTARA RTN8
81200 SKUDAI JOHOR

No. Pendaftaran

PMYR0220H0080689 / 0109E-539789

Nama Pemilik Berdaftar

YAMANA / YAMAHA 135CC

No. Pendaftaran

134

Alamat Berdaftar

PETROL

No. Pendaftaran

PENASARAN PENPAIAN

No. Pendaftaran

MOTOSIKAL

No. Pendaftaran

MOTOSIKAL : 2017

No. Pendaftaran

21.05.2017

No. Pendaftaran

RTN

No. Pendaftaran

No. Pendaftaran

No. Pendaftaran

Full Settlement

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 6 January 2020

To : NTUC /LKK-

By Fax: 6338-1500

Attn: Motor Claims Dept

Tel:

VEHICLE NO : JSD 7114

Yamaha Jupiter LC 135

ACCIDENT DATE: 2 January 2020

Description	Qty	Quotation \$
1 Handle Bar <i>distorted</i>	1	135.00 ✓
2 Handle Bar Bracket <i>new</i>	1	155.00 X
3 Front Panel <i>new</i>	1	195.00 X
4 Inner Panel <i>new</i>	1	185.00 X
5 Front Mudguard <i>new cut / broken</i>	1	235.00 X ✓
6 Fork Tube <i>new</i>	1 set	480.00 ✓
7 Fork Under Bracket <i>new</i>	1	185.00 ✓
8 Front Side Fairing RH <i>new cut</i>	1	155.00 X ✓
9 Front Side Fairing LH <i>new</i>	1	165.00 X
10 Rear Tail Panel RH <i>new</i>	1	175.00 X
11 Rear Footrest Bracket <i>broken</i>	1	135.00 ✓
12 Rear Footrest Rubber <i>new</i>	1	65.00 X
13 Pillion Bar <i>new</i>	1	95.00 X
14 Rear LH Signal <i>broken</i>	1	78.00 ✓
15 Exhaust Pipe <i>new / broken</i>	1	850.00 ✓
16 Swing Arm <i>distorted</i>	1	450.00 X ✓
17 Rear Mudguard <i>distorted</i>	1	175.00 ✓
18 Exhaust Chrome Guard <i>new</i>	1	185.00 X

Sub-Total 4,098.00

Less 10% 409.80

Sub-Total 3,688.20

Accepted by Repairer

Signature: _____

Date: _____

is subject to final approval from Insurance Company

• Agreement (terms) must be received and

• No illegal modifications is allowed

• Third party survey is on a written Pre-Inspection

• Parts prices are subject to confirmation

• To verify damaged parts (and reserves)

• To verify estimated repair cost

the Repairer of the following:

LKK Auto Components hence notify

VEHICLE NO : JSD 7114

Yamaha Jupiter LC 135

Nett items

- | | | | |
|---|--|--------|-------|
| 1 | Rear number plate | 20.00 | 15/- |
| 2 | Towing fee | 40.00 | X |
| 3 | Remove & replace fork tube, fork oil seal, front rim, exhaust pipe & swing arm | 180.00 | 150/- |
| 4 | Supply body decal sticker and painting. | 120.00 | 80/- |

365.00

Sub-Total

360.00

Body alignment & 250.00
120/-

Nett Total

4,048.20

6208.20

2955.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Repair Sum 1700/-

Kindly revert upon completion
Thank you

07/01/2020 @ 1800hrs

N/A Arthur

2/sum

3 day.

S9 MOTOR TRADING PTE LTD

:LG

T Ryan

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20000388/Dyf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 05-03-2020



ATTN : AZHARI

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 2387E	Veh. Inspected	JSD 7114
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1078442-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	07/01/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA JUPITER 135	c.c	134
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	PMYUG0420H0080689	Colour	RED
Odometer	61870 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90 R17	MICHELIN	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90 R17	MICHELIN	3 mm
L/H Rear Tyre			mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, FRONT AND N/S
REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/01/2020	Inspect Date / Time	07/01/2020 (06:24 PM)
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

5a. RemarksA)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSD 7114

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	DISTORTED	135.00	135.00
1	HANDLE BAR BRACKET	NOT NECESSARY	155.00	-
1	FRONT PANEL	TO REPAIR SEE LABOUR	195.00	-
1	INNER PANEL	NOT NECESSARY	185.00	-
1	FRONT MUDGUARD	CUT / BROKEN	235.00	235.00
1	SET FORK TUBE	BENT	480.00	480.00
1	FORK UNDER BRACKET	DAMAGED	185.00	185.00
1	FRONT SIDE FAIRING RH	CUT	155.00	155.00
1	FRONT SIDE FAIRING LH	TO REPAIR SEE LABOUR	165.00	-
1	REAR TAIL PANEL RH	TO REPAIR SEE LABOUR	175.00	-
1	REAR FOOTREST BRACKET	BROKEN	135.00	135.00
1	REAR FOOTREST RUBBER	NOT NECESSARY	65.00	-
1	PILLION BAR	TO REPAIR SEE LABOUR	95.00	-
1	REAR LH SIGNAL	BROKEN	78.00	78.00
1	EXHAUST PIPE	BENT / BROKEN	850.00	850.00
1	SWING ARM	DISTORTED	450.00	450.00
1	REAR MUDGUARD	DEFORMED	175.00	175.00
1	EXHAUST CHROME GUARD	NOT NECESSARY	185.00	-
	LESS 10% DISCOUNT		-409.80	-287.80
			3,688.20	2,590.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	BENT	20.00	15.00
			20.00	15.00
<u>LABOUR</u>				
	TOWING FEE.	NOT NECESSARY	40.00	-

Report Ref No. CS/INC20000388/Dyf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REPLACE FORK TUBE,FORK OIL SEAL,FRONT RIM,EXHAUST PIPE & SWING ARM.INCLUSIVE OF THE REPAIR OF FRONT PANEL,FRONT SIDE FAIRING LH,REAR TAIL PANEL RH AND PILLION BAR.		180.00	150.00
	SUPPLY BODY DECAL STICKER AND PAINTING.		120.00	80.00
	BODY ALIGNMENT.		260.00	120.00
			600.00	350.00
GRAND TOTAL			4,308.20	2,955.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,700.00

Report Ref No. CS/INC20000388/Dyf3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.