



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

MS FCIL Insured's Veh No : SHD8861M

Date of Accident : 28 December 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 02 January 2020

Estimate To Repair SMD5799X - Opel INSIGNIA GRANDSPORT B16DTH

Chassis No : W0VZM6EF7J1070415

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	n/s headlamp	\$ 1,300.00
02	1 pc	front bumper	\$ 2,100.00
03	1 pc	n/s front bumper sensor	\$ 450.00
04	1 pc	n/s front fender	\$ 920.00
			\$ 4,770.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To rust-proofing of the affected areas.	\$ 100.00
02		To check electrical lighting concerned.	\$ 50.00
03		To reinstall of rear bumper parking sensor.	\$ 50.00
04		Panel beating, knocking and straighten the necessary portion,	\$ 750.00
		remove and renewal of parts, adjust and realign the same.	
05		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 1,850.00
		Total	\$ 6,620.00