



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004488
INV Date 24/06/2020
Reference CC4/FCI20000394/Eba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMK 1721J
Insured Veh. SHC 7258S
Claim No. D20000073MFSH
Policy No. D-19092579MFSH
Accident Date 26/12/2019
Inspection Date 14/01/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20000394/Eba3q2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 24-06-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7258S	Veh. Inspected	SMK 1721J
Policy No.	D-19092579MFSH	Coverage (\$)	0.00
Claim No.	D20000073MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	07/01/2020

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JF1SK7KL5KG006359	Colour	BROWN
Odometer	11152	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/12/2019	Inspection Date	14/01/2020
Survey held at	25 Leng Kee Road		
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 1721J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MUFFLER ASSY RH (N)	NOT NECESSARY	504.00	-
1	TAIL PIPE CUTTER (N)	NOT NECESSARY	72.00	-
1	BUMPER FACE R HG (N)	BROKEN	482.40	482.40
1	BRKT SD R RH (N)	NOT NECESSARY	14.40	-
1	BRKT SD R LH (N)	NOT NECESSARY	14.40	-
1	BEAM COMPL R EU (N)	BENT	252.00	252.00
1	COVER HOOK R (N)	NOT NECESSARY	10.80	-
1	BUMPER GUARD R RGD (N)	CUT	216.00	216.00
	LESS 20% DISCOUNT		-313.20	-190.08
			1,252.80	760.32
	<u>SPECIAL NETT ITEMS</u>			
1	CARGO STEP PANEL S/S (SN)	DENTED	420.00	420.00
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			520.00	440.00
	<u>LABOUR</u>			
	REPAIR /REPLACE REAR END PANEL AND REAR BUMPER .		1,120.00	1,120.00
	RESPRAY REAR END PANEL AND REAR BUMPER .		880.00	880.00
	REMOVE/REFIX EXHAUST TO FACILITATE REPAIR .	NOT NECESSARY	150.00	-
	SUPPLY /INSTALL REVERSE SENSOR 2 EYES.		300.00	120.00
	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR.	NOT NECESSARY	150.00	-
	TO CONDUCT REAR PORTION ANTI RUST COATING AFTER REPAIR .		580.00	290.00
			-	-
			-	-
			-	-
			3,180.00	2,410.00
	GRAND TOTAL		4,952.80	3,610.32
	RECOMMENDED COST OF REPAIRS			3,610.32

Report Ref No. CC4/FCI20000394/Eba3q2



Report Ref No. CC4/FCI20000394/Eba3q2

A black ink signature of Chen Tsue Yee, consisting of several fluid, overlapping strokes.

CHEN TSUE YEE

Automotive Assessor

A black ink signature of Ho Leong Chuan, featuring a stylized 'H' and 'L' with a small '2' at the end.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 1721J

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 1721J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

