

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/0001/2020
DATE : 27-DEC-2019

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : XIE JIXIANG
ADDRESS : APT BLK 136 RIVERVALE STREET
#06-742
S(540136)
TELEPHONE NO : 98256234

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900081761
VEHICLE NO : SMK1721J
MODEL CODE : SK7AKFL
MODEL/YEAR : FORESTER 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YF23032
CHASSIS NO : JF1SK7KL5KG006359
MILEAGE : 1 KM
DATE IN : 27/12/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 26/12/2019

Print Date : 06/01/2020
Print Time : 13:04:19

Steve (LKK)
83228813
Stevechan@lkkcorp.com

WHL Pujul
14/1/20, to 1-10 pm
P/P
By Before spy
5 - 3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMK1721J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TPCLAIM 1ST CAP DATE:26/12/2019 TIME:0725 LOCATION:REPUBLIC BLVD LANE TO KPE		
3	ZZ/002	REPAIR/REPLACE REAR END PANEL AND REAR BUMPER ⁵⁶⁰	1120.00	560 1120 ✓
4	ZZ/003	RESPRAY REAR END PANEL AND REAR BUMPER ⁴⁴⁰	840.00	440 880 ✓
5	ZZ/004	REMOVE/REFIC EXHAUST TO FACILITATE REPAIR	150.00	X
6	ZZ/005	SUPPLY/INSTALL REVERSE SENSOR 2 EYES (Trans~)	300.00	120 ✓
7	ZZ/006	REMOEV/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	X
8	ZZ/007	TO CONDUCT REAR PORTION ANTI RUST COATING AFTER REPAIR ⁷⁹⁰	580.00	? 290 ✓
9	ZZ/008	SUNDRIES	100.00	20 ✓
TOTAL LABOUR CHARGES			3240.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMK1721J

		DAMAGED PARTS & PRICES			S/LIST REMARKS
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	
1	MUFFLER ASSY RH	44300SJ030	504.00	? X NN	
2	TAIL PIPE CUTTER	44370FL000	72.00	X NN	
3	BUMPER FACE R HG	57704SJ310	482.40	/ OR	
4	BRKT SD R RH	57707SJ320	14.40	X NN	
5	BRKT SD R LH	57707SJ330	14.40	X NN	
6	BEAM COMPL R EU	57711SJ0309P	252.00	? ✓ BT	
7	COVER HOOK R	57731SJ300	10.80	X NN	
8	BUMPER GUARD R RGD	57734SJ310	216.00	/ CUT	
9	CARGO STEP PANEL S/S	E7710SJ000			420.00 / 00
SUB TOTAL			1566.00	0.00	420.00 0.00
LESS DISCOUNT (NETT-20 %)			313.20	0.00	0.00 0.00
GRAND TOTAL			1252.80	0.00	420.00 0.00
OVERALL TOTAL			1672.80		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMK1721J

TOTAL LABOUR CHARGES	3240.00
TOTAL SPARE PARTS CHARGES	1672.80

GRAND TOTAL	4912.80 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.