



Case Details

Case Reference Number : TAX/01/20/2003

Type of Repair : Accident Repair

Vehicle Registration Number : SHB3L

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10000-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd

Accident Date and Time : 31/12/2019 04:40 PM

Vehicle Age(In Months) : 70

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace ▾	/ BR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾	/ MC
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace ▾	/ BR
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	1	59.10	Replace ▾	/ BR
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			DEFLECTOR, RADIATOR RH	1	83.50	83.50	25.00	62.63	Replace	0	0	Not Give ▾	X NAI
One Time Key In	Main			DEFLECTOR, RADIATOR LH	1	77.00	77.00	25.00	57.75	Replace	0	0	Not Give ▾	X NAI

Total Spare Part Cost 40,726.70

Surveyor Total 18,692.46

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 32,581.36

Final Sur Total 14,953.97

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace ▾ / BR
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace ▾ / CH
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace ▾ / MIS
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace ▾ / BR
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	1	217.80	Replace ▾ / TN
One Time Key In	Main			THERMISTOR ASSY	1	107.00	107.00	10.00	96.30	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	1	265.68	Replace ▾ / BR
One Time Key In	Main			FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			BRACKET, FR TURN LOWER RH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			LENS & BODY, FR TURN RH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace ▾ / BR
One Time Key In	Main			EMBLEM FRONT	1	64.88	64.88	25.00	48.66	Replace	1	48.66	Replace ▾ / MIS
One Time Key In	Main			HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			COVER, RADIATOR	1	122.80	122.80	25.00	92.10	Replace	0	0	Not Give ▾ X NAI

Total Spare Part Cost 40,726.70

Surveyor Total 18,692.46

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 32,581.36

Final Sur Total 14,953.97

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Give	X NAI
One Time Key In	Main			GRILLE, RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Give	X NAI
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	/ QR
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give	X NAI
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0	Not Give	X NAI
One Time Key In	Main			UNDER COVER SIDE/LH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	X NAI
One Time Key In	Main			UNDER COVER SIDE/RH	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	X NAI
One Time Key In	Main			HOOD PANEL	1	748.10	748.10	25.00	561.08	Replace	1	0	Repair	X R
One Time Key In	Main			HOOD HINRE LH	1	55.90	55.90	25.00	41.92	Replace	1	41.92	Replace	/ BT
One Time Key In	Main			HOOD HINGE RH	1	55.90	55.90	25.00	41.92	Replace	1	41.92	Replace	/ BT
One Time Key In	Main			WIPER GARNISH	1	614.00	614.00	25.00	460.50	Replace	1	460.50	Replace	/ CHT
One Time Key In	Main			WIPER GARNISH COVER,LH	1	23.80	23.80	25.00	17.85	Replace	0	0	Not Give	X NAI
One Time Key In	Main			WIPER GARNISH COVER,RH	1	23.80	23.80	25.00	17.85	Replace	1	17.85	Replace	/ MIS
One Time Key In	Main			HOOD LOCK	1	128.90	128.90	25.00	96.68	Replace	0	0	Not Give	X NAI
One Time Key In	Main			CABLE ASSY,HOOD	1	52.20	52.20	25.00	39.15	Replace	0	0	Not Give	X NAI
One Time Key In	Main			HOOD AUXILIARY CATCH	1	8.60	8.60	25.00	6.45	Replace	0	0	Not Give	X NAI

Total Spare Part Cost 40,726.70

Surveyor Total 18,692.46

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 32,581.36

Final Sur Total 14,953.97

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CLAMP, HOOD LOCK	1	5.90	5.90	25.00	4.43	Replace	0	0	Not Give	X NAI
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	/ APC
One Time Key In	Main			HINGE LOWER RHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0	Not Give	X NAI
One Time Key In	Main			HINGE UPPER RHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0	Not Give	X NAI
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	X NAI
One Time Key In	Main			MIRROR ASSY,RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0	Not Give	X NAI
One Time Key In	Main			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give	X NAI
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	X NAI
One Time Key In	Main			QUARTER GLASS FRT/RH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give	X NAI
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	X NAI
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair	X R
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ APC
One Time Key In	Main			PILLAR, FR BODY, LH	1	363.10	363.10	25.00	272.33	Replace	0	0	Not Give	X NAI
One Time Key In	Main			SEAT BELT FRT/LH	1	822.60	822.60	25.00	616.95	Replace	1	616.95	Replace	/ jammed
One Time Key In	Main			SEAT BELT FRT/RH	1	822.60	822.60	25.00	616.95	Replace	1	616.95	Replace	/ jammed
One Time Key In	Main			DASH BOARD	1	906.10	906.10	25.00	679.58	Replace	1	679.58	Replace	/ DR
Total Spare Part Cost									40,726.70	Surveyor Total		18,692.46		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									32,581.36	Final Sur Total		14,953.97		

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			SENSOR, AIR BAG, FRT/RH/LH	1	273.30	273.30	10.00	245.97	Replace	1	245.97	Replace ✓ MC
One Time Key In	Main			AIR BAG ASSY, INSTR DRIVE	1	1,555.80	1,555.80	10.00	1,400.22	Replace	1	1,400.2	Replace ✓ BR
One Time Key In	Main			AIR BAG ASSY, INSTR/PASSENGER	1	3,177.00	3,177.00	10.00	2,859.30	Replace	1	2,859.3	Replace ✓ BR
One Time Key In	Main			AIR BAG COMPUTER	1	815.20	815.20	10.00	733.68	Replace	1	733.68	Replace ✓ MC
One Time Key In	Main			AIR BAG SPIRAL CABLE	1	953.70	953.70	10.00	858.33	Replace	1	858.33	Replace ✓ MC
One Time Key In	Main			AIR BAG STEERING, DRIVER	1	2,360.40	2,360.40	10.00	2,124.36	Replace	1	2,124.3	Replace ✓ BR
One Time Key In	Main			WIRE ASSY, AIR BAG	1	23.60	23.60	10.00	21.24	Replace	1	21.24	Replace ✓ MC
One Time Key In	Main			LOWER ARM FRT/RH	1	625.90	625.90	25.00	469.42	Replace	0	0	Check ✓ X MI
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	1	1,095.3	Replace ✓ BT
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace ✓ CRA
One Time Key In	Main			HEAD LAMP RH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace ✓ BR
One Time Key In	Main			WIPER WASHER INLET	1	36.90	36.90	25.00	27.67	Replace	1	27.67	Replace ✓ BR
One Time Key In	Main			WIPER WASHER JAR	1	180.10	180.10	25.00	135.07	Replace	1	135.07	Replace ✓ BR
One Time Key In	Main			MOTOR NO:1, WIPER WASHER JAR	1	239.00	239.00	10.00	215.10	Replace	1	215.10	Replace ✓ BR
One Time Key In	Main			MOTOR NO:2, WIPER WASHER JAR	1	240.00	240.00	10.00	216.00	Replace	1	216.00	Replace ✓ BR
One Time Key In	Main			TUBE & ACCESSORY	1	631.90	631.90	25.00	473.92	Replace	1	473.92	Replace ✓ BR
Total Spare Part Cost									40,726.70	Surveyor Total 18,692.46			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost									32,581.36	Final Sur Total 14,953.97			

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HOSE SUB-ASSY DISCHARGE	1	386.90	386.90	25.00	290.17	Replace	0	0	Not Give	X NAI
One Time Key In	Main			HOSE SUB-ASSY SUCTION	1	405.40	405.40	25.00	304.05	Replace	0	0	Not Give	X NAI
One Time Key In	Main			RADIATOR ASSY UPPER	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give	X NAI
One Time Key In	Main			SUPPORT RADIATOR, LH	1	17.70	17.70	25.00	13.27	Replace	0	0	Not Give	X NAI
One Time Key In	Main			SUPPORT RADIATOR, RH	1	54.50	54.50	25.00	40.88	Replace	0	0	Not Give	X NAI
One Time Key In	Main			RADIATOR LOWER SUPPORT	1	876.30	876.30	25.00	657.22	Replace	0	0	Not Give	X NAI
One Time Key In	Main			RADIATOR HOSE LOWER	1	42.40	42.40	25.00	31.80	Replace	0	0	Not Give	X NAI
One Time Key In	Main			RADIATOR HOSE BYPASS NO.1	1	37.20	37.20	25.00	27.90	Replace	0	0	Not Give	X NAI
One Time Key In	Main			RADIATOR HOSE BYPASS NO.2	1	29.00	29.00	25.00	21.75	Replace	0	0	Not Give	X NAI
One Time Key In	Main			COOLANT	1	12.32	12.32	0.00	12.32	Replace	0	0	Not Give	X NAI
One Time Key In	Main			COOLANT RESERVE TANK	1	395.30	395.30	25.00	296.48	Replace	0	0	Not Give	X NAI
One Time Key In	Main			INLET ASSY, AIR	1	232.50	232.50	25.00	174.38	Replace	0	0	Not Give	X NAI
One Time Key In	Main			WIRE, ENGINE ROOM	1	5,567.10	5,567.10	10.00	5,010.39	Replace	0	0	Not Give	X NAI
One Time Key In	Main			ENGINE MOUNTING RH	1	276.20	276.20	25.00	207.15	Replace	0	0	Not Give	X NAI
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM JOINT TO JOINT), NO.1	1	13.60	13.60	25.00	10.20	Replace	0	0	Not Give	X NAI

Total Spare Part Cost 40,726.70

Surveyor Total 18,692.46

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 32,581.36

Final Sur Total 14,953.97

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM JOINT TO JOINT), NO.2	1	13.60	13.60	25.00	10.20	Replace	0	0	Not Give	X N/A
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM JOINT TO JOINT), NO.3	1	13.60	13.60	25.00	10.20	Replace	0	0	Not Give	X N/A
One Time Key In	Main			HOSE, WINDSHIELD WASHER (FROM MOTOR TO JOINT)	1	17.60	17.60	25.00	13.20	Replace	0	0	Not Give	X N/A
One Time Key In	Main			RESERVOIR ASSY, BRAKE MASTER	1	199.70	199.70	25.00	149.77	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BRACKET, RESERVOIR BRAKE	1	58.70	58.70	25.00	44.03	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FENDER FRT/RH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	/ 00
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ MC
One Time Key In	Main			FENDER PROTECTOR FRT/RH SIDE	1	113.90	113.90	25.00	85.43	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	Replace	/ DR
One Time Key In	Main			FENDER LINER PAD, FR WHEEL RH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	X N/A
One Time Key In	Main			FENDER APRON SUB FRT/RH	1	637.80	637.80	25.00	478.35	Replace	1	0	Repair	X R
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	1,113.1	Replace	/ BT
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	/ CRU
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Check	X N/A
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	0	0	Not Give	X N/A

Total Spare Part Cost 40,726.70

Surveyor Total 18,692.46

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 32,581.36

Final Sur Total 14,953.97

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			SHOCK ABSORBER FRT/RH	1	394.20	394.20	25.00	295.65	Replace	0	0	Check ▾ X NAI
One Time Key In	Main			SHOCK ABSORBER MOUNTNG FRT,RH/LH	1	193.80	193.80	25.00	145.35	Replace	1	145.35	Replace ▾ / NAI
One Time Key In	Main			SHOCK ABSORBER BEARING, FRT LH/RH	1	34.00	34.00	25.00	25.50	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			STABILIZER BAR LINK FRT/RH/LH	1	195.00	195.00	25.00	146.25	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			PILLAR, FR BODY RH	1	363.10	363.10	25.00	272.33	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			MEMBER SUB-ASSY, FR RH	1	810.70	810.70	25.00	608.03	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			STABILIZER BAR FRT	1	348.80	348.80	25.00	261.60	Replace	0	0	Not Give ▾ X NAI
One Time Key In	Main			STABILIZER BAR LINK FRT/RH/LH	1	195.00	195.00	25.00	146.25	Replace	0	0	Check ▾ X NAI
One Time Key In	Main			STEERING KNUCKLE RH FRT	1	625.90	625.90	25.00	469.42	Replace	0	0	Check ▾ X NAI
One Time Key In	Main			JOINT ASSY, LWR BALL	1	195.60	195.60	25.00	146.70	Replace	0	0	Check ▾ X NAI
One Time Key In	Main			TIE ROD END RH	1	159.30	159.30	25.00	119.48	Replace	0	0	Check ▾ X NAI
One Time Key In	Main			CROSS MEMBER FRT	1	2,497.50	2,497.50	25.00	1,873.13	Replace	0	0	Check ▾ X NAI
One Time Key In	Main			DRIVE SHAFT RH	1	1,764.40	1,764.40	25.00	1,323.30	Replace	0	0	Check ▾ X NAI
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair ▾ X R
Total Spare Part Cost									40,726.70	Surveyor Total 18,692.46			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost									32,581.36	Final Sur Total 14,953.97			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,183.00	900.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	1,183.00	900	
Total:			1,183.00	900.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0	
3	Main	TO REPSRAY FRONT HOOD	378.00	200	
4	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	150	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
6	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
7	Main	TO RESPRAY RIM	180.00	0	
8	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
9	Main	RESPRAY MIRROR COVER RH	180.00	0	
10	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
11	Main	TO REPRAY FRONT PILLAR RH	180.00	150	
12	Main	TO RESPRAY FRONT PILLAR LH	180.00	0	
Total:			3,150.00	1,300.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	
2	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	/ APC
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	/ APC
5	Main	TO ALIGN CHASSIS	350.00	0	
Total:			1,833.20	535.32	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0	
7	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
8	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	742.20	445.32	<i>nk</i>
9	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
Total:			1,833.20	535.32	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	32,581.36	14,953.97
Total Labour Cost	0.00	900.00
Total Spray Painting	0.00	1,300.00
Other	0.00	535.32
Overall Total	32,581.36	17,689.29
Lump Sum Repair Option		
Lump Sum Total	32,600.00	17,700.00
Surveyor Approved Amount		17,700.00
No of Repair Days*	10	7
Remarks		L/S repair, take after spray.
Surveyor Name		STEVE CHEN
Signature		
Survey Date	06/01/2020	

Save

Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: