



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Notified
L1Ry @30,000p
Running After Paint

ATTN : MOTOR CLAIM DEPT.

T/P VEH NO : GBG7169R

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
ADDRESS :

CONTACT :

VEHICLE NO YP6943J TRANS.

CHASSIS NO :

MAKE / MODEL : ISUZU LORRY

ENGINE NO :

OWNER'S INSURER FIRST CAPITAL

ACCIDENT DATE : 23-Oct-19

JOB-CODE : TP S/A : MICHELLE

CLAIM DETAIL

MATERIALS

- 1 TAILLAMP ASSY LH
- 2 REAR MUDFLAP LH
- 3 REAR MUDFLAP BRACKET INNER LH
- 4 REAR MUDFLAP BRACKET OUTER LH
- 5 REAR MUDFLAP LOWER RUBBER - ISUZU LH
- 6 REAR WHEEL BEARING LH INNER
- 7 REAR WHEEL BEARING LH OUTER
- 8 REAR AXLE 11,200
- 9 REAR AXLE SPRING 1SET LH
- 10 REAR AXLE SPRING 1SET RH
- 11 REAR CENTRE SHAFT
- 12 REAR SHAFT BRACKET 2PCS
- 13 REAR WHEEL SHAFT LH
- 14 REAR WHEEL SHAFT RH
- 15 REAR WHEEL SHAFT WHEEL BEARING LH
- 16 REAR WHEEL SHAFT WHEEL BEARING RH
- 17 LONG SHAFT ASSY
- 18 LONG SHAFT CENTRE MOULDING

	QTY	QUO-PRICE	DISC %	DISC-PRICE	SUR-DISP	REV. PRICE
B/L	1.00	\$ 450.00	10.00	\$ 405.00	Y	✓
T/L	1.00	\$ 520.00	10.00	\$ 468.00	Y	✓
A/L	1.00	\$ 220.00	10.00	\$ 198.00	Y	✓
A/L	1.00	\$ 220.00	10.00	\$ 198.00	Y	✓
M/L	1.00	\$ 180.00	10.00	\$ 162.00	Y	✓
M/L	1.00	\$ 450.00	10.00	\$ 405.00	Y	✓
M/L	1.00	\$ 450.00	10.00	\$ 405.00	Y	✓
A/L	1.00	\$ 13,500.00	10.00	\$ 12,150.00	Y	✓
D/L	1.00	\$ 2,000.00	10.00	\$ 1,800.00	Y	✓
S/L	1.00	\$ 2,000.00	10.00	\$ 1,800.00	Y	X
R	1.00	\$ 8,850.00	10.00	\$ 7,965.00	Y	X
S/L	1.00	\$ 240.00	10.00	\$ 216.00	Y	X
S/L	1.00	\$ 980.00	10.00	\$ 882.00	Y	X
S/L	1.00	\$ 980.00	10.00	\$ 882.00	Y	X
M/L	1.00	\$ 450.00	10.00	\$ 405.00	Y	X
M/L	1.00	\$ 450.00	10.00	\$ 405.00	Y	X
S/L	1.00	\$ 8,850.00	10.00	\$ 8,850.00	Y	X
S/L	1.00	\$ 450.00	10.00	\$ 450.00	Y	X
TOTAL (PARTS) :		\$ 41,240.00		\$ 38,046.00		

SPECIAL NETT ITEM

- 1 REAR CABIN ASSY RH 11,500
- 2 REAR CABIN TAILLAMP PANEL LH
- 3 REAR TOP PANEL ALUMINIUM RH 3PCS
- 4 REAR STICKER 60KM
- 5 REAR REFLECTOR STICKER - RED
- 6 REAR REFLECTOR STICKER SIDE RH- BLUE & ORANGE
- 7 REAR FENDER MUDFLAP BRACKET LH (FRONT)
- 8 REAR FENDER MUDFLAP BRACKET LH (REAR)
- 9 REVERSE CAMERA
- 10 REAR TYRE LH INNER - 215/85/R22

B/L	1.00	\$ 12,800.00	0.00	\$ 12,800.00	Y	✓
B/L	1.00	\$ 680.00	0.00	\$ 680.00	Y	✓
B/L	1.00	\$ 1,200.00	0.00	\$ 1,200.00	Y	✓
M/L	1.00	\$ 30.00	0.00	\$ 30.00	Y	1500
M/L	1.00	\$ 180.00	0.00	\$ 180.00	Y	1000
M/L	1.00	\$ 360.00	0.00	\$ 360.00	Y	2000
B/L	1.00	\$ 180.00	0.00	\$ 180.00	Y	✓
B/L	1.00	\$ 180.00	0.00	\$ 180.00	Y	✓
M/L	1.00	\$ 380.00	0.00	\$ 380.00	Y	✓
C/L	1.00	\$ 480.00	0.00	\$ 480.00	Y	2000

- REAR TYRE LH OUTER - 215/85/R22
 REAR RIM LH INNER
 REAR RIM LH OUTER
 14 REAR CRANE
 15 REAR CRANE FORK HYDRAULIC
 16 REAR SPRING BRACKET FRONT
 17 REAR SPRING BRACKET REAR
 18 REAR CABIN TAILLAMP WIRE HARDNESS
 19 HYDRAULIC OIL
 20 REVERSE SENSOR 1SET
 21 SIREN LAMP
 22 CONE BRACKET X2
 23 HYDRAULIC OIL —
 24 HYDRAULIC HOSE 1SET (12PCS)
 25 KING DOLLEY ROLLER
 26 REVERSE CAMERA CONVERTER UNIT
 27 WATER TANK
 28 WATER TANK BRACKET ASSY
 29 STANDARD VOLUME LOCKABLE MILD STEEL
 STORAGE COMPARTMENT

67	1.00	\$	480.00	0.00	\$	480.00	Y	208in
Sn	1.00	\$	680.00	0.00	\$	680.00	Y	X
Sn	1.00	\$	680.00	0.00	\$	680.00	Y	X
R	1.00	\$	12,500.00	0.00	\$	12,500.00	Y	X
R	1.00	\$	2,800.00	0.00	\$	2,800.00	Y	X
R	1.00	\$	650.00	0.00	\$	650.00	Y	X
R	1.00	\$	650.00	0.00	\$	650.00	Y	2
R	1.00	\$	650.00	0.00	\$	650.00	Y	✓
TR	1.00	\$	860.00	0.00	\$	860.00	Y	508in
nu	1.00	\$	450.00	0.00	\$	450.00	Y	X
Sn	1.00	\$	520.00	0.00	\$	520.00	Y	X
Sn	1.00	\$	205.00	0.00	\$	205.00	Y	X
Sn	2.00	\$	600.00	0.00	\$	600.00	Y	X
Repeater	1.00	\$	450.00	0.00	\$	450.00	Y	X
Sn	1.00	\$	7,200.00	0.00	\$	7,200.00	Y	X
R	1.00	\$	3,850.00	0.00	\$	3,850.00	Y	X
Sn	1.00	\$	290.00	0.00	\$	290.00	Y	X
Sn	1.00	\$	120.00	0.00	\$	120.00	Y	X
R	1.00	\$	380.00	0.00	\$	380.00	Y	2
R	1.00	\$	5,200.00	0.00	\$	5,200.00	Y	2

TOTAL (PARTS) :

\$ 55,035.00

\$ 55,035.00

LABOUR

- 1 STRAIGHTEN & PANEL BEAT ACCIDENT AREAS
 2 SPRAY PAINTING ON ACCIDENT AREA
 3 R&R CRANE TO SERVICE TO LIFT UP & DOWN
 4 R&R REAR SUSPENSION LH
 5 CHECK & REPAIR WIRING SYSTEM
 6 RESPRAY TUFF KOTE ON AFFECTED AREA
 7 CONDUCT CHASSIS REPAIR REAR LH PORTION
 8 R&R REAR AXLE, AXLE SPRING & LONG SHAFT TO ASSIT REPAIR
 9 RESET & PROGRAMME LTA SYSTEM & INSPECTION
 10 RESPRAY CHASSIS PANEL ON ACCIDENT AREA
 11 TOWING -KING DOLLEY
 12 POST ACCIDENT REPAIR INSPECTION

	1.00	\$	3,800.00	0.00	\$	3,800.00	Y	2500l
	1.00	\$	1,800.00	0.00	\$	1,800.00	Y	1000l
(BHT)	1.00	\$	480.00	0.00	\$	480.00	Y	350l
	1.00	\$	480.00	0.00	\$	480.00	Y	200l
	1.00	\$	80.00	0.00	\$	80.00	Y	20l
	1.00	\$	120.00	0.00	\$	120.00	Y	60l
nn	1.00	\$	1,200.00	0.00	\$	1,200.00	Y	X
	1.00	\$	900.00	0.00	\$	900.00	Y	300l
nn	1.00	\$	980.00	0.00	\$	980.00	Y	X
	1.00	\$	800.00	0.00	\$	800.00	Y	300l
(Bill)	1.00	\$	280.00	0.00	\$	280.00	Y	200l
(Bill)	1.00	\$	180.00	0.00	\$	180.00	Y	X

TOTAL (LABOUR) :

\$ 11,100.00

\$ 11,100.00

TOTAL PARTS & LABOUR

\$ 107,375.00

\$ 104,181.00

EXCESS : :S\$ _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Blk 8 Sin Ming Industrial Estate #01-64/66 Singapore 576643 Tel: (65) 6284 1542, (65) 6284 1575 Fax: (65) 6487 5315