



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2103753

INV Date 28/05/2021

Reference CC4/FCI20000404/Aga3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMN 1876E

Insured Veh. SH 7749K

Claim No. D20000159MFSH

Policy No. D-19092580MFSH

Accident Date 18/12/2019

Inspection Date 07/01/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20000404/Aga3q2	
			Date: 28/05/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7749K	Veh. Inspected	SMN 1876E	
Policy No.	D-19092580MFSH	Coverage (\$)	0.00	
Claim No.	D20000159MFSH	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	07/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1261082	Colour	BLACK	
Odometer	63029 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/12/2019	Inspection Date	07/01/2020	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 1876E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RH	DENTED	630.00	630.00
1	FRONT FENDER INNER COWLING RH	NOT NECESSARY	103.00	-
1	FRONT FENDER ARCH RH	CUT	266.90	266.90
1	FRONT DOOR RH	DENTED	1,385.30	1,166.00
1	FRONT DOOR OUTER GARNISH RH	CUT	420.00	274.00
1	REAR DOOR RH	TO REPAIR SEE LABOUR	380.00	-
1	REAR DOOR OUTER GARNISH RH	CUT	420.00	285.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,088.50	-
1	REAR FENDER ARCH RH	CUT	360.00	360.00
	LESS 10% DISCOUNT		-505.37	-298.19
			4,548.33	2,683.71
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	20.00	-
			20.00	-
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR DOOR RH AND REAR FENDER RH .		1,400.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	600.00
	TUFF COAT.		250.00	50.00
	WIRING CHECK .		180.00	30.00
	REMOVE AND REFIX FRONT DOOR MECHANISM.		180.00	80.00
	REMOVE AND REFIX REAR DOOR MECHANISM .	NOT NECESSARY	150.00	-
			3,560.00	1,160.00
	GRAND TOTAL		8,128.33	3,843.71



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00
---	--	--	-----------------

Report Ref No. CC4/FCI20000404/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 1876E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

