



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003063
INV Date 09/04/2020
Reference CC3/CTI20000408/Fea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHA 4543Z
Insured Veh. SKD 5670G
Claim No. SNM20D200041C02/0
Policy No. DMPCSN3024921906
Accident Date 01/01/2020
Inspection Date 06/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI20000408/Fea3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-04-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKD 5670G	Veh. Inspected	SHA 4543Z	
Policy No.	DMPCSN3024921906	Coverage (\$)	0.00	
Claim No.	SNM20D200041C02/0	Excess (\$)	0.00	
Assign From		Assign Date	06/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVLU186599	Colour	BLUE	
Odometer	31816	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	8 mm	
L/H Front Tyre	195/65 R15	MICHELIN	8 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	8 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/01/2020	Inspection Date	06/01/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4543Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER (G3)	CUT	418.30	418.30
1	FRONT BUMPER BRACKET -RH	NOT NECESSARY	28.00	-
1	FRONT BUMPER TOP BRACKET -RH	NOT NECESSARY	12.00	-
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT FENDER -RH	TO REPAIR SEE LABOUR	490.70	-
1	FRONT BUMPER SIDE GRILLE -RH	SCRATCHED	186.60	186.60
1	HEADLAMP -RH	SCRATCHED	2,110.30	2,110.30
1	HEADLAMP SUPPORT PANEL (ADDITIONAL)	BROKEN	949.30	949.30
1	DAYLIGHT -RH (ADDITIONAL)	CRACKED	642.50	642.50
1	FRONT BUMPER UPPER CTR MOLDING (ADDITIONAL)	CRACKED	188.00	188.00
	LESS 20% DISCOUNT		-1,009.54	-903.40
			4,038.16	3,613.60
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER -RH .		700.00	640.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.		80.00	50.00
	TUFF KOTE.		80.00	30.00
			1,360.00	1,120.00
GRAND TOTAL			5,398.16	4,733.60
RECOMMENDED COST OF REPAIRS				4,733.60

Report Ref No. CC3/CTI20000408/Fea3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.