

TDS/2020

ASS. REC. BY:

REF:

CS/CT1 20000410 / E4f3n2

did instruction:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person):

Tan Kah Leong

of

CT1

Date/Time:

7 Jan. 2020 3:27p.m

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 7474C

Insured:

GBC 1122K

at Workshop n/a:

Auburn Auto

Tel:

9787 5558

of Autorace #104-38 Sh Ming

Policy No: DM CVSN 30267619066

Claim No:

SNM 200 200070

Sum Insured:

Excess:

Make of Vely:

(Client's Record)

D.O.A.

3 Jan. 2020

CA / REV / REP. / REV 24 HRS

mgp

Date/Time:

7.1.2020 3:34p.m

Person Contacted:

Sam

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 7474C - NA / CT1 20000410 / h4 D.O.A - 03/01/2020
	GBC 1122K - NA / CT1 20000410 / h4 D.O.A - 03/01/2020

ASS. REQ. BY: stweREF: CT1

ASSIGNMENT

From:

Date:

8. Jan. 2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SL5 7474C

at Workshop with:

Auburn Auto

of:

Autorart #104-38 S'n ming

Insured:

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

'sup'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL5 7474C

Yr Regn:

4/10/17Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra

C.C.

1591

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

65950

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH0841CMJ4537507Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

215/45R17

R:

h

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Roadstone

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

3/1/20

D.O.I.

8/1/20

Survey held at

AuburnDes. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/1/20MV-64KFinalize\$6100, 7 days (Sam) (Red \$17699-86, 74%)

RECEIVED 20 JAN 2020

Date/Time, File Pass in?



: Prel. Report

1)



: Final Report

Date/Time, File Return in?

2)

20/1/20 Typist

Days Of Repair:

7

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

\$ + RS \$

Photos

Other:

TOTAL

220

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Wheel end (\$

Rep. Format:

Emp. Sum. / P.D.:\$6100K

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

	Case No.	File Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jan 2020		07 Jan 2020 15:29 Edit Adj Rpt				Pending for Survey Report Cancel Case

Home	Reference	Claim Details	Documents	Show All				
CLAIM SUBFOLDER DETAILS [Created by insurer]								
Insured:								
Main Claimant:	TOH HONG HUA, ID: S1593114J							
Vehicle Reg. No.:	SLS7474C	Date of Loss:	03/01/2020 17:00 - :59					
Claim Type:	TP / SNM20D200070C02	Policy/Cover Note No.:	DMCVSN30267619066					
Vehicle Reg. No. (Insured):	GBC1122K	Policy No. (Claimant):	08-VX020981-MVA					
		Excess:	S\$500.00					
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]							
Claimant's Insurer:	QBE Insurance (Singapore) Pte Ltd (HQ) - Tel: 62246633							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 16/01/2020]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail								
There are no mail for this case.								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete								
Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.								

Steve Chen (LKK Auto)

From: Sam Ng <samuel.auburnauto@gmail.com>
Sent: Friday, January 17, 2020 10:17 AM
To: Steve Chen (LKK Auto)
Cc: Yvonne Wong (LKK Auto)
Subject: Re: SLS7474C - Finalize

Hi Steve,

The company decided to accept the offer, kindly revert to the relevant personal.

with regards

Sam

Auburn Auto Pte Ltd

+65 9787 5558

On Thu, 16 Jan 2020 at 20:09, Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Sam,

Kindly refer our finalize \$6100 (L/S, before GST). 7 repair days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen| Assistant Automotive Assessor

Summer Lee (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 7 January, 2020 3:27 PM
To: Sam Ng; 'assignments'
Subject: RE: OUR REF: SNM20D200070/GBC1122K/TKL - ACCIDENT INVOLVING SLS7474C & GBC1122K ON 03 JAN 2020 AT 17:25

WITHOUT PREJUDICE

Dear Sam,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK.

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Kah Leong
Sent: Tuesday, January 7, 2020 3:17 PM
To: Sam Ng <samuel.auburnauto@gmail.com>
Subject: RE: OUR REF: SNM20D200070/GBC1122K/TKL - ACCIDENT INVOLVING SLS7474C & GBC1122K ON 03 JAN 2020 AT 17:25

Without Prejudice

Dear Sam,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.entaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, January 7, 2020 3:12 PM

To: Tan Kah Leong <KahLeong.Tan@sg.entaiping.com>; Sam Ng <samuel.auburnauto@gmail.com>

Cc: Susan Teo <susan.teo@sg.entaiping.com>; Chee So Chow <sochow.chee@sg.entaiping.com>; Albert Chua <albert.chua@sg.entaiping.com>; Claims Dept of CTI <claimsdept@sg.entaiping.com>

Subject: OUR REF: SNM20D200070/GBC1122K/TKL - ACCIDENT INVOLVING SLS7474C & GBC1122K ON 03 JAN 2020 AT 17:25

Dear Kah Leong,

Please conduct PRS for SLS7474C.

Note : officer in charge – Kah Leong 63896193

**** Kindly quote our reference number when replying.*

Thank You

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.entaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Albert Chua

Sent: Monday, 6 January, 2020 7:28 PM

To: Claims Dept of CTI <claimsdept@sg.entaiping.com>

Cc: Susan Teo <susan.teo@sg.entaiping.com>; Chee So Chow <sochow.chee@sg.entaiping.com>

Subject: RE: ACCIDENT INVOLVING SLS7474C & GBC1122K ON 03 JAN 2020 AT 17:25

Please prepare file and direct to the officer in charge. Thank you.

Since they want to do direct settlement, we can see if they agree to us appointing the surveyor instead.

Regards,

Albert Chua
Deputy Head of Claims
Claims Department

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Feedback of China Taiping Insurance
Sent: Monday, 6 January 2020 5:44 pm
To: Albert Chua <albert.chua@sg.entaiping.com>
Cc: Susan Teo <susan.teo@sg.entaiping.com>; Chee So Chow <sochow.chee@sg.entaiping.com>
Subject: Fw: ACCIDENT INVOLVING SLS7474C & GBC1122K ON 03 JAN 2020 AT 17:25

Dear Albert,

Please refer to the email below and reply to the sender.

Best regards.

Seah Poon Lip

From: Sam Ng <samuel.auburnauto@gmail.com>
Sent: Monday, January 6, 2020 5:21 PM
To: Feedback of China Taiping Insurance <feedback@sg.entaiping.com>; Auburn Auto Claims <auburnauto.claim@gmail.com>
Subject: RE: ACCIDENT INVOLVING SLS7474C & GBC1122K ON 03 JAN 2020 AT 17:25

Dear Officer-In-Charge,

We refer to the above.

We are handling the claims for our client's car:

[SLS7474C]

The car is currently at:

176, Sin Ming Drive

#04-18 Sin Ming Autocare

📍 Singapore 575721.

The other party [GBC1122K] is under [China TaiPing] Insurance.

We would like to amicably settle this directly with you.

In this regard, we would appreciate it if you could list your surveyors list for us to choose to inspect car before our repair.

Thank you.

Kindly call Samuel -97875558(hp) to make an Appointment

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 114J

Vehicle Details

Vehicle No.: SLS7474C
Vehicle to be Exported: No
Intended Deregistration Date: 08 Jan 2020
Vehicle Make: HYUNDAI
Vehicle Model: ELANTRA AD 1.6 GLS AT
Primary Colour: Red
Manufacturing Year: 2017
Engine No.: G4FGHU620797
Chassis No.: KMHD841CMJU537507
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$12,547.00
Original Registration Date: 04 Oct 2017
First Registration Date: 04 Oct 2017
Transfer Count: 0
Actual ARF Paid: \$12,547.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 03 Oct 2027
PARF Rebate Amount: \$9,410.00

Intended COE Rebate Details

COE Expiry Date: 03 Oct 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,902.00
COE Rebate Amount: \$33,188.00
Total Rebate Amount: \$42,598.00

The information contained herein is correct as at 08 Jan 2020

OK

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 8608 0808

Email: auburnauto.claim@gmail.com

Vehicle No: SLS7474C

Model: HYUNDAI ELANTR

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Rear Tailgate / <i>DD</i>	\$ 2,580.00 <i>1615 /</i>
2	Rear Taillamp (LH) / <i>OR (RH) ? / OR</i>	<i>1pc - 395</i> \$ 1,500.00 <i>790 /</i>
2	Rear Tailgate Lamp (LH) / <i>OR (RH) ? / OR</i>	<i>1pc - 395</i> \$ 920.00 <i>596 /</i>
1	Rear Tailgate Mechanism X <i>N/A</i>	\$ 800.00
1	Rear Tailgate Lock / <i>BT</i>	\$ 480.00 <i>199.30 /</i>
1	Inner lock X <i>N/A</i>	\$ 240.00
1	Outer lock X <i>N/A</i>	\$ 180.00
1	Upper Lock X <i>N/A</i>	\$ 325.00
1	Lower Lock X <i>N/A</i>	\$ 422.00
1	Rear Bumper / <i>OR</i>	\$ 1,800.00 <i>459 /</i>
1	Rear Bumper Side Retainers / <i>OR</i>	\$ 428.00 <i>64 /</i>
1	Bumper Sensor X <i>N/A</i>	\$ 320.00
1	Rear Bumper Reflectors (LH) / <i>OR (RH) X N/A</i>	\$ 350.00 <i>45 /</i>
1	Rear Bumper Top Step Garnish X <i>N/A</i>	\$ 320.00
1	Rear End Panel / <i>DD</i>	\$ 1,800.00 <i>454 /</i>
1	Rear End Panel Inner Garnish / <i>CR4</i>	\$ 580.00 <i>88-60 /</i>
1	Rear Boot Garnish X <i>N/A</i>	\$ 380.00
1	Hydraulic Hinge X <i>R</i>	\$ 200.00
2	Rubber Moulding / <i>CR4</i>	\$ 120.00 <i>/</i>
1	Number Plate / <i>CR4</i>	\$ 120.00 <i>35 /</i>
1	Rear Exhaust X <i>N/A</i>	\$ 2,800.00
1	Rear Reverse Camera X <i>N/A</i>	\$ 320.00
1	Rear Tailgate "HYUNDAI" Emblem / <i>NR</i>	\$ 160.00 <i>60 /</i>
1	Rear Tailgate "ELITE" Emblem / <i>NR</i>	\$ 120.00 <i>60 /</i>
1	Rear Tailgate "ELANTRA" Emblem / <i>NR</i>	\$ 180.00 <i>60 /</i>

Supp

Bumper lower Spokes / OR \$665.86

Boot Side trim LH / CR4 \$355 /

\$ 17,445.00

Page 1 of 3

Spare tyre top board / TN \$290 /

Rear bumper reinforcement / OR \$455 /

Rear LH fender liner / OR \$189 /

*6600.76
- 20%
5280.60 /*

c/f: \$

\$ 17,445.00

Special Nett Items**AMT SS**

1	Rear Windscreen Sealant X <i>MM</i>	\$	120.00
1	Back bumper clip / <i>MC</i>	\$	150.00 <i>30</i>
1	Rear Reverse Sensor (1 set) / <i>shorted</i>	\$	620.00 <i>230</i>
		\$	<u>890.00</u>

S/N. Labour Charges*230 ✓*

1	Remove and refit rear tailgate	\$	300.00 <i>300</i>
2	Remove and refit rear bumper	\$	300.00 <i>230</i>
3	Remove and Refit Rear Panel, <i>for LH front</i>	\$	800.00 <i>700 600</i>
4	Remove, refit and replaced damage lamps and check up rear electrical wiring	\$	150.00 X
5	Remove and refit inner garnishes trim to assist repair	\$	200.00 <i>50</i>
6	Remove and refit rear reverse sensor	\$	240.00 <i>30</i>
7	To apply undercoating on replaced panel	\$	120.00 <i>30</i>
8	To Respray Painting.	\$	1,400.00 <i>1000</i>

\$ 3,510.00**GRAND TOTAL**\$ 21,845.00*2110**P- 5280.60**M- 230**L- 2110**7620.60**L/S- 6096.48**= 6100*

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20000410/EYF3N2

Date: 23/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30267619066
Claimant Vehicle No :	SLS7474C	Insured Vehicle No :	GBC1122K
Date of Loss:	03/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200070C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS7474C	Engine No:	G4FGHU620797
Make & Model:	HYUNDAI ELANTRA, 1.6 Elite (MD) (A)	Chassis No:	KMHD841CMJU537507
Reg. Date:	04/10/2017 (Man. Year: 2017)	Odometer:	65050 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Roadstone 5 mm	Rear Left Side:	Roadstone 5 mm
Front Right Side:	Roadstone 5 mm	Rear Right Side:	Roadstone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,289.86	5,510.61	14,779.25	72.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	2,110.00	1,400.00	39.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,799.86	7,620.61	16,179.25	67.98
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	23,799.86	6,100.00	17,699.86	74.37

INSPECTION

Date of Assignment:	07/01/2020		
Date Inspected:	08/01/2020	Inspected At:	Autocare #04-38 Sin Ming Repairer: Auburn Auto Pte Ltd
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
(Contact) 8722 1113
(Email) _____
(Signature) [Signature]
(Date/Time) 8/1/20, 2:00pm

[Signature]
13/1/2020

W/L M/L

7 days

L/S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jan 2020)

Parts: 143 HYUNDAI ELANTRA 1.6 Elite (MD) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS7474C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	2,580.00 F	*1,615.00 FL
2	2		*REAR TAILLAMP	Broken	1,500.00 F	*790.00 FL
3	2		*REAR TAILGATE LAMP	N/S Cut / O/S Broken	920.00 F	*596.00 FL
4	1		*REAR TAILGATE MECHANISM	Not Necessary	800.00 F	*- FL
5	1		*REAR TAILGATE LOCK	Bent	480.00 F	*199.30 FL
6	1		*INNER LOCK	Not Necessary	240.00 F	*- FL
7	1		*OUTER LOCK	Not Necessary	180.00 F	*- FL
8	1		*UPPER LOCK	Not Necessary	325.00 F	*- FL
9	1		*LOWER LOCK	Not Necessary	422.00 F	*- FL
10	1		*REAR BUMPER	Broken	1,800.00 F	*459.00 FL
11	1		*REAR BUMPER SIDE RETAINERS	Broken	428.00 F	*64.00 FL
12	1		*BUMPER SENSOR	Not Necessary	320.00 F	*- FL
13	1		*REAR BUMPER REFLECTORS	N/S Missing /O/S Not Necessary	350.00 F	*45.00 FL
14	1		*REAR BUMPER TOP STEP GARNISH	Not Necessary	320.00 F	*- FL
15	1		*REAR END PANEL	Dented	1,800.00 F	*454.00 FL
16	1		*REAR END PANEL INNER GARNISH	Crushed	580.00 F	*88.60 FL
17	1		*REAR BOOT GARNISH	Not Necessary	380.00 F	*- FL
18	1		*HYDRAULIC HINGE	Repair	200.00 F	*- FL
19	2		*RUBBER MOULDING	Crushed (1 PCS ONLY)	120.00 F	*120.00 FL
20	1		*NUMBER PLATE	Cut	120.00 F	*35.00 FL
21	1		*REAR EXHAUST	Not Necessary	2,800.00 F	*- FL
22	1		*REAR REVERSE CAMERA	Not Necessary	320.00 F	*- FL
23	1		*REAR TAILGATE HYUNDAI EMBLEM	Necessary	160.00 F	*60.00 FL
24	1		*REAR TAILGATE ELITES EMBLEM	Necessary	120.00 F	*60.00 FL
25	1		*REAR TAILGATE ELANTRA EMBLEM	Necessary	180.00 F	*60.00 FL
26	1		*BUMPER LOWER SPOILER	Broken	665.86 F	*665.86 FL
27	1		*BOOT SIDE TRIM LH	Crushed	355.00 F	*355.00 FL
28	1		*SPARE TYRE TOP BOARD	Torn	290.00 F	*290.00 FL
29	1		*REAR BUMPER REINFORCEMENT	Dented	455.00 F	*455.00 FL
30	1		*REAR LH FENDER LINER	Broken	189.00 F	*189.00 FL
31	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
32	1		*BACK BUMPER CLIP	Necessary	150.00 FS	*30.00 FS
33	1		*SET REAR REVERSE SENSOR	Shorted	620.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	20,289.86	6,830.76
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,320.15
Total Parts (S\$)	20,289.86	5,510.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT REAR TAILGATE	New	300.00	200.00
2	REMOVE AND REFIT REAR BUMPER	New	300.00	200.00
3	REMOVE AND REFIT REAR PANEL ,REAR LH FINAL	New	800.00	600.00
4	REMOVE ,REFIT AND REPLACED DAMAGE LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	150.00	0.00
5	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR	New	200.00	50.00
6	REMOVE AND REFIT REAR REVERSE SENSOR	New	240.00	30.00
7	TO APPLY UNDERCOATING ON REPLACED PANEL	New	120.00	30.00
8	TO RESPRAY PAINTING	New	1,400.00	1,000.00
Gross Labour Cost (S\$)			3,510.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >