

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5903B**AAD2001-003***Not Authorised*
11 Sep & 13 Oct

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

06 JAN 2020

SHC 5903B

VF1ABL15AUC281409

RENAULT

LATITUDE

31.12.19

FCIL

23/3/2015

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel) TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH

LIST

\$	<i>Bu</i>	561.70	✓
\$	<i>Sn</i>	411.90	X
\$	<i>Sn</i>	98.10	X
\$	<i>Sn</i>	82.10	X
\$	<i>Sn</i>	59.80	✓
\$	<i>Sn</i>	16.60	✓
\$	<i>Sn</i>	80.80	X
\$	<i>Sn</i>	54.20	X
\$	<i>Sn</i>	16.60	X
\$	<i>Bu</i>	547.80	✓
\$	<i>N</i>	114.50	} X
\$	<i>N</i>	100.90	
\$	<i>N</i>	745.80	
\$	<i>Sn</i>	404.56	
\$	<i>Sn</i>	313.10	
\$	<i>N</i>	401.40	
\$	<i>Sn</i>	401.40	
\$	<i>N</i>	401.40	
\$	<i>N</i>	1,677.20	
\$	<i>Sn</i>	344.70	
\$	<i>Sn</i>	178.20	}
\$	<i>Sn</i>	277.70	
\$	<i>Sn</i>	277.70	
\$	<i>Sn</i>	82.40	}
\$	<i>N</i>	95.80	
\$	<i>Sn</i>	145.10	

Trans-cab Auto Services Pte Ltd**AAD2001-003**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5903B

27	1	BOOT STRUT RH	\$	145.10	} <i>SHC</i> <i>X</i>
28	1	BOOT HINGE LH	\$	254.20	
29	1	BOOT HINGE RH	\$	253.80	
30	2	BOOT RUBBER PLUG	\$	139.90	
31	1	BOOT LOCK LINKAGE	\$	20.60	
32	1	BOOT LOCK LINKAGE HOLDER	\$	99.50	
33	1	BOOT INNER TRIM BOARD	\$	611.00	
34	1	BOOT SWITCH	\$	113.00	
35	1	BOOT LOCK	\$	246.60	
36	1	BOOT LOCK CATCH	\$	41.70	
37	1	FENDER PANEL REAR RH	\$	1,933.20	
38	1	WHEELARCH REAR RH	\$	275.40	
39	1	FENDER PANEL INNER TRIM REAR RH	\$	671.45	
40	1	AIR VENT	\$	59.40	
41	1	EXHAUST REAR	\$	<i>7</i> 5,263.60	
42	1	EXHAUST CAP REAR	\$	<i>1</i> 125.40	
TOTAL			\$	18,145.31	
10%			\$	1,814.53	
			\$	16,330.78	

Special Nett

1	1SET	PARKING AID	\$	<i>SH</i> 700.00 <i>X</i>
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00 ✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00 <i>X</i>
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 20.00 <i>X</i>
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00 <i>X</i>
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>nn</i> 20.00 <i>X</i>
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00 <i>X</i>
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00 ✓
10	1	BOOT STICKER "Trans-cab"	\$	<i>nn</i> 30.00
11	1	BOOT STICKER "6555-3333"	\$	<i>nn</i> 30.00
12	2	REAR WINDSCREEN SEALANT	\$	<i>nn</i> 80.00 } <i>X</i>
13	1	WINDSCREEN MOULDING	\$	<i>nn</i> 100.00
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00

Trans-cab Auto Services Pte Ltd**AAD2001-003**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5903B

15	1	BOOT INNER TRIM CLIP	\$	nn	45.00	}	X
16	1SET	BOOT FINISHER CLIP	\$	nn	24.20		
17	1	TAILLAMP CLIP LH	\$	nn	5.00		
18	1	TAILLAMP CLIP RH	\$	nn	5.00		
19	1	Rear Bumper Protector	\$	nn	100.00		
20	1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00		
21	1	FENDER INNER TRIM CLIP RH	\$	nn	28.00		
22	1	REAR RIGHT TYRE	\$	Sn	300.00		
23	1	REAR RIGHT TYRE RIM	\$	Sn	380.00		
24	1	EXHAUST BRACKET REAR	\$	Sn	24.80		
25	1	EXHAUST MOUNTING REAR	\$	Sn	16.00		
TOTAL			\$		2,250.00		

TOTAL PARTS \$ 18,580.78**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i>	170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>100</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		7,500.00	<i>2000</i>

Trans-cab Auto Services Pte Ltd**AAD2001-003**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5903B

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	~ 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
Putty and spray painting of the affected portion.	\$	7,500.00	2201
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
TOTAL	\$	17,850.00	

Over All Total \$ 36,430.78**LUMP SUM (REPAIR DAY)****25 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date: