



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2005877  
INV Date 27/08/2020  
Reference CC4/LPC20000421/Eka3s2  
Code LPC2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SMK 6685Y  
Insured Veh. XD 8318B  
Claim No. 19/20/20/VC05/022872  
Policy No. Z/19/VC05/004144-001  
Accident Date 06/01/2020  
Inspection Date 07/01/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC20000421/Eka3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 27-08-2020		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 8318B	Veh. Inspected	SMK 6685Y	
Policy No.	Z/19/VC05/004144-001	Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/022872	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	06/01/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI KONA	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHK281GUKU024592	Colour	GREY	
Odometer	25613	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	TRIANGLE	5 mm	
L/H Front Tyre	215/55 R17	TRIANGLE	5 mm	
R/H Rear Tyre	215/55 R17	TRIANGLE	5 mm	
L/H Rear Tyre	215/55 R17	TRIANGLE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/01/2020	Inspection Date	07/01/2020	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 6685Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	CUT	1,580.00	494.70
1	FRONT BUMPER SIDE RETAINER RHS	BROKEN	138.00	138.00
10	FRONT BUMPER CLIPS @ \$5.00	NECESSARY	50.00	30.00
1	FRONT BUMPER SIDE PROTECTOR RHS	CUT	238.00	166.60
1	FRONT BUMPER SIDE REFLECTOR RHS	NOT NECESSARY	115.00	-
1	FRONT BUMPER UPPER CENTER MOULDING (SILVER COLOR)	NOT NECESSARY	398.00	-
1	FRONT HEADLAMP RHS	CUT	1,584.00	1,384.40
1	FRONT RUNNING DAY LIGHT RHS	NOT NECESSARY	982.00	-
1	FRONT FENDER RHS	DENTED	783.00	597.40
1	FRONT FENDER PROTECTOR RHS	CUT	298.00	130.50
10	FRONT FENDER PROTECTOR CLIPS RHS @ \$4.00	NECESSARY	40.00	20.00
1	FRONT FENDER SPLASH SHIELD RHS	NOT NECESSARY	182.00	-
1	FRONT FENDER BADGE RHS	NECESSARY	60.00	60.00
1	FRONT FENDER WHEEL HOUSE PANEL RHS	NOT NECESSARY	798.00	-
1	FRONT RIM RHS	NOT NECESSARY	1,628.00	-
5	FRONT WHEEL HUP CAP @ \$58.00	NOT NECESSARY	290.00	-
1	FRONT LOWER ARM RHS	NOT NECESSARY	498.00	-
1	FRONT STABILIZER LINK RHS	NOT NECESSARY	178.00	-
1	FRONT SHOCK ABSORBER RHS	NOT NECESSARY	428.00	-
1	FRONT DOOR RHS	NOT NECESSARY	1,225.00	-
1	DOOR MIRROR RH (ADDITIONAL)	BROKEN	646.10	646.10
	LESS 20% DISCOUNT		-2,427.82	-733.54
			9,711.28	2,934.16
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT TYRE RHS (SN)	NOT NECESSARY	400.00	-
			400.00	-
<b><u>LABOUR</u></b>				
	TO REMOVE & REFOCUS FRONT HEADLAMP AND RUNNING LIGHT.		120.00	30.00
	TO DISCONNECT & RE-CONNECT ELECR TIC POWER.		120.00	50.00

Report Ref No. CC4/LPC20000421/Eka3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	60.00
	TO REMOVE & REPLACED TYRE, RIM & CONDUCT WHEEL BALANCING.		120.00	-
	TO APPLY RUSTPROOFING & TUFF COATING TREATMENT.		100.00	30.00
	TO KNOCKING & PANEL BEATING.		1,600.00	400.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		1,300.00	400.00
			3,510.00	970.00
GRAND TOTAL			13,621.28	3,904.16

RECOMMENDED COST OF REPAIRS				3,904.16
-----------------------------	--	--	--	----------

Report Ref No. CC4/LPC20000421/Eka3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 6685Y

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 6685Y

RE-INSPECTION





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

